

Register entry, as of 29 October 2026

Listed for sale

Record ID 320f8e0a3b8e

2019 Hyundai Tucson SE

2.0 L, 4 cylinders · 4WD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

KM8 J2CA4 5 K U 988322

WMI 1-3

Hyundai Motor Co

DESCRIPTOR 4-8

Tucson · 2.0 L

CHECK 9

Computes

YEAR 10

2019

PLANT 11

Ulsan

SERIAL 12-17

Build sequence

§1 IDENTITY [1]

Model year	2019	Engine	2.0 L, 4 cylinders
Make	Hyundai	Fuel	Gasoline
Model	Tucson	Drive	4WD
Trim	SE	Maker	HYUNDAI MOTOR CO
Body	Sport Utility Vehicle	Plant	Ulsan, South Korea

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/hyundai/tucson/2019

6 recalls listed by Transport Canada for this model year

Label 2024552 23 Sep 2024

Issue: On certain vehicles, the compliance label may be missing information in French. The words listed on the label for "Tires", "Rims", "Front" and "Rear" appear in English only, when they should be listed as "Tires/Pneus", "Rims/Jantes", "Front/Avant" and "Rear/Arriere". Canadian regulations require this information to be listed on the label in both English and French. Safety Risk: These small errors do not affect vehicle safety. Corrective Actions: This is not a recall. The company has corrected the compliance label for all new vehicles.

Engine 2022244 8 May 2022

Issue: Hyundai Auto Canada is conducting a Product Improvement Campaign that provides an update to the engine control module to detect potential problems before an engine fails. An engine failure would cause a sudden loss of power with an inability to restart. Note: This only affects certain vehicles equipped with a 2.0 L Nu GDI engine. For the Sonata model, only the Sonata Hybrid and Plug-In Hybrid (PHEV) models are affected by this campaign. This is an expansion of R0180 (Transport Canada #2021-575). Any vehicle that received a software update under campaign R0180 does not require this update. Safety Risk: A sudden loss of engine power could increase the risk of an accident. An engine failure could also create the risk of a fire. Corrective Actions: Hyundai will notify owners by mail and advise you to take your vehicle to a dealer to update the software for the engine control module. Note: Hyundai recommends that you should always follow the correct vehicle maintenance schedule, which is printed in the Owner's Manual. If you experience unusual engine noise, reduced power, or a check engine/oil warning light, Hyundai advises you to immediately visit a Hyundai dealership to have your vehicle diagnosed.



Engine

2021575 17 Sep 2021

This recall was replaced by Transport Canada Recall No. 2022-244. Issue: Hyundai Auto Canada is conducting a Product Improvement Campaign that provides an update to the engine control module to detect potential problems before an engine fails. An engine failure would cause a sudden loss of power with an inability to restart. Note: This only affects certain vehicles equipped with a 2.0 L Nu GDI engine. For the Sonata model, only the Sonata Hybrid and Plug-In Hybrid (PHEV) models are affected by this campaign. All vehicles previously included in TC # 2021-034 are now part of this new campaign. Safety Risk: A sudden loss of engine power could increase the risk of an accident. An engine failure could also create the risk of a fire. Corrective Actions: Hyundai will notify owners by mail and advise you to take your vehicle to a dealer to update the software for the engine control module. Note: Hyundai recommends that you should always follow the correct vehicle maintenance schedule, which is printed in the Owner's Manual. If you experience unusual engine noise, reduced power, or a check engine/oil warning light, Hyundai advises you to immediately visit a Hyundai dealership to have your vehicle diagnosed.

Brakes

2020648 30 Dec 2020

Issue: On certain vehicles, a problem in the control module for the antilock brake system (ABS) could cause it to short circuit. Note: This is an expansion of recall 2020-431. This recall does not affect vehicles equipped with Smart Cruise Control(SCC). Safety Risk: A short circuit could create a fire risk. Corrective Actions: Hyundai will notify owners by mail and advise you to take your vehicle to a dealer to revise the ABS fuse wiring and update the ABS control module, if necessary. Hyundai recommends that you should park your vehicle outdoors, and away from other vehicles or structures until the recall repairs have been completed.

Brakes

2020431 13 Sep 2020

This recall was replaced by Transport Canada Recall No. 2020-648. Issue: On certain vehicles, the control module for the antilock brake system (ABS) could corrode internally and cause a short circuit. Safety Risk: A short circuit could create a fire risk. Corrective Actions: Hyundai will notify owners of this problem by mail. The corrective actions for this recall are still being finalized. Hyundai recommends that you should park your vehicle outdoors, and away from other vehicles or structures until the recall repairs have been completed.

Engine

2019640 16 Dec 2019

Issue: Hyundai Auto Canada is conducting a Product Improvement Campaign that provides an update to the engine control module to detect potential problems before an engine fails. An engine failure would cause a sudden loss of power with an inability to restart. Note: This affects Sonata and Santa Fe Sport equipped with a 2.4 L GDI or 2.0 L Turbo GDI engine, as well as Tucson equipped with a 2.4 L GDI engine. Safety Risk: A sudden loss of engine power could increase the risk of an accident. Corrective Actions: The company will notify owners by mail. Owners will be instructed to take their vehicle to a dealer to update the software for the engine control module. Note: Vehicles previously repaired under Product Improvement Campaign R0153 (TC # 2019-130) do not require this software update. Owners can find additional information at www.hyundaiengineinfo.ca.

Listed for the model year, not checked against your VIN. Hyundai confirms which apply.

Check your VIN with Hyundai Canada or call a Hyundai dealer with your VIN.

www.hyundaicanada.com/en/owners-section/recalls

United States: 1 NHTSA record for this model year, kept apart from the Canadian listing.^[3]

§3 VALUE [4]

This car asks \$16,977^[5], \$1,527 over the median of \$15,450^[4].



Lowest ask	\$11,817
Middle half	\$14,648 – \$16,782
Median ask	\$15,450
This car	\$16,977

Same configuration · 14 live listings · as of 29 Oct 2026



OTHER 2019 HYUNDAI TUCSON LISTINGS ^[5]

Blenheim, ON · 97,416 km	\$17,520
Toronto, ON · 48,893 km	\$20,720
Tillsonburg, ON · 122,604 km	\$15,593
Montmagny, QC · 161,461 km	\$12,949
Saint John, NB · 117,920 km	\$14,857
Montmagny, QC · 161,461 km	\$12,949

§4 EVENTS

2019	Model year 2019 ^[1] Assembly plant Ulsan, South Korea
16 Dec 2019	Transport Canada recall 2019640 ^[2] Issued for the model year · Engine
13 Sep 2020	Transport Canada recall 2020431 ^[2] Issued for the model year · Brakes
30 Dec 2020	Transport Canada recall 2020648 ^[2] Issued for the model year · Brakes
17 Sep 2021	Transport Canada recall 2021575 ^[2] Issued for the model year · Engine
8 May 2022	Transport Canada recall 2022244 ^[2] Issued for the model year · Engine
23 Sep 2024	Transport Canada recall 2024552 ^[2] Issued for the model year · Label
29 Oct 2026	Listed for sale, Québec, QC ^[5] Kia Ste-Foy · asking \$16,977

§5 DOCUMENTS

Window sticker We have not collected this label yet.

SOURCES

- | | |
|---|--|
| [1] Cardog identity register, decoded from the VIN | [4] Cardog market quote, same configuration, 14 live listings, as of 29 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year | [5] Live public dealer listings on Cardog, as of 29 Oct 2026 |
| [3] NHTSA recall records (United States), listed for the model year | |

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

