Register entry, as of 27 October 2026 Listed for sale Record ID 0d62f9a7d75e

2019 Toyota RAV4 XLE AWD

2.5 L, 4 cylinders · AWD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

2T3	R1RFV	5	K	C	034009
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Toyota Motor Manufacturi…	RAV4 · 2.5 L	Verified	2019	Cambridge	Build sequence

§1 IDENTITY [1]

Model year	2019	Engine	2.5 L, 4 cylinders
Make	Toyota	Fuel	Gasoline
Model	RAV4	Drive	AWD
Trim	XLE AWD	Maker	TOYOTA MOTOR MANUFACTURING CANADA
Body	Sport Utility Vehicle	Plant	Cambridge, Ontario, Canada

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/toyota/rav4/2019

7 recalls listed by Transport Canada for this model year

Electrical

2021723 24 Nov 2021

Issue: This recall is for certain block heater kits installed on certain vehicles or sold as accessories at Toyota or Lexus dealerships. On certain vehicles, the engine block heater cable may not have enough heat protection and could be damaged by high temperatures. If this happens, the cable could short circuit while plugged in, and cause the wiring to overheat or melt. Note: This recall only affects the following block heater/cord part numbers: C014003034 PK5A408J09 PU14000904 C014003151 PK5A408J13 PU14000905 C014000885 PK5A489J11 PU14000907 C014000888 PK5A489J22 PU14000909 C014000907 PK5A410H00 PU14000911 C014100904 PU14000900 PU14000913 C014100907 PU14000901 PU14003571 C014100911 PU14000902 PK5A489J14 PK5A408J05 PU14000903 Safety Risk: Engine block heater wiring that overheats or melts could create the risk of a fire. Corrective Actions: Toyota recommends that you should stop using the engine block heater immediately. Toyota will notify owners by mail and instruct you to take your vehicle to a dealer to disable the engine block heater. For some vehicles, the corrective actions for this recall are under development. For others, a new engine block heater cannot be installed, and the owner will receive a refund of the purchase price of the engine block heater.

Fuel system

2020514 28 Oct 2020

Issue: On certain vehicles, the low-pressure fuel pump could fail. If this happens, then engine may run rough or may not start and the check engine light may turn on. This could also result in a sudden loss of engine power while driving. Note: This recall is an expansion of recalls SRC R95/SRC R96 and SRC RA2/SRC RA3 (Transport Canada Recall Numbers 2020-005 and 2020-088). Safety Risk: A sudden loss of engine power could increase the risk of a crash. Corrective Actions: The company will notify owners by mail and instruct you to take your vehicle to a dealer to replace the fuel pump.

Steering

2020288 24 Jun 2020

Issue: On certain vehicles, the cover of the electric power steering (EPS) gearbox may not be properly attached. As a result, water can enter the gearbox and corrode internal components. Under certain conditions, this can result in a loss of power steering assist. Safety Risk: A loss of power steering assist may result in a sudden increase in steering effort, especially at low vehicle speeds. This could increase the risk of a crash. Corrective Action: Toyota will notify owners by mail and instruct you to take your vehicle to a Toyota dealer to replace the electric power steering gear assembly.

Engine

2020039 6 Feb 2020

Issue: On certain vehicles equipped with a 2.5-L 4-cylinder engine, the engine block may be porous. As a result, the engine block could crack and cause internal or external coolant leaks. This could cause engine overheating or internal engine damage and result in an engine failure. For non-hybrid vehicles, this could also result in a sudden loss of engine power while driving. Note: This problem may lead to engine noise, smoke, cause warning lights to turn on and/or cause an audible chime to sound before an engine failure. Safety Risk: A sudden loss of engine power could increase the risk of a crash. Additionally, an engine failure could create the risk of a fire. Corrective Actions: The company will notify owners by mail and instruct you to take your vehicle to a dealer to inspect the engine block casting serial number. If the serial number is within the identified range, the dealer will replace the engine with a new one.

Accessories

2019428 23 Aug 2019

Issue: On certain vehicles, the hook and loop material used to attach the carpet to its underpadding may not be flame resistant. As a result, when it is tested alone, the loop fasteners do not meet the requirements of Canadian regulations. Safety Risk: As the carpet is always assembled, and the loop fasteners are very small, this problem does not create a safety risk. Corrective Action: This is not a recall. The company has made production changes to ensure that all new vehicles meet the requirements of Canadian regulations.

Visual system

2019382 6 Aug 2019

Issue: On certain vehicles, the connector for the audio display unit may have been damaged during assembly. This could cause the backup camera system to not activate when the transmission is shifted into reverse. Canadian regulations require the rearview image to display when in reverse gear. Safety Risk: A rearview camera that does not turn on could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: Toyota will notify owners by mail including instructions on how to inspect for the issue. Owners who are uncomfortable inspecting for themselves can take their vehicle to a dealer to have the backup camera system inspected. The audio display unit will be replaced with a new one if necessary.

1 more on the model-year record, cardog.app/tools/recalls/toyota/rav4/2019

> Listed for the model year, not checked against your VIN. Toyota confirms which apply.
> Check your VIN with Toyota Canada or call a Toyota dealer with your VIN.
> www.toyota.ca/en/owners/recalls/

United States: 8 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $27,995[5], $1,397 over the median of $26,598[4].

Lowest ask	$19,999
Middle half	$24,999 – $28,761
Median ask	$26,598
This car	$27,995

Same configuration · 36 live listings · as of 27 Oct 2026

OTHER 2019 TOYOTA RAV4 LISTINGS [5]

Toronto, ON · 0 km	$28,988
Victoria, BC · 201,795 km	$23,930

Quebec, QC · 136,370 km	$23,499
Brandon, MB · 182,705 km	$26,995
Smiths Falls, ON · 143,033 km	$22,995
Surrey, BC · 187,095 km	$22,967

§4 EVENTS

2019	Model year 2019[1] Assembly plant Cambridge, Ontario, Canada
24 Jul 2019	Transport Canada recall 2019360[2] Issued for the model year · Brakes
6 Aug 2019	Transport Canada recall 2019382[2] Issued for the model year · Visual system
23 Aug 2019	Transport Canada recall 2019428[2] Issued for the model year · Accessories
6 Feb 2020	Transport Canada recall 2020039[2] Issued for the model year · Engine
24 Jun 2020	Transport Canada recall 2020288[2] Issued for the model year · Steering
28 Oct 2020	Transport Canada recall 2020514[2] Issued for the model year · Fuel system
24 Nov 2021	Transport Canada recall 2021723[2] Issued for the model year · Electrical
26 Oct 2026	Listed for sale, Lévis, QC[5] Lévis Mazda · asking $27,995

§5 DOCUMENTS

Window sticker We have not collected this label yet.

SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same configuration, 36 live listings, as of 27 Oct 2026
[5] Live public dealer listings on Cardog, as of 27 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.