Register entry, as of 28 October 2026 Listed for sale Record ID 849a943a02b2

2016 GMC Sierra SLT

5.3 L, 8 cylinders · 4WD · Pickup · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

3GT	U2NEC	9	G	G	329152
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
GMC · GENERAL MOTORS…	Sierra · 5.3 L	Verified	2016	Silao	Build sequence

§1 IDENTITY [1]

Model year	2016	Engine	5.3 L, 8 cylinders
Make	GMC	Fuel	Gasoline
Model	Sierra	Drive	4WD
Trim	SLT	Maker	GENERAL MOTORS LLC
Body	Pickup	Plant	Silao, Guanajuato, Mexico

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/gmc/sierra/2016

11 recalls listed by Transport Canada for this model year

Electrical

2024294 24 May 2024

Issue: On certain trucks, the repairs completed by a General Motors dealer during recall N192220470 (Transport Canada recall no. 2019-325) or customer satisfaction program no. N192270330 may not have been completed properly. As a result, a second repair is required. Additionally, certain trucks may not have had the updated parts installed during production. On certain trucks equipped with a power sliding rear window, the rear defroster wiring could overheat and melt. Safety Risk: Wiring that overheats and melts can create the risk of a fire. Corrective Actions: General Motors will notify owners by mail and advise you to take your truck to a dealership to replace the contact cover for the sliding rear window. The dealer will also update the heating, ventilation, and air conditioning (HVAC) software, if necessary. If the rear window or sliding glass assembly are damaged, they will be replaced.

Airbag

2021410 1 Jul 2021

Issue: On certain trucks, the side curtain airbag inflators could be defective. As a result, the driver and/or passenger side curtain airbag inflator(s) could fail. If this happens, the end cap from the inflator or other parts could be propelled into the vehicle and strike a person. Note: This recall replaces Transport Canada Recall No. 2020-576. Safety Risk: A metal end cap or other parts that strike a person could create a risk of injury. Corrective Action: General Motors will notify owners by mail and instruct you to take your truck to a dealer to replace both side curtain airbags.

Brakes

2019533 24 Oct 2019

Issue: On certain vehicles, there may be an error in the electronic-brake control module software. This could cause the driveline-protection system to activate when a wheel-speed sensor fails. If this happens, the brakes could apply and cause the vehicle to pull to one side. Note: This recall only affects vehicles equipped with four-wheel drive, a 5.3-L engine, and a 3.08 ratio rear axle. The problem can only occur when the vehicle is in four-wheel drive or automatic mode, and travelling at a speed between 66 and 97 km/h (41 and 60 mph). A wheel-speed sensor failure will cause the electronic stability control (ESC) and anti-lock braking system (ABS) warning lights to turn on, and a "Service StabiliTrak" message to display. Safety Risk: A vehicle that suddenly pulls to one side could increase the risk of a crash. Corrective Actions: General Motors will notify owners by mail and instruct you to take your vehicle to a dealer to update the electronic-brake control module software. General Motors advises that using two-wheel-drive mode can eliminate the risk until the recall repair is completed.

Other

2019420 21 Aug 2019

Issue: This recall is for aftermarket replacement rear window glass produced by Vitro Automotriz. Certain rear window glass may not have been properly tempered. If the window breaks, the glass may separate into large pieces instead of very small ones. Note: This is a voluntary recall that is not being conducted under the requirements of the Motor Vehicle Safety Act. Safety Risk: Glass that breaks in to large pieces could create a risk of injury. Corrective Actions: The company will notify consumers by mail and instruct them to inspect the designation code marked on the rear window glass. Products affected by this recall have the designation “DOT 287” along with the lettering “VMR” (Replacement Market) and a date code that is before July 2019. This information is printed on the bottom corner of the glass. Consumers should contact Vitro's customer service at 1-412-995-6457 or argbacklites@vitro.com to arrange for replacement of the glass.

Electrical

2019325 28 Jun 2019

Issue: On certain trucks equipped with a power sliding rear window, the rear defroster circuit could overheat. This could cause melting, smoke or, in rare instances, a fire. Safety Risk: A fire could create a risk of injury. Corrective Actions: The company will notify owners by mail and advise you to take your truck to a dealer to replace the covers for the buss bar and contacts for the rear sliding window. If the rear window or sliding glass assembly are damaged due to a problem with the rear defroster, they will also be replaced.

Brakes

2019324 28 Jun 2019

Issue: On certain vehicles, there could be a reduction in power brake assist due to a decrease in output from the vacuum pump. This could cause a hard brake pedal and an increase in brake pedal effort to stop the vehicle. Safety Risk: A sudden increase in brake pedal force could lead to an increase in stopping distance. This could increase the risk of a crash. Corrective Actions: The company will notify owners by mail and instruct them to take their vehicle to a dealer to reprogram the electronic brake control module.

5 more on the model-year record, cardog.app/tools/recalls/gmc/sierra/2016

> Listed for the model year, not checked against your VIN. GMC confirms which apply.
> Check your VIN with GMC Canada or call a GMC dealer with your VIN.
> www.gmccanada.ca/en/ownercenter/recalls

United States: 13 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $26,499[5], $1,599 over the median of $24,900[4].



Lowest ask	$16,590
Middle half	$21,938 – $27,995
Median ask	$24,900
This car	$26,499

Same configuration · 13 live listings · as of 28 Oct 2026

OTHER 2016 GMC SIERRA LISTINGS [5]

Watrous, SK · 202,924 km	$27,995

§4 EVENTS

2016	Model year 2016[1] Assembly plant Silao, Guanajuato, Mexico
9 Dec 2015	Transport Canada recall 2015590[2] Issued for the model year · Airbag
11 Feb 2016	Transport Canada recall 2016068[2] Issued for the model year · Electrical
28 Apr 2016	Transport Canada recall 2016190[2] Issued for the model year · Suspension
9 Sep 2016	Transport Canada recall 2016439[2] Issued for the model year · Airbag
10 Jul 2017	Transport Canada recall 2017342[2] Issued for the model year · Airbag
28 Jun 2019	Transport Canada recall 2019325[2] Issued for the model year · Electrical
28 Jun 2019	Transport Canada recall 2019324[2] Issued for the model year · Brakes
21 Aug 2019	Transport Canada recall 2019420[2] Issued for the model year · Other
24 Oct 2019	Transport Canada recall 2019533[2] Issued for the model year · Brakes
1 Jul 2021	Transport Canada recall 2021410[2] Issued for the model year · Airbag
24 May 2024	Transport Canada recall 2024294[2] Issued for the model year · Electrical
26 Oct 2026	Listed for sale, Calgary, AB[5] Eastside Dodge · asking $26,499
27 Oct 2026	Listing last updated[5] asking $26,499

§5 DOCUMENTS

Window sticker	This VIN reads as model year 1986 or 2016, before our coverage for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same configuration, 13 live listings, as of 28 Oct 2026

[5] Live public dealer listings on Cardog, as of 28 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.