Register entry, as of 27 October 2026 Listed for sale Record ID 278a68a6f56f

2017 BMW X5 xDrive35i

3.0 L, 6 cylinders · AWD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

5UX	KR0C3	6	H	0	V72253
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Bmw Manufacturer Corpor…	X5 · 3.0 L	Verified	2017	United States	Build sequence

§1 IDENTITY [1]

Model year	2017	Engine	3.0 L, 6 cylinders
Make	BMW	Fuel	Gasoline
Model	X5	Drive	AWD
Trim	xDrive35i	Maker	BMW MANUFACTURER CORPORATION / BMW NORTH AMERICA
Body	Sport Utility Vehicle	Plant	United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/bmw/x5/2017

7 recalls listed by Transport Canada for this model year

Label

2024544 15 Aug 2024

Issue: On certain vehicles, the tire and loading information label does not list that there is no spare tire in both official languages. The label reads as "NONE" when it should read as "NONE / AUCUN". Canadian regulations require the information to be listed on the label in both English and French. Safety Risk: This error does not affect vehicle safety. Corrective Actions: This is not a recall. The company has corrected the tire and loading information label for all new vehicles.

Engine

2024468 13 Aug 2024

Issue: On certain vehicles, fluid from the positive crankcase ventilation (PCV) system could leak on the intake air hose. As a result, the fluid could enter the electrical connector for the water pump and cause a short circuit. Safety Risk: A short circuit can create the risk of a fire, even while the vehicle is parked and turned off. Corrective Actions: To reduce the safety risk, BMW advises you to park your vehicle outdoors and away from other vehicles or structures until the recall repairs are completed. BMW will notify owners by mail and advise you to take your vehicle to a dealership to inspect and, if necessary, replace the water pump and electrical connector. The dealer will also install a shield on the connector.

Engine

2021711 19 Nov 2021

Issue: On certain vehicles, the exhaust gas recirculation (EGR) cooler could crack internally and leak. If this happens, you may notice the following symptoms: a warning symbol in the instrument cluster displaying a loss of coolant, reduced engine power, an unpleasant exhaust odour, an unusual noise from the engine and/or smoke from the engine compartment. Note: This recall replaces Transport Canada Recall no. 2018-587. Safety Risk: A cracked EGR cooler could create the risk of an engine fire. Corrective Actions: BMW will notify owners by mail and instruct you to take your vehicle to a dealer to replace the EGR cooler. The dealer will also inspect the intake manifold, and replace it, if necessary.

Fuel system

2021469 29 Jul 2021

Issue: On certain vehicles equipped with a diesel engine, the high-pressure fuel pump may wear prematurely. This can cause reduced engine performance and could lead to a sudden engine stall. Note: A warning lamp on the instrument cluster will turn on if the fuel pressure drops. Safety Risk: A loss of engine power could increase the risk of a crash. Corrective Actions: BMW will notify owners by mail and instruct you to take your vehicle to a dealer to replace the high-pressure fuel pump.

Engine

2018587 26 Oct 2018

This recall was replaced by Transport Canada Recall No. 2021-711. On certain vehicles, the cooler for Exhaust Gas Recirculation (EGR) module may develop an internal leak and coolant could mix with diesel engine soot/sediment. In rare circumstances, this condition could result in smouldering particles and lead to the melting of the intake manifold, increasing the risk of a fire causing injury and/or damage to property. Correction: Dealers will inspect the EGR cooler, and if necessary, replace it. If it is determined that the EGR cooler has leaked internally, the intake manifold will also be replaced. The EGR pipe connecting the cooler to the manifold will be cleaned. Note: An operator may be alerted to this condition by one or more of the following symptoms: A warning symbol in the instrument cluster displaying a loss of engine coolant, a reduction in engine power, an unpleasant odour (exhaust gas), an unusual noise from the engine compartment, and/or smoke from the engine compartment.

Label

2017269 19 May 2017

Certain M-Series vehicles may fail to comply with the requirements of Canada Motor Vehicle Safety Standard (CMVSS) 110 - Tire Selection and Rims. For some X5 M and X6 M vehicles, the tire and loading information label incorrectly states the vehicles were equipped with 20-inch tires, however the vehicles are equipped with 21-inch tires. For some M6 Cabriolet and M6 Coupe vehicles, the tire and loading information label incorrectly states the vehicles were equipped with 19-inch tires, however the vehicle is equipped with 20-inch tires. Additionally, the label for the M6 Cabriolet and M6 Coupe vehicles incorrectly displays a value of 32psi (220 kPa), although it should display a value of 35psi (240kPa). Correction: Dealers will replace the Tire and Loading label.

1 more on the model-year record, cardog.app/tools/recalls/bmw/x5/2017

> Listed for the model year, not checked against your VIN. BMW confirms which apply.
> Check your VIN with BMW Canada or call a BMW dealer with your VIN.
> crm.bmw.ca/en-CA/VehicleRecall

United States: 6 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $22,999[5], $1,445 under the median of $24,444[4].

Lowest ask	$13,995
Middle half	$20,749 – $24,971
Median ask	$24,444
This car	$22,999

Same configuration · 10 live listings · as of 27 Oct 2026

OTHER 2017 BMW X5 LISTINGS [5]

Oakville, ON · 117,870 km	$26,988
Penticton, BC · 134,966 km	$24,995
Vancouver, BC · 62,700 km	$34,900
Westbank, BC · 182,036 km	$17,995
Gananoque, ON · 115,820 km	$2,408,995
North Vancouver District, BC · 121,536 km	$21,499

§4 EVENTS

2017	Model year 2017[1] Assembly plant United States
17 Mar 2017	Transport Canada recall 2017150[2] Issued for the model year · Airbag
19 May 2017	Transport Canada recall 2017269[2] Issued for the model year · Label
26 Oct 2018	Transport Canada recall 2018587[2] Issued for the model year · Engine
29 Jul 2021	Transport Canada recall 2021469[2] Issued for the model year · Fuel system
19 Nov 2021	Transport Canada recall 2021711[2] Issued for the model year · Engine
13 Aug 2024	Transport Canada recall 2024468[2] Issued for the model year · Engine
15 Aug 2024	Transport Canada recall 2024544[2] Issued for the model year · Label
24 Jan 2026	Listed for sale, Toronto, ON[5] Ryder Auto Sales · asking $22,999
24 Oct 2026	Listing last updated[5] asking $22,999

§5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same configuration, 10 live listings, as of 27 Oct 2026

[5] Live public dealer listings on Cardog, as of 27 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.