Register entry, as of 29 October 2026 Listed for sale Record ID 74c0e30d6123

# 2007 Toyota Yaris

1.5 L, 4 cylinders · 4x2 · Sedan · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

| JTD | BT923 | 9 | 7 | 1 | 180515 |
|---|---|---|---|---|---|
| WMI 1–3 | DESCRIPTOR 4–8 | CHECK 9 | YEAR 10 | PLANT 11 | SERIAL 12–17 |
| Toyota Motor Corporation | Yaris · 1.5 L | Computes | 2007 | Iwate | Build sequence |

## §1 IDENTITY [1]

| | | | |
|---|---|---|---|
| Model year | 2007 | Engine | 1.5 L, 4 cylinders |
| Make | Toyota | Fuel | Gasoline |
| Model | Yaris | Drive | 4x2 |
| Trim | Not in the decode | Maker | TOYOTA MOTOR CORPORATION |
| Body | Sedan | Plant | Iwate, Iwate, Japan |

## §2 OBLIGATIONS [2]

cardog.app/tools/recalls/toyota/yaris/2007

**8** recalls listed by Transport Canada for this model year

### Electrical

2021723 24 Nov 2021

Issue: This recall is for certain block heater kits installed on certain vehicles or sold as accessories at Toyota or Lexus dealerships. On certain vehicles, the engine block heater cable may not have enough heat protection and could be damaged by high temperatures. If this happens, the cable could short circuit while plugged in, and cause the wiring to overheat or melt. Note: This recall only affects the following block heater/cord part numbers: C014003034 PK5A408J09 PU14000904 C014003151 PK5A408J13 PU14000905 C014000885 PK5A489J11 PU14000907 C014000888 PK5A489J22 PU14000909 C014000907 PK5A410H00 PU14000911 C014100904 PU14000900 PU14000913 C014100907 PU14000901 PU14003571 C014100911 PU14000902 PK5A489J14 PK5A408J05 PU14000903 Safety Risk: Engine block heater wiring that overheats or melts could create the risk of a fire. Corrective Actions: Toyota recommends that you should stop using the engine block heater immediately. Toyota will notify owners by mail and instruct you to take your vehicle to a dealer to disable the engine block heater. For some vehicles, the corrective actions for this recall are under development. For others, a new engine block heater cannot be installed, and the owner will receive a refund of the purchase price of the engine block heater.

### Airbag

2017007 9 Jan 2017

On certain vehicles, long-term exposure to high absolute humidity and temperature, combined with high temperature cycling, could eventually degrade the propellant contained in the passenger frontal airbag. This could cause the airbag to deploy with more force than normal. As a result, if the vehicle were involved in a collision that warrants airbag deployment, fragments could be propelled toward vehicle occupants, and the airbag assembly could be damaged, preventing proper function. These issues could increase the risk of injury. Correction: Depending on the model, dealers will either replace the passenger frontal airbag inflator or airbag assembly. Note: Canadian climate results in the propellant degrading slowly. The recall is being conducted as a precaution to address future risk, and is expected to replace airbag inflators before their function would be affected.

### Electrical

2015493 21 Oct 2015

On certain vehicles, inconsistent application of grease during the manufacturing process could cause the driver's side power window master switch to stick or become inoperative due to electrical contact point wear. This could cause debris to accumulate between the contact points, potentially resulting in an electrical short circuit. If a short circuit occurs, the switch assembly may overheat, produce smoke, melt and/or potentially lead to a fire causing injury and/or property damage. Correction: Dealers will inspect the driver's power window master switch and apply a specialized grease that inhibits heat build-up, or replace the power window master switch circuit board, as necessary. Note: This is an expansion of recall 2012-338.

### Airbag

2014124 9 Apr 2014

On certain vehicles, electrical circuitry in the steering wheel assembly may become damaged. As a result, the driver's airbag may not function as intended, causing the instrument panel airbag warning lamp to illuminate. Failure of the driver's airbag to deploy during a crash (where deployment is warranted) could increase the risk of injury to the seat occupant. Correction: Dealers will replace the spiral cable assembly.

### Seats and restraints

2014123 9 Apr 2014

On certain vehicles, the front seat position adjustment mechanism springs could break, which could cause the seat to appear to be locked into position even though it is not. This could allow the seat to slide forward or rearward in a crash, increasing the risk of injury and/or damage to property. Correction: Dealers will inspect seat rails and replace as necessary.

### Electrical

2012338 10 Oct 2012

On certain vehicles, due to improperly applied grease, the driver's side power window master switch could stick or become inoperative. If attempts are made to lubricate the switch, the switch assembly could overheat and melt. A melting switch may produce smoke and potentially lead to a fire causing property damage and/or personal injury. Correction: Dealers will inspect the driver's power window master switch and apply a specialized grease that inhibits heat build-up, or replace the power window master switch circuit board, as necessary.

2 more on the model-year record, cardog.app/tools/recalls/toyota/yaris/2007

> Listed for the model year, not checked against your VIN. Toyota confirms which apply.
> Check your VIN with Toyota Canada or call a Toyota dealer with your VIN.
> www.toyota.ca/en/owners/recalls/

United States: 10 NHTSA records for this model year, kept apart from the Canadian listing.[3]

## §3 VALUE [4]

This car asks $7,929[5], $937 over the median of $6,992[4].




| | |
|---|---|
| Lowest ask | $5,800 |
| Middle half | $6,097 – $6,998 |
| Median ask | $6,992 |
| This car | $7,929 |

Same model year · 6 live listings · as of 29 Oct 2026

#### OTHER 2007 TOYOTA YARIS LISTINGS [5]

| | |
|---|---|
| London, ON · 172,996 km | $6,995 |
| Burnaby, BC · 1 km | $5,800 |

## §4 EVENTS

| | |
|---|---|
| 2007 | Model year 2007[1]<br>Assembly plant Iwate, Iwate, Japan |
| 29 Jan 2009 | Transport Canada recall 2009027[2]<br>Issued for the model year · Seats and restraints |
| 28 Sep 2010 | Transport Canada recall 2010323[2]<br>Issued for the model year · Accessories |
| 10 Oct 2012 | Transport Canada recall 2012338[2]<br>Issued for the model year · Electrical |
| 9 Apr 2014 | Transport Canada recall 2014124[2]<br>Issued for the model year · Airbag |
| 9 Apr 2014 | Transport Canada recall 2014123[2]<br>Issued for the model year · Seats and restraints |
| 21 Oct 2015 | Transport Canada recall 2015493[2]<br>Issued for the model year · Electrical |
| 9 Jan 2017 | Transport Canada recall 2017007[2]<br>Issued for the model year · Airbag |
| 24 Nov 2021 | Transport Canada recall 2021723[2]<br>Issued for the model year · Electrical |
| 24 Oct 2026 | Listed for sale, Lachine, QC[5]<br>Spinelli Toyota Lachine · asking $7,929 |
| 29 Oct 2026 | Listing last updated[5]<br>asking $7,929 |

## §5 DOCUMENTS

Window sticker We have not collected this label yet.

### SOURCES


[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same model year, 6 live listings, as of 29 Oct 2026

[5] Live public dealer listings on Cardog, as of 29 Oct 2026


### STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.