Register entry, as of 29 November 2026 Listed for sale Record ID 9334a5ac59cf

2020 Mercedes-Benz GLC-Class GLC300-4M

2.0 L, 4 cylinders · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

WDC	0G8EB	6	L	V	208552
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Mercedes-Benz Cars	GLC-Class · 2.0 L	Computes	2020	Uusikaupunki	Build sequence

§1 IDENTITY [1]

Model year	2020	Engine	2.0 L, 4 cylinders
Make	Mercedes-Benz	Fuel	Gasoline
Model	GLC-Class	Drive	Not in the decode
Trim	GLC300-4M	Maker	Mercedes-Benz Cars
Body	Sport Utility Vehicle	Plant	Uusikaupunki, Finland

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/mercedes-benz/glc-class/2020

20 recalls listed by Transport Canada for this model year

Structure — 2026364 — 24 Jul 2026

Issue: On certain vehicles, moisture could enter the driver-side door lock microswitch and cause it to corrode. As a result, the microswitch may fail to automatically engage the parking brake and/or the auto park feature when the door is opened. If this happens, the vehicle could roll away. Note: This problem could also cause the radio and/or interior lights to remain on after exiting the vehicle. Safety Risk: A parked vehicle that rolls away could create the risk of an injury or a crash. Corrective Actions: To reduce the safety risk, Mercedes-Benz recommends that you should always use the parking brake when you park. Mercedes-Benz will notify owners by mail and advise you to take your vehicle to a dealership to replace the driver-side door lock.

Lights and instruments — 2024064 — 2 Feb 2024

Issue: On certain vehicles, the headlamps were not adjusted properly at the factory. Safety Risk: Headlamps that aren't adjusted properly could cause reduced visibility and/or glare for oncoming drivers, and increase the risk of a crash. Corrective Actions: Mercedes-Benz will notify owners by mail and advise you to take your vehicle to a dealership to inspect the headlamps, and adjust them as necessary.

Structure — 2023673 — 15 Dec 2023

Issue: On certain vehicles, the plastic panel located between the windshield and the panoramic sunroof may not have been attached correctly during a prior service repair. Over time, the panel could loosen and separate from the vehicle. Note: This is an expansion of Transport Canada recall 2021-170. Safety Risk: A panel that detaches from a moving vehicle could create a road hazard for others and increase the risk of a crash. Corrective Actions: Mercedes-Benz will notify owners by mail and advise you to take your vehicle to a dealership to replace the front roof panel.

Powertrain

2022372 8 Jul 2022

Issue: On certain vehicles, the transmission wiring harness may have been routed incorrectly. As a result, the wiring could be damaged by contact with the front driveshaft. If this happens, there could be a loss of power to the wheels. Safety Risk: A loss of power to the wheels could increase the risk of a crash. Corrective Actions: Mercedes-Benz will notify owners by mail and instruct you to take your vehicle to a dealership to inspect the transmission wiring harness, and replace it if necessary.

Other

2022263 20 May 2022

Issue: On certain vehicles equipped with the emergency calling (eCall) system, the SIM card for the communications module could disable itself. If this happens, the eCall system would not work properly when there is a crash or when the SOS button is pressed. Safety Risk: If the eCall system does not work in an emergency situation, there could be a delay in response from emergency services. Corrective Actions: Mercedes-Benz will notify owners by mail and send a wireless over-the-air software update to each vehicle. If the update cannot be completed successfully, you will be notified to schedule an appointment to have the update performed by a dealer.

Visual system

2022177 12 Apr 2022

Issue: On certain vehicles, a software problem could cause the rearview camera image not to appear on the central display. Canadian regulations require the rearview image to display when the transmission is shifted into reverse gear. Safety Risk: A rearview camera image that does not display could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: Mercedes-Benz will notify owners by mail and instruct you to take your vehicle to a dealership to update the rearview camera software.

14 more on the model-year record, cardog.app/tools/recalls/mercedes-benz/glc-class/2020

> Listed for the model year, not checked against your VIN. Mercedes-Benz confirms which apply. Check your VIN with Mercedes-Benz Canada or call a Mercedes-Benz dealer with your VIN.
> www.mercedes-benz.ca/en/recalls

§3 VALUE [3]

This car asks $26,999[4], $996 under the median of $27,995[3].



Lowest ask	$21,788
Middle half	$25,795 – $28,900
Median ask	$27,995
This car	$26,999

Same configuration · 29 live listings · as of 29 Nov 2026

OTHER 2020 MERCEDES-BENZ GLC-CLASS LISTINGS [4]

North York, ON · 60,000 km	$28,999
Langley, BC · 56,184 km	$28,495
Vaughan, ON · 75,201 km	$28,900
Montréal, QC · 83,431 km	$25,795
Richmond, BC · 91,174 km	$22,483
Oakville, ON · 46,061 km	$30,888

§4 EVENTS

2020 Model year 2020[1]
Assembly plant Uusikaupunki, Finland

2 Oct 2019	Transport Canada recall 2019484[2] Issued for the model year · Airbag
7 Feb 2020	Transport Canada recall 2020046[2] Issued for the model year · Electrical
9 Jun 2020	Transport Canada recall 2020253[2] Issued for the model year · Seats and restraints
22 Jun 2020	Transport Canada recall 2020282[2] Issued for the model year · Engine
6 Jul 2020	Transport Canada recall 2020307[2] Issued for the model year · Brakes
27 Oct 2020	Transport Canada recall 2020512[2] Issued for the model year · Steering
12 Dec 2020	Transport Canada recall 2020614[2] Issued for the model year · Electrical
1 Feb 2021	Transport Canada recall 2021041[2] Issued for the model year · Accessories
12 Feb 2021	Transport Canada recall 2021064[2] Issued for the model year · Electrical
3 Mar 2021	Transport Canada recall 2021112[2] Issued for the model year · Other
22 Mar 2021	Transport Canada recall 2021170[2] Issued for the model year · Structure
14 May 2021	Transport Canada recall 2021291[2] Issued for the model year · Visual system
13 Jul 2021	Transport Canada recall 2021431[2] Issued for the model year · Airbag
13 Dec 2021	Transport Canada recall 2021755[2] Issued for the model year · Fuel system
12 Apr 2022	Transport Canada recall 2022177[2] Issued for the model year · Visual system
20 May 2022	Transport Canada recall 2022263[2] Issued for the model year · Other
8 Jul 2022	Transport Canada recall 2022372[2] Issued for the model year · Powertrain
15 Dec 2023	Transport Canada recall 2023673[2] Issued for the model year · Structure
2 Feb 2024	Transport Canada recall 2024064[2] Issued for the model year · Lights and instruments

24 Jul 2026	Transport Canada recall 2026364[2] Issued for the model year · Structure
28 Nov 2026	Listed for sale, Thornhill, ON[4] YST Auto Sales · asking $26,999

§5 DOCUMENTS

Window sticker	We do not collect window stickers for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] Cardog market quote, same configuration, 29 live listings, as of 29 Nov 2026

[4] Live public dealer listings on Cardog, as of 29 Nov 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.