

Register entry, as of 28 October 2026

Listed for sale

Record ID fbcd01cab276

2019 Acura TLX SH-AWD TECH+A / TCH+AR V6

3.5 L, 6 cylinders · 4WD · Sedan · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

19U **UB3F6** **7** **K** **A** **800043**

WMI 1-3

Acura · AMERICAN HONDA...

DESCRIPTOR 4-8

TLX · 3.5 L

CHECK 9

Verified

YEAR 10

2019

PLANT 11

Marysville

SERIAL 12-17

Build sequence

§1 IDENTITY [1]

Model year	2019	Engine	3.5 L, 6 cylinders
Make	Acura	Fuel	Gasoline
Model	TLX	Drive	4WD
Trim	SH-AWD TECH+A / TCH+AR V6	Maker	AMERICAN HONDA MOTOR CO., INC.
Body	Sedan	Plant	Marysville, Ohio, United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/acura/tlx/2019

6

 recalls listed by Transport Canada for this model year

Seats and restraints

2026251 21 May 2026

Issue: On certain vehicles, the weight sensor for the front passenger seat may not have been manufactured properly. As a result, the passenger-front airbag and knee airbag could deploy in a crash that doesn't require them to. Note: This recall is an expansion of Transport Canada recall no. 2024-059. If the weight sensor fails, the SRS warning light would turn on in the instrument panel. Safety Risk: An airbag system that doesn't work properly could increase the risk of injury in a crash. Corrective Actions: The company will notify owners by mail and advise you to take your vehicle to a dealership to replace the passenger-front seat weight sensor.

Fuel system

2024262 6 May 2024

Issue: This recall is for low-pressure fuel pumps installed on certain vehicles or sold at dealerships as a replacement part. On certain vehicles, the low-pressure fuel pump could fail. If this happens, the engine may run rough or may not start and the check engine light may turn on. This could also result in a sudden loss of engine power while driving. Note: This recall replaces Transport Canada recall no. 2023-679. Vehicles that were repaired under that recall don't require this repair. Safety Risk: A sudden loss of engine power could increase the risk of a crash. Corrective Actions: The company will notify owners by mail and advise you to take your vehicle to a dealership to replace the fuel pump motor.



Fuel system

2023679 18 Dec 2023

This recall was replaced by Transport Canada recall no. 2024-262. Issue: This recall is for low-pressure fuel pumps installed on certain vehicles or sold at dealerships as a replacement part. On certain vehicles, the low-pressure fuel pump could fail. If this happens, the engine may run rough or may not start and the check engine light may turn on. This could also result in a sudden loss of engine power while driving. Note: This is an expansion of Transport Canada recall nos. 2020-236 and 2021-182. Safety Risk: A sudden loss of engine power could increase the risk of a crash. Corrective Actions: The company will notify owners by mail and advise you to take your vehicle to a dealership to replace the fuel pump motor.

Engine

2023603 8 Nov 2023

Issue: On certain vehicles equipped with a V6 engine, the connecting rod bearings could wear prematurely and become damaged. If this happens, the engine could make abnormal noises and a warning light may turn on. If you continue to drive the vehicle with these symptoms, the engine could fail. Safety Risk: An engine failure could cause a sudden loss of power and/or increase the risk of a vehicle fire. Both issues could increase the risk of a crash or injury. Corrective actions: Honda will notify owners by mail and advise you to take your vehicle to a dealership to inspect the engine. If damage is found, the dealer will replace the necessary parts.

Fuel system

2021182 26 Mar 2021

Issue: On certain vehicles, the low-pressure fuel pump could fail. If this happens, then engine may run rough or may not start and the check engine light may turn on. This could also result in a sudden loss of engine power while driving. Note: This is an expansion of Transport Canada Recall No. 2020-236. Safety Risk: A sudden loss of engine power could increase the risk of a crash. Corrective Actions: The company will notify owners by mail and instruct you to take your vehicle to a dealer to replace the fuel pump motor.

Engine

2019179 11 Apr 2019

Issue: On certain vehicles, the teeth on the timing belt may separate due to a manufacturing issue. This could result in an engine stall. Safety Risk: An engine stall could increase the risk of a crash. Corrective Actions: The company will notify owners by mail and instruct them to take their vehicle to a dealer to inspect the lot number on the timing belt. If it is within the affected range, the belt will be replaced. Additionally, dealers will inspect the engine for internal damage.

Listed for the model year, not checked against your VIN. Acura confirms which apply.

Check your VIN with Acura Canada or call a Acura dealer with your VIN.

www.acura.ca/en/recalls

United States: 6 NHTSA records for this model year, kept apart from the Canadian listing.^[3]

§3 VALUE ^[4]

This car asks \$22,999^[5], the median^[4].



Lowest ask	\$13,995
Middle half	\$20,246 – \$25,497
Median ask	\$22,999
This car	\$22,999

Same model year · 15 live listings · as of 28 Oct 2026

OTHER 2019 ACURA TLX LISTINGS ^[5]

Whitby, ON · 119,710 km	\$20,500
Vernon, BC · 135,514 km	\$26,995
Saint-Félicien, QC · 212,593 km	\$18,980
Baie-Comeau, QC · 212,593 km	\$18,980
St-Félicien, QC · 212,593 km	\$18,980
Carignan, QC · 65,587 km	\$23,498



§4 EVENTS

2019	Model year 2019 ^[1] Assembly plant Marysville, Ohio, United States
11 Apr 2019	Transport Canada recall 2019179 ^[2] Issued for the model year · Engine
26 Mar 2021	Transport Canada recall 2021182 ^[2] Issued for the model year · Fuel system
8 Nov 2023	Transport Canada recall 2023603 ^[2] Issued for the model year · Engine
18 Dec 2023	Transport Canada recall 2023679 ^[2] Issued for the model year · Fuel system
6 May 2024	Transport Canada recall 2024262 ^[2] Issued for the model year · Fuel system
29 Apr 2026	Listed for sale, Mississauga, ON ^[5] VAULT MOTORS · asking \$22,999
21 May 2026	Transport Canada recall 2026251 ^[2] Issued for the model year · Seats and restraints
28 Oct 2026	Listing last updated ^[5] asking \$22,999

§5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.

SOURCES

- | | |
|---|---|
| [1] Cardog identity register, decoded from the VIN | [4] Cardog market quote, same model year, 15 live listings, as of 28 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year | [5] Live public dealer listings on Cardog, as of 28 Oct 2026 |
| [3] NHTSA recall records (United States), listed for the model year | |

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

