

Register entry, as of 28 October 2026

Listed for sale

Record ID 1600ba865f6f

2020 Jeep Wrangler Unlimited Sport

3.6 L, 6 cylinders · 4WD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

1C4 HJXDG 7 L W 247050

WMI 1-3

Jeep · FCA US LLC

DESCRIPTOR 4-8

Wrangler · 3.6 L

CHECK 9

Verified

YEAR 10

2020

PLANT 11

Toledo

SERIAL 12-17

Build sequence

§1 IDENTITY [1]

Model year	2020	Engine	3.6 L, 6 cylinders
Make	Jeep	Fuel	Gasoline
Model	Wrangler	Drive	4WD
Trim	Unlimited Sport	Maker	FCA US LLC
Body	Sport Utility Vehicle	Plant	Toledo, Ohio, United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/jeep/wrangler/2020

9 recalls listed by Transport Canada for this model year

Structure 2023165 23 Mar 2023

Issue: The frame on certain vehicles may have been built with an extra and unused mounting stud near the fuel tank. As a result, the stud could contact the fuel tank in a crash and create a fuel leak. Note: This recall only affects two-door models. Safety Risk: A fuel leak can create the risk of a fire. Corrective Actions: FCA Canada will notify owners by mail and instruct you to take your vehicle to a dealership to inspect and, if necessary, remove the stud.

Powertrain 2023089 23 Feb 2023

Issue: Under certain conditions, the clutch pressure plate could overheat and break. If this happens, the pressure plate may also crack or break the transmission case. This could cause debris to fall from the vehicle. Note: This recall only affects certain vehicles equipped with a 3.6 L engine and a manual transmission. Vehicles repaired under FCA Canada recalls Y01, Y03 and Y07 (Transport Canada recall 2021-035) also require this repair. Safety Risk: Debris from an overheated and fractured pressure plate could contact nearby parts and increase the risk of a fire. Parts that fall from the vehicle could create a road hazard for others and increase the risk of injury. Corrective Actions: FCA Canada will notify owners by mail and advise you to take your vehicle to a dealership to replace the clutch assembly. The dealer will also inspect and, if necessary, update the instrument panel cluster and powertrain control module software.

Engine 2022584 14 Oct 2022

Issue: On certain vehicles equipped with a 3.0 L diesel engine, the high-pressure fuel pump could fail. If this happens, you may notice a change in engine performance, a fuel leak, or a malfunction indicator lamp and/or service electronic throttle control tell-tale may turn on. This could also result in a sudden loss of engine power while driving. Safety Risk: A sudden loss of engine power could increase the risk of a crash. Corrective Actions: FCA Canada will notify owners by mail and instruct you to take your vehicle to a dealership to replace the high-pressure fuel pump. Additional fuel system parts may be replaced, if necessary.



Visual system

2022476 25 Aug 2022

Issue: On certain vehicles equipped with a 3.0 L diesel engine, a software problem could cause the radio to reset. If you shift to reverse while the computer is resetting, the rearview camera image will not appear on the display. Canadian regulations require the rearview image to display when the transmission is shifted into reverse gear. Safety Risk: A rearview camera image that is slow to appear could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: FCA Canada will notify owners by mail and instruct you to take your vehicle to a dealership to update the radio software.

Fuel system

2021530 26 Aug 2021

Issue: On certain vehicles, the connector on the high pressure fuel line in the engine compartment could crack and create a fuel leak. Note: This recall only affects vehicles equipped with a 2.0 L engine. Safety Risk: A fuel leak can create the risk of a fire. Corrective Actions: FCA Canada will notify owners by mail and instruct you to take your vehicle to a dealer to inspect the fuel supply line. It will be replaced, if required.

Powertrain

2021035 28 Jan 2021

Issue: In certain circumstances, the clutch pressure plate could overheat and break. If this happens, the pressure plate may also crack or break the transmission case. This could cause debris to fall from the vehicle. Note: This recall only affects certain vehicles equipped with a 3.6 L engine and a manual transmission. Safety Risk: Debris from an overheated and fractured pressure plate could contact nearby parts and increase the risk of a fire. Parts that fall from the vehicle could create a road hazard for others, and increase the risk of injury. Corrective Actions: FCA Canada will notify owners by mail and instruct you to take your vehicle to a dealer to update vehicle software. This update will reduce the engine power if the clutch overheats.

3 more on the model-year record, cardog.app/tools/recalls/jeep/wrangler/2020

Listed for the model year, not checked against your VIN. Jeep confirms which apply.


Check your VIN with Mopar Canada or call a Jeep dealer with your VIN.

www.mopar.com/en-ca/my-vehicle/recalls/search.html

United States: 12 NHTSA records for this model year, kept apart from the Canadian listing.^[3]

§3 VALUE [4]

This car asks \$38,695^[5], \$8,697 over the median of \$29,998^[4].



Lowest ask	\$15,995
Middle half	\$25,999 – \$33,998
Median ask	\$29,998
This car	\$38,695

Same model year · 89 live listings · as of 28 Oct 2026

OTHER 2020 JEEP WRANGLER LISTINGS [5]

Toronto, ON · 44,222 km	\$27,995
Spruce Grove, AB · 100,973 km	\$35,987
Ottawa, ON · 108,626 km	\$31,787
Ingersoll, ON · 294,793 km	\$16,790
Kelowna, BC · 66,366 km	\$35,404
Kelowna, BC · 73,110 km	\$33,404



§4 EVENTS

2020	Model year 2020 ^[1] Assembly plant Toledo, Ohio, United States
24 Jan 2020	Transport Canada recall 2020024 ^[2] Issued for the model year · Steering
3 Mar 2020	Transport Canada recall 2020083 ^[2] Issued for the model year · Powertrain
6 Apr 2020	Transport Canada recall 2020145 ^[2] Issued for the model year · Visual system
28 Jan 2021	Transport Canada recall 2021035 ^[2] Issued for the model year · Powertrain
26 Aug 2021	Transport Canada recall 2021530 ^[2] Issued for the model year · Fuel system
25 Aug 2022	Transport Canada recall 2022476 ^[2] Issued for the model year · Visual system
14 Oct 2022	Transport Canada recall 2022584 ^[2] Issued for the model year · Engine
23 Feb 2023	Transport Canada recall 2023089 ^[2] Issued for the model year · Powertrain
23 Mar 2023	Transport Canada recall 2023165 ^[2] Issued for the model year · Structure
29 Jul 2026	Listed for sale, North Vancouver, BC ^[5] North Vancouver Nissan · asking \$38,695
14 Sep 2026	Window sticker collected ^[6] Issued by STELLANTIS
25 Oct 2026	Listing last updated ^[5] asking \$38,695

§5 DOCUMENTS [6]

Window sticker	PDF, issued by STELLANTIS, collected 14 Sep 2026 VIN not read from the file
----------------	--

SOURCES

[1] Cardog identity register, decoded from the VIN	[4] Cardog market quote, same model year, 89 live listings, as of 28 Oct 2026
[2] Transport Canada recall database, listed for the model year	[5] Live public dealer listings on Cardog, as of 28 Oct 2026
[3] NHTSA recall records (United States), listed for the model year	[6] Window sticker, issued by STELLANTIS, collected 14 Sep 2026



STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote, live public dealer listings and the window sticker. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

