

2024 Ford Expedition Platinum

3.5 L, 6 cylinders · 4WD · Sport Utility Vehicle · Flexible Fuel Vehicle (FFV)

VEHICLE IDENTIFICATION NUMBER ^[1]

1FM	JU1M8	1	R	E	A20459
WMI 1-3 Ford Motor Company	DESCRIPTOR 4-8 Expedition · 3.5 L	CHECK 9 Verified	YEAR 10 2024	PLANT 11 Jefferson County	SERIAL 12-17 Build sequence

§1 IDENTITY ^[1]

Model year	2024	Engine	3.5 L, 6 cylinders
Make	Ford	Fuel	Flexible Fuel Vehicle (FFV)
Model	Expedition	Drive	4WD
Trim	Platinum	Maker	FORD MOTOR COMPANY
Body	Sport Utility Vehicle	Plant	Jefferson County, Kentucky, United States

§2 OBLIGATIONS ^[2]

cardog.app/tools/recalls/ford/expedition/2024

6 recalls listed by Transport Canada for this model year

Other20262799 Jun 2026

Issue: On certain vehicles, the chrome plating on the center console could bubble and peel. If this happens, sharp edges can be created. Safety Risk: Exposed sharp edges can increase the risk of injury. Corrective Actions: Ford will notify owners by mail and advise you to take your vehicle to a dealership to inspect and, if necessary, replace the center console.

Lights and instruments202607920 Feb 2026

Issue: On certain vehicles, a software problem with the integrated trailer module (ITRM) may cause the trailer lights not to work when towing. This problem could also cause the trailer brakes not to work on certain vehicles. Note: This problem would cause a "Trailer brake module fault" message to be displayed and turn signal telltale to flash rapidly. This recall also affects certain Super Duty incomplete vehicles. Safety Risk: Trailer lights that don't work could make the vehicle less visible and cause following drivers not to recognize that the vehicle is braking or intends to turn or change lanes. These issues could increase the risk of a crash. Additionally, a loss of trailer brakes could increase the risk of a crash. Corrective Actions: Ford will notify owners by mail and send a wireless over-the-air software update to eligible vehicles to update the ITRM software. Alternatively, you may schedule an appointment to have the update performed at a Ford dealership.

Visual system20252609 May 2025

Issue: On certain vehicles, a software problem could cause the rearview camera image not to display or to freeze when the transmission is shifted into reverse. Safety Risk: A rearview camera image that doesn't display correctly could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: Ford will notify owners by mail and send a wireless over-the-air software update to eligible vehicles to update the SYNC software. Alternatively, you may schedule an appointment to have the update performed at a Ford dealership.

Brakes

2025259 9 May 2025

Issue: On certain vehicles, the front brake lines may have been bent during engine installation. As a result, the brake lines could become damaged by contact with the engine air cleaner outlet pipe. This could lead to a brake fluid leak and cause reduced braking. Safety Risk: Reduced braking can cause extended stopping distances and increase the risk of a crash. Corrective Actions: Ford will notify owners by mail and advise you to take your vehicle to a dealership to inspect and, if necessary, replace the front brake lines and/or the air cleaner outlet pipe.

Engine

2025163 28 Mar 2025

Issue: On certain vehicles, the engine cup plug(s) may not have been installed properly. As a result, engine oil could leak and cause a loss of power to the wheels. Note: This recall only affects certain vehicles equipped with a 3.5 L turbo engine. Vehicles affected by Transport Canada recall no. 2024-687 also require this repair. Safety Risk: A loss of power to the wheels could increase the risk of a crash. Oil that leaks onto hot components can create the risk of a fire. Additionally, an oil leak could create a hazard for others and increase the risk of a crash. Corrective Action: Ford will notify owners by mail and advise you to take your vehicle to a dealership to inspect and, if necessary, replace the cup plug(s).

Engine

2024687 8 Nov 2024

Issue: On certain vehicles, the rear engine cup plug may not have been installed properly. As a result, engine oil could leak and cause a loss of power to the wheels. Note: This recall only affects certain vehicles equipped with a 3.5 L turbo engine. Safety Risk: A loss of power to the wheels could increase the risk of a crash. Oil that leaks onto hot components can create the risk of a fire. Additionally, an oil leak could create a hazard for others and increase the risk of a crash. Corrective Action: Ford will notify owners by mail and advise you to take your vehicle to a dealership to inspect and, if necessary, replace the cup plug.

Listed for the model year, not checked against your VIN. Ford confirms which apply.


Check your VIN with Ford Canada or call a Ford dealer with your VIN.

www.ford.ca/support/recalls/

United States: 7 NHTSA records for this model year, kept apart from the Canadian listing.^[3]

§3 VALUE ^[4]

This car asks \$69,995^[5], \$500 under the median of \$70,495^[4].



Lowest ask	\$62,799
Middle half	\$68,850 – \$77,075
Median ask	\$70,495
This car	\$69,995

Same configuration · 8 live listings · as of 28 Oct 2026

OTHER 2024 FORD EXPEDITION LISTINGS ^[5]

Vanderhoof, BC · 48,604 km	\$78,888
Montréal, QC · 25,947 km	\$72,895
Ottawa, ON · 53,518 km	\$61,075
Steinbach, MB · 113,815 km	\$59,995
Kentville, NS · 100,820 km	\$51,888
Airdrie, AB · 76,100 km	\$59,885

§4 EVENTS

2024

Model year 2024^[1]

Assembly plant Jefferson County, Kentucky, United States



8 Nov 2024	Transport Canada recall 2024687 ^[2] Issued for the model year · Engine
28 Mar 2025	Transport Canada recall 2025163 ^[2] Issued for the model year · Engine
9 May 2025	Transport Canada recall 2025260 ^[2] Issued for the model year · Visual system
9 May 2025	Transport Canada recall 2025259 ^[2] Issued for the model year · Brakes
13 Sep 2025	Listed for sale, Wyoming, ON ^[5] Ron Clark Motors · asking \$69,995
20 Feb 2026	Transport Canada recall 2026079 ^[2] Issued for the model year · Lights and instruments
9 Jun 2026	Transport Canada recall 2026279 ^[2] Issued for the model year · Other
14 Sep 2026	Window sticker collected ^[6] Issued by FORD
27 Oct 2026	Listing last updated ^[5] asking \$69,995

§5 DOCUMENTS ^[6]

Window sticker	PDF, issued by FORD, collected 14 Sep 2026 VIN not read from the file
----------------	--

SOURCES

- | | |
|---|---|
| [1] Cardog identity register, decoded from the VIN | [4] Cardog market quote, same configuration, 8 live listings, as of 28 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year | [5] Live public dealer listings on Cardog, as of 28 Oct 2026 |
| [3] NHTSA recall records (United States), listed for the model year | [6] Window sticker, issued by FORD, collected 14 Sep 2026 |

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote, live public dealer listings and the window sticker. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

