

2020 Chevrolet Bolt EV Premier

FWD · Hatchback · Electric

VEHICLE IDENTIFICATION NUMBER ^[1]**1G1 FZ6S0 4 L 4 129414**

WMI 1-3

Chevrolet · GENERAL MOT...

DESCRIPTOR 4-8

Bolt EV

CHECK 9

Verified

YEAR 10

2020

PLANT 11

Lake Orion

SERIAL 12-17

Build sequence

§1 IDENTITY ^[1]

Model year	2020	Engine	Not in the decode
Make	Chevrolet	Fuel	Electric
Model	Bolt EV	Drive	FWD
Trim	Premier	Maker	GENERAL MOTORS LLC
Body	Hatchback	Plant	Lake Orion, Michigan, United States

§2 OBLIGATIONS ^[2]

cardog.app/tools/recalls/chevrolet/bolt-ev/2020

6 recalls listed by Transport Canada for this model year

High voltage

2024371 27 Jun 2024

Issue: On certain vehicles, the recall repairs completed by a General Motors dealer during recall N212345941/N212345944 (Transport Canada recall no. 2021-524) may not have been done correctly. As a result, a second repair is required. On certain vehicles, the high-voltage battery could overheat when it is charged to over 90% of its capacity. As a result, the battery could create smoke or heat, which can melt or damage the battery and nearby parts. Safety Risk: A battery that overheats can create a fire risk. Corrective Actions: General Motors will notify owners by mail and advise you to take your vehicle to a dealership to install an advanced diagnostic software that will monitor the high-voltage battery and warn you if it detects a problem. If you see this warning, you should contact a dealership to arrange replacement of the affected high-voltage battery module. Please click here for additional information, including precautions to take until the recall repairs are completed, or call 1-800-263-3777 : https://my.gm.ca/chevrolet/en/how-to-support/safety/boltevre recall

Seats and restraints

2023664 14 Dec 2023

Issue: On certain vehicles, the recall repairs may not have been completed by a General Motors dealer during recall N222383790 and/or N222383791 (Transport Canada recall number 2022-719). As a result, a second inspection is required. On certain vehicles, the carpet could catch fire after a crash where a front seat belt pretensioner deploys. Safety Risk: A fire that occurs after a crash could create an increased risk of injury. Corrective Actions: General Motors will notify owners by mail and advise you to take your vehicle to a dealership to inspect and, if necessary, install foil tape under the carpet near the front seatbelt pretensioners. On certain model year vehicles, the technician will also install seatbelt pretensioner covers.



Seats and restraints

2022719 15 Dec 2022

Issue: On certain vehicles, the carpet could catch fire after a crash where a front seat belt pretensioner deploys. Safety Risk: A fire that occurs after a crash could create an increased risk of injury. Corrective Actions: General Motors will notify owners by mail and instruct you to take your vehicle to a dealership to install foil tape under the carpet near the front seatbelt pretensioners. On certain model year vehicles, the technician will also install seatbelt pretensioner covers.

Accessories

2021631 14 Oct 2021

Issue: This recall is for certain driver's all-weather floor liners sold with new vehicles or as accessory parts sold at General Motors dealerships. On certain vehicles, the accelerator pedal could get stuck on the floor liner. If this happens, the vehicle may not slow down when you release the accelerator pedal. Note: If you continue to push the brake pedal, the brake-override system will allow you to stop the vehicle. Safety Risk: A stuck accelerator pedal could lead to unintended acceleration and increase the risk of a crash. Corrective Actions: General Motors will notify owners by mail and instruct you to take your vehicle to a dealer to replace the driver's all-weather floor liner. You should remove the all-weather floor liner until you receive the replacement part.

High voltage

2021524 20 Aug 2021

Issue: On certain vehicles, the high-voltage battery could overheat when it is charged to over 90% of its capacity. As a result, the battery could create smoke or heat, which can melt or damage the battery and nearby parts. Safety Risk: A battery that overheats can create a fire risk. Corrective Actions: General Motors will notify owners by mail and advise you to take your vehicle to a dealership to install an advanced diagnostic software that will monitor the high-voltage battery and warn you if it detects a problem. If you see this warning, you should contact a dealership to arrange replacement of the affected high-voltage battery module. Please click here for additional information, including precautions to take until the recall repairs are completed, or call 1-800-263-3777 : https://my.gm.ca/chevrolet/en/how-to-support/safety/boltevre recall

Structure

2020130 26 Mar 2020

Issue: On certain vehicles, the rear doors may unlatch suddenly due to a damaged cable caused by repeated rear window movement. As a result of this damage, a rear door could open while driving when the window is lowered. A damaged cable may also cause the inside door handle not to work. Safety Risk: A door that opens while the vehicle is moving could create an increased risk of injury. Corrective Actions: General Motors will notify owners by mail and instruct you to take your vehicle to a dealer to replace the inside door handle cable in both rear doors. Note: Until the recall repairs are completed, you can prevent the chance of a door opening while driving by turning on the child lock feature in the rear doors.

Listed for the model year, not checked against your VIN. Chevrolet confirms which apply.

Check your VIN with Chevrolet Canada or call a Chevrolet dealer with your VIN.

www.chevrolet.ca/en/ownercenter/recalls

United States: 8 NHTSA records for this model year, kept apart from the Canadian listing.^[3]

§3 VALUE [4]

This car asks \$25,400^[5], \$7,178 over the median of \$18,222^[4].



Lowest ask	\$10,995
Middle half	\$15,999 – \$20,498
Median ask	\$18,222
This car	\$25,400

Same model year · 20 live listings · as of 28 Oct 2026

OTHER 2020 CHEVROLET BOLT EV LISTINGS [5]

Ste-Julie, QC · 145,260 km	\$14,998
Vancouver, BC · 45,336 km	\$26,500
Kentville, NS · 168,113 km	\$15,999



Notre-Dame-Des-Prairies, QC · 151,522 km	\$15,995
Yarmouth, NS · 168,113 km	\$15,999
Middleton, NS · 168,113 km	\$15,999

§4 EVENTS

2020	Model year 2020 ^[1] Assembly plant Lake Orion, Michigan, United States
26 Mar 2020	Transport Canada recall 2020130 ^[2] Issued for the model year · Structure
20 Aug 2021	Transport Canada recall 2021524 ^[2] Issued for the model year · High voltage
14 Oct 2021	Transport Canada recall 2021631 ^[2] Issued for the model year · Accessories
15 Dec 2022	Transport Canada recall 2022719 ^[2] Issued for the model year · Seats and restraints
14 Dec 2023	Transport Canada recall 2023664 ^[2] Issued for the model year · Seats and restraints
27 Jun 2024	Transport Canada recall 2024371 ^[2] Issued for the model year · High voltage
27 Oct 2026	Listed for sale, Cranbrook, BC ^[5] Jack Carter Northstar GM Cranbrook · asking \$25,400
28 Oct 2026	Listing last updated ^[5] asking \$25,400

§5 DOCUMENTS

Window sticker We have not collected this label yet.

SOURCES

- | | |
|---|---|
| [1] Cardog identity register, decoded from the VIN | [4] Cardog market quote, same model year, 20 live listings, as of 28 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year | [5] Live public dealer listings on Cardog, as of 28 Oct 2026 |
| [3] NHTSA recall records (United States), listed for the model year | |

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

