

Register entry, as of 29 October 2026

Listed for sale

Record ID b302802867d2

# 2000 Chevrolet Silverado

4.8 L, 8 cylinders · 4x2 · Pickup · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

**1GC** **EC14V** **X** **Y** **Z** **326985**

WMI 1-3

Chevrolet · GENERAL MOT...

DESCRIPTOR 4-8

Silverado · 4.8 L

CHECK 9

Verified

YEAR 10

2000

PLANT 11

Roanoke

SERIAL 12-17

Build sequence

## §1 IDENTITY [1]

|            |                   |        |                                 |
|------------|-------------------|--------|---------------------------------|
| Model year | 2000              | Engine | 4.8 L, 8 cylinders              |
| Make       | Chevrolet         | Fuel   | Gasoline                        |
| Model      | Silverado         | Drive  | 4x2                             |
| Trim       | Not in the decode | Maker  | GENERAL MOTORS LLC              |
| Body       | Pickup            | Plant  | Roanoke, Indiana, United States |

## §2 OBLIGATIONS [2]

[cardog.app/tools/recalls/chevrolet/silverado/2000](https://cardog.app/tools/recalls/chevrolet/silverado/2000)

## 10 recalls listed by Transport Canada for this model year

### Other

2006057 9 Mar 2006

On certain vehicles, the galvanized-braided-steel tailgate support cables used to support the tailgate in the full open (horizontal) position can corrode over time and fracture when loads are applied to them. Tailgate support cable corrosion may not be visible because of the plastic sheathing covering the cable. If one cable fractured, the remaining cable may retain the tailgate in a horizontal position. If the remaining cable was weakened by corrosion, it could fracture within moments of the first cable fracture. If both cables fractured, the tailgate would suddenly drop approximately 10 degrees and strike the top surface of the rear bumper. If anyone is sitting or standing on the horizontal surface of the tailgate when both cables fracture, they could fall and be injured. On vehicles without a rear bumper, the tailgate may drop to a lower position. Correction: Dealers will replace the existing galvanized support cables with stainless steel support cables.

### Brakes

2005116 22 Apr 2005

On certain 1999-2002 1500 series and 2001-2005 2500 & 3500 series trucks equipped with a manual transmission, the parking brake friction lining may wear to an extent where the parking brake can become ineffective in immobilizing a parked vehicle. Correction: Dealers will install a low-force spring clip retainer on vehicles equipped with PBR parking brake system and install a redesigned parking brake cable assembly on vehicle equipped with a TRW parking brake system.

### Brakes

2005010 14 Jan 2005

Certain vehicles are equipped with a hydraulic pump driveshaft that can fracture, resulting in immediate loss of hydraulic power steering assist. On certain vehicles equipped with Hydro-Boost power brakes, the same condition can result in loss of power assist for braking after the reserve pressure is depleted. Correction: Dealers will replace the hydraulic pump. This action is deemed a Customer Satisfaction Campaign and is not being conducted under the Safety Act.



**Brakes**

2004395 5 Nov 2004

Certain vehicles located in Ontario, Quebec, New Brunswick, Nova Scotia, Prince Edward Island, and Newfoundland & Labrador may experience unwanted Antilock Brake System (ABS) activation and increased stopping distances during low-speed brake application (less than 16 km/h and greater than 6 km/h). This condition does not set any ABS codes nor does it illuminate the ABS warning lamp. Correction: Dealers will remove the wheel speed sensor and thoroughly clean the wheel speed sensor mounting surface on the bearing, apply Zinc-X to the cleaned surface, grease the mounting surface, reinstall the wheel speed sensor, and check the output voltage to ensure the wheel speed signal is within specifications.

**Other**

2004102 18 Mar 2004

On certain vehicles, the galvanized-braided-steel tailgate support cables used to support the tailgate in the full open (horizontal) position can corrode over time and fracture when loads are applied to them. Tailgate support cable corrosion may not be visible because of the plastic sheathing covering the cable. If one cable fractured, the remaining cable may retain the tailgate in a horizontal position. If the remaining cable was weakened by corrosion, it could fracture within moments of the first cable fracture. If both cables fractured, the tailgate would suddenly drop approximately 10 degrees and strike the top surface of the rear bumper. If anyone is sitting or standing on the horizontal surface of the tailgate when both cables fracture, they could fall and be injured. On vehicles without a rear bumper, the tailgate may drop to a lower position. Correction: Dealers will replace the existing galvanized support cables with stainless steel support cables.

**Airbag**

2002120 28 Jun 2002

Certain vehicles have an air bag sensing diagnostic module (SDM) which contains an anomaly that could result in the driver and passenger's air bag failing to deploy during certain frontal collisions. In a vehicle crash, front seat occupants may receive more severe injuries. Correction: Dealers will recalibrate the SDM.

4 more on the model-year record, [cardog.app/tools/recalls/chevrolet/silverado/2000](https://cardog.app/tools/recalls/chevrolet/silverado/2000)

Listed for the model year, not checked against your VIN. Chevrolet confirms which apply.

Check your VIN with Chevrolet Canada or call a Chevrolet dealer with your VIN.

[www.chevrolet.ca/en/ownercenter/recalls](https://www.chevrolet.ca/en/ownercenter/recalls)

United States: 24 NHTSA records for this model year, kept apart from the Canadian listing.<sup>[3]</sup>

**§3 VALUE [4]**

This car asks \$31,988<sup>[5]</sup>, the median<sup>[4]</sup>.



|             |                     |
|-------------|---------------------|
| Lowest ask  | \$31,988            |
| Middle half | \$31,988 – \$31,988 |
| Median ask  | \$31,988            |
| This car    | \$31,988            |

Same model year · 1 live listings · as of 29 Oct 2026

**§4 EVENTS**

2000 Model year 2000<sup>[1]</sup>  
Assembly plant Roanoke, Indiana, United States

8 Mar 2000 Transport Canada recall 2000055<sup>[2]</sup>  
Issued for the model year · Brakes

8 Mar 2000 Transport Canada recall 2000053<sup>[2]</sup>  
Issued for the model year · Steering



15 Sep 2000      Transport Canada recall 2000194<sup>[2]</sup>  
Issued for the model year · Seats and restraints

17 Nov 2000      Transport Canada recall 2000270<sup>[2]</sup>  
Issued for the model year · Brakes

28 Jun 2002      Transport Canada recall 2002120<sup>[2]</sup>  
Issued for the model year · Airbag

18 Mar 2004      Transport Canada recall 2004102<sup>[2]</sup>  
Issued for the model year · Other

5 Nov 2004      Transport Canada recall 2004395<sup>[2]</sup>  
Issued for the model year · Brakes

14 Jan 2005      Transport Canada recall 2005010<sup>[2]</sup>  
Issued for the model year · Brakes

22 Apr 2005      Transport Canada recall 2005116<sup>[2]</sup>  
Issued for the model year · Brakes

9 Mar 2006      Transport Canada recall 2006057<sup>[2]</sup>  
Issued for the model year · Other

25 Oct 2026      Listed for sale, Gorrie, ON<sup>[5]</sup>  
Pentastic Motors · asking \$31,988

28 Oct 2026      Listing last updated<sup>[5]</sup>  
asking \$31,988

## §5 DOCUMENTS

Window sticker      This VIN reads as model year 2000, before our coverage for this manufacturer.

## SOURCES

[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same model year, 1 live listings, as of 29 Oct 2026

[5] Live public dealer listings on Cardog, as of 29 Oct 2026

## STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

