

Register entry, as of 26 October 2026

Listed for sale

Record ID 32d4132419d8

2003 GMC Envoy

4.2 L, 6 cylinders · 4WD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

1GK DT13S 9 3 2 302511

WMI 1-3

GMC · GENERAL MOTORS...

DESCRIPTOR 4-8

Envoy · 4.2 L

CHECK 9

Verified

YEAR 10

2003

PLANT 11

Moraine

SERIAL 12-17

Build sequence

§1 IDENTITY [1]

Model year	2003	Engine	4.2 L, 6 cylinders
Make	GMC	Fuel	Gasoline
Model	Envoy	Drive	4WD
Trim	Not in the decode	Maker	GENERAL MOTORS LLC
Body	Sport Utility Vehicle	Plant	Moraine, Ohio, United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/gmc/envoy/2003

11 recalls listed by Transport Canada for this model year

Other

2019420 21 Aug 2019

Issue: This recall is for aftermarket replacement rear window glass produced by Vitro Automotriz. Certain rear window glass may not have been properly tempered. If the window breaks, the glass may separate into large pieces instead of very small ones. Note: This is a voluntary recall that is not being conducted under the requirements of the Motor Vehicle Safety Act. Safety Risk: Glass that breaks in to large pieces could create a risk of injury. Corrective Actions: The company will notify consumers by mail and instruct them to inspect the designation code marked on the rear window glass. Products affected by this recall have the designation "DOT 287" along with the lettering "VMR" (Replacement Market) and a date code that is before July 2019. This information is printed on the bottom corner of the glass. Consumers should contact Vitro's customer service at 1-412-995-6457 or argbacklites@vitro.com to arrange for replacement of the glass.

Structure

2005328 27 Oct 2005

Certain vehicles located in Ontario, Quebec, New Brunswick, Nova Scotia, Prince Edward Island, and Newfoundland & Labrador have a rear side door latch that may not latch or not unlatch due to corrosion caused by road splash, such as water and road salt. If the door is not latched properly and goes unnoticed, it could open while the vehicle is in motion. Correction: Dealers will install a seal along the lower part of the rocker panel to prevent intrusion of corrosive material, and inspect the door latch. Functional latches will be cleaned and lubricated. Non-functioning latches will be replaced.

Lights and instruments

2005131 2 May 2005

On certain vehicles, the directional/hazard signals may not operate as designed. Actuation of the turn signal or hazard lights will cause them to illuminate and remain illuminated (not flash as intended). Drivers may not be able to clearly signal their intentions to turn, change travel lanes or potentially warn others of an impaired vehicle operating condition. Correction: Dealers will replace the turn signal/hazard flasher module.



Lights and instruments

2004390 29 Oct 2004

On certain vehicles, vibration and heat may cause the tail lamp/stop lamp bulb to loosen in its socket. If this occurs, the bulb may flicker and eventually become inoperative. The loss of one or both of the tail lamps/stop lamps could reduce the vehicle's visibility to following drivers and fail to warn others that the vehicle is braking and/or is stopped, which could lead to a vehicle crash. Correction: Dealers will inspect the tail lamp/stop lamp assemblies and, if necessary, replace them.

Brakes

2004088 9 Mar 2004

On certain vehicles, the brake hoses are not labelled with a designation that identifies the manufacturer of the assembly as required by CMVSS 106. This non-compliance has no effect on the performance of the involved brake hose assemblies. Correction: Since this does not pose a safety risk, no corrective action is required.

Electrical

2004045 4 Feb 2004

On certain vehicles, water may seep into the windshield wiper module. If this were to happen, it could result in windshield wipers that will not turn on, cease operation while driving, fail to turn off, turn on by themselves, and/or continuous windshield washer pump operation. Improper operation of the windshield wiper system in a severe weather situation could reduce the driver's visibility, resulting in a possible vehicle crash without prior warning. Correction: Dealer will install a Gore-Tex patch over the windshield wiper module vent-hole. The wiper motor, circuit board, and electrical connector will be inspected for signs of water intrusion and/or corrosion and replaced as required.

5 more on the model-year record, cardog.app/tools/recalls/gmc/envoy/2003

Listed for the model year, not checked against your VIN. GMC confirms which apply.
Check your VIN with GMC Canada or call a GMC dealer with your VIN.
www.gmccanada.ca/en/ownercenter/recalls

United States: 10 NHTSA records for this model year, kept apart from the Canadian listing.^[3]

§3 VALUE [4]

This car asks \$6,480^[5], the median^[4].



Lowest ask	\$6,480
Middle half	\$6,480 – \$6,480
Median ask	\$6,480
This car	\$6,480

Same model year · 1 live listings · as of 26 Oct 2026

§4 EVENTS

2003	Model year 2003 ^[1] Assembly plant Moraine, Ohio, United States
13 Aug 2002	Transport Canada recall 2002151 ^[2] Issued for the model year · Airbag
19 Feb 2003	Transport Canada recall 2003037 ^[2] Issued for the model year · Airbag
25 Feb 2003	Transport Canada recall 2003048 ^[2] Issued for the model year · Powertrain



16 Apr 2003	Transport Canada recall 2003098 ^[2] Issued for the model year · Brakes
16 Jul 2003	Transport Canada recall 2003172 ^[2] Issued for the model year · Seats and restraints
4 Feb 2004	Transport Canada recall 2004045 ^[2] Issued for the model year · Electrical
9 Mar 2004	Transport Canada recall 2004088 ^[2] Issued for the model year · Brakes
29 Oct 2004	Transport Canada recall 2004390 ^[2] Issued for the model year · Lights and instruments
2 May 2005	Transport Canada recall 2005131 ^[2] Issued for the model year · Lights and instruments
27 Oct 2005	Transport Canada recall 2005328 ^[2] Issued for the model year · Structure
21 Aug 2019	Transport Canada recall 2019420 ^[2] Issued for the model year · Other
24 Oct 2026	Listed for sale, New Westminster, BC ^[5] Luxor Motor Sports LTD · asking \$6,480

§5 DOCUMENTS

Window sticker This VIN reads as model year 2003, before our coverage for this manufacturer.

SOURCES

- | | |
|---|--|
| [1] Cardog identity register, decoded from the VIN | [4] Cardog market quote, same model year, 1 live listings, as of 26 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year | [5] Live public dealer listings on Cardog, as of 26 Oct 2026 |
| [3] NHTSA recall records (United States), listed for the model year | |

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

