

Register entry, as of 28 October 2026

Listed for sale

Record ID 55182811e714

2016 GMC Yukon Denali

6.2 L, 8 cylinders · 4WD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

1GK S2CKJ 3 G R 330395

WMI 1-3

GMC · GENERAL MOTORS...

DESCRIPTOR 4-8

Yukon · 6.2 L

CHECK 9

Verified

YEAR 10

2016

PLANT 11

Arlington

SERIAL 12-17

Build sequence

§1 IDENTITY [1]

Model year	2016	Engine	6.2 L, 8 cylinders
Make	GMC	Fuel	Gasoline
Model	Yukon	Drive	4WD
Trim	Denali	Maker	GENERAL MOTORS LLC
Body	Sport Utility Vehicle	Plant	Arlington, Texas, United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/gmc/yukon/2016

6 recalls listed by Transport Canada for this model year

Brakes

2019533 24 Oct 2019

Issue: On certain vehicles, there may be an error in the electronic-brake control module software. This could cause the driveline-protection system to activate when a wheel-speed sensor fails. If this happens, the brakes could apply and cause the vehicle to pull to one side. Note: This recall only affects vehicles equipped with four-wheel drive, a 5.3-L engine, and a 3.08 ratio rear axle. The problem can only occur when the vehicle is in four-wheel drive or automatic mode, and travelling at a speed between 66 and 97 km/h (41 and 60 mph). A wheel-speed sensor failure will cause the electronic stability control (ESC) and anti-lock braking system (ABS) warning lights to turn on, and a "Service StabiliTrak" message to display. Safety Risk: A vehicle that suddenly pulls to one side could increase the risk of a crash. Corrective Actions: General Motors will notify owners by mail and instruct you to take your vehicle to a dealer to update the electronic-brake control module software. General Motors advises that using two-wheel-drive mode can eliminate the risk until the recall repair is completed.

Other

2019420 21 Aug 2019

Issue: This recall is for aftermarket replacement rear window glass produced by Vitro Automotriz. Certain rear window glass may not have been properly tempered. If the window breaks, the glass may separate into large pieces instead of very small ones. Note: This is a voluntary recall that is not being conducted under the requirements of the Motor Vehicle Safety Act. Safety Risk: Glass that breaks in to large pieces could create a risk of injury. Corrective Actions: The company will notify consumers by mail and instruct them to inspect the designation code marked on the rear window glass. Products affected by this recall have the designation "DOT 287" along with the lettering "VMR" (Replacement Market) and a date code that is before July 2019. This information is printed on the bottom corner of the glass. Consumers should contact Vitro's customer service at 1-412-995-6457 or argbacklites@vitro.com to arrange for replacement of the glass.



Brakes

2019324 28 Jun 2019

Issue: On certain vehicles, there could be a reduction in power brake assist due to a decrease in output from the vacuum pump. This could cause a hard brake pedal and an increase in brake pedal effort to stop the vehicle. Safety Risk: A sudden increase in brake pedal force could lead to an increase in stopping distance. This could increase the risk of a crash. Corrective Actions: The company will notify owners by mail and instruct them to take their vehicle to a dealer to reprogram the electronic brake control module.

Tires

2016502 12 Oct 2016

On certain vehicles equipped with Continental P275/55R20 CrossContact LX20 tires, a manufacturing defect could cause a lack of adhesion between belts in the tire. Affected tires may exhibit localized tread wear, excessive vibration, noise and bulging in the tread area. Continued use could cause the belts to separate, which could lead to full belt/tread loss. This could increase the risk of a crash causing injury and/or damage to property. Correction: Dealers will inspect tire date code markings to determine whether they are from the affected date code. Affected tires will be replaced.

Airbag

2016439 9 Sep 2016

On certain vehicles, the sensing and diagnostic module (SDM), which controls airbag and pretensioner deployment, contains a software defect which may prevent the deployment of frontal airbags and pretensioners in certain circumstances. Failure of frontal airbags and seatbelt pretensioners to deploy in a crash (when warranted) could increase the risk of injury. Correction: Dealers will reflash the SDM with new software. In vehicles with any previous deployment events recorded in the SDM, the dealers will replace the existing SDM with a new SDM containing the latest software. Note: This recall affects 2014–2017 model year Sierra LD/Silverado LD models and 2015–2016 model year Sierra HD/Silverado HD model vehicles.

Suspension

2016190 28 Apr 2016

Certain vehicles may have been built with front upper control arms with a poor quality weld near the control arm's bushing. If these welds were to fail, it could cause the upper control arm to deform or separate from the bushing, which could affect steering and directional control of the vehicle, increasing the risk of a crash causing injury and/or property damage. Correction: Dealers will replace the left and right front upper control arms, and perform a realignment.

Listed for the model year, not checked against your VIN. GMC confirms which apply.

Check your VIN with GMC Canada or call a GMC dealer with your VIN.

www.gmccanada.ca/en/ownercenter/recalls

United States: 5 NHTSA records for this model year, kept apart from the Canadian listing.^[3]

§3 VALUE ^[4]

This car asks \$19,888^[5], \$6,794 under the median of \$26,682^[4].



Lowest ask	\$17,998
Middle half	\$19,762 – \$29,425
Median ask	\$26,682
This car	\$19,888

Same configuration · 8 live listings · as of 28 Oct 2026

OTHER 2016 GMC YUKON LISTINGS ^[5]

Lethbridge, AB · 256,871 km	\$31,000
Lethbridge, AB · 256,871 km	\$31,000
Stettler, AB · 256,491 km	\$31,000
Lethbridge, AB · 256,871 km	\$31,000
Lethbridge, AB · 194,270 km	\$27,995
Burlington, ON · 116,616 km	\$30,700



§4 EVENTS

2016	Model year 2016 ^[1] Assembly plant Arlington, Texas, United States
28 Apr 2016	Transport Canada recall 2016190 ^[2] Issued for the model year · Suspension
9 Sep 2016	Transport Canada recall 2016439 ^[2] Issued for the model year · Airbag
12 Oct 2016	Transport Canada recall 2016502 ^[2] Issued for the model year · Tires
28 Jun 2019	Transport Canada recall 2019324 ^[2] Issued for the model year · Brakes
21 Aug 2019	Transport Canada recall 2019420 ^[2] Issued for the model year · Other
24 Oct 2019	Transport Canada recall 2019533 ^[2] Issued for the model year · Brakes
28 May 2026	Listed for sale, Mississauga, ON ^[5] Leopard Motors Inc · asking \$19,888
28 Oct 2026	Listing last updated ^[5] asking \$19,888

§5 DOCUMENTS

Window sticker This VIN reads as model year 1986 or 2016, before our coverage for this manufacturer.

SOURCES

- | | |
|---|---|
| [1] Cardog identity register, decoded from the VIN | [4] Cardog market quote, same configuration, 8 live listings, as of 28 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year | [5] Live public dealer listings on Cardog, as of 28 Oct 2026 |
| [3] NHTSA recall records (United States), listed for the model year | |

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

