

Register entry, as of 28 October 2026

Listed for sale Record ID b2fcd561c97d

2024 GMC Sierra HD Fleet/Base

6.6 L, 8 cylinders · 4WD · Pickup · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

1GT 49SE7 9 R F 228193

WMI 1-3	DESCRIPTOR 4-8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12-17
GMC · GENERAL MOTORS...	Sierra HD · 6.6 L	Verified	2024	Flint	Build sequence

§1 IDENTITY [1]

Model year	2024	Engine	6.6 L, 8 cylinders
Make	GMC	Fuel	Gasoline
Model	Sierra HD	Drive	4WD
Trim	Fleet/Base	Maker	GENERAL MOTORS LLC
Body	Pickup	Plant	Flint, Michigan, United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/gmc/sierra-hd/2024

6 recalls listed by Transport Canada for this model year

Tires 2026394 13 Aug 2026

Issue: On one truck, the tire pressure label lists the incorrect rear tire pressure information. This could lead you to underinflate the tires and could cause poor handling and/or a tire failure. Note: This recall only affects one truck equipped with the enhanced towing option and a 20-inch tire and wheel accessory package. Safety Risk: Poor handling or a tire failure could cause a loss of control and result in a crash. Corrective Actions: General Motors will notify the owner by mail and advise them to take their truck to a dealership to inspect and, if necessary, install a tire label overlay, update the engine control module, inflate the tires to the correct pressure and calibrate the tire pressure monitor system (TPMS).

Structure 2024720 26 Nov 2024

Issue: On certain trucks, water could leak into the exterior tailgate switch. As a result, the tailgate could unlatch and open unexpectedly while parked. If this happens, cargo that is not secured could fall out of the truck bed and onto the road when the vehicle is moving. Note: This recall only affects trucks equipped with a power-locking tailgate. This recall is an expansion of GM recall no. N232426400 (Transport Canada recall no. 2024-061. Safety Risk: Cargo that falls from the truck bed could create a road hazard for others and increase the risk of a crash. Corrective Actions: General Motors will notify owners by mail and advise you to take your truck to a dealership to replace the exterior tailgate switch. To reduce the safety risk, General Motors recommends that you should inspect the tailgate to ensure it's closed and latched before driving.

Structure 2024061 1 Feb 2024

Issue: On certain trucks, water could leak into the exterior tailgate switch. As a result, the tailgate could unlatch and open unexpectedly while parked. If this happens, cargo that is not secured could fall out of the truck bed and onto the road when the vehicle is moving. Note: This recall only affects trucks equipped with a power-locking tailgate. Safety Risk: Cargo that falls from the truck bed could create a road hazard for others and increase the risk of a crash. Corrective Actions: General Motors will notify owners by mail and advise you to take your truck to a dealership to replace the exterior tailgate switch. To reduce the safety risk, General Motors recommends that you should inspect the tailgate to ensure it's closed and latched before driving.



Lights and instruments

2024060 1 Feb 2024

Issue: On certain vehicles, a software problem could cause the lower beam headlamps not to turn on as it becomes dark outside if the multi-function switch is in the "OFF" or "PARKING LAMP" position. This could also cause the daytime running lamps (DRLs) to turn off when the vehicle is moving. As a result, the vehicles may not meet certain requirements of Canadian regulations. Safety Risk: Headlamps and/or DRLs that don't turn on could reduce visibility, make the vehicle less visible to others and increase the risk of a crash. Corrective Actions: General Motors will notify owners by mail and advise you to take your vehicle to a dealership to update the body control module (BCM) software.

Lights and instruments

2023472 24 Aug 2023

Issue: On certain vehicles, the automatic headlamps may not turn on soon enough as it becomes dark outside. Canadian regulations require automatic headlamps to turn on when the ambient light level drops below a certain point (1000 lux). Safety Risk: Headlamps that don't turn on as it becomes dark outside could reduce visibility and increase the risk of a crash. Corrective Actions: General Motors will notify owners by mail and send a wireless over-the-air software update to eligible vehicles to update the body control module (BCM) software. Alternatively, you may schedule an appointment to have the update performed at a GM dealership.

Steering

2023429 3 Aug 2023

Issue: On certain trucks, the steering gear shaft may not have been manufactured properly. As a result, the steering gear shaft could break and cause a loss of steering control. Safety Risk: A loss of steering control could increase the risk of a crash. Corrective Actions: General Motors will notify owners by mail and advise you to take your truck to a dealership to inspect the steering gear assembly, and replace it if necessary.


Listed for the model year, not checked against your VIN. GMC confirms which apply.

Check your VIN with GMC Canada or call a GMC dealer with your VIN.

www.gmccanada.ca/en/ownercenter/recalls

§3 VALUE [3]

This car asks \$69,800^[4], \$12,740 under the median of \$82,540^[3].



Lowest ask	\$47,995
Middle half	\$74,073 – \$89,402
Median ask	\$82,540
This car	\$69,800

Same model year · 136 live listings · as of 28 Oct 2026

OTHER 2024 GMC SIERRA HD LISTINGS [4]

Calgary, AB · 85,000 km	\$47,995
Mississauga, ON · 33,122 km	\$80,751
Mississauga, ON · 71,142 km	\$75,751
Drayton Valley, AB · 88,322 km	\$49,704
Drayton Valley, AB · 44,668 km	\$32,995
Mississauga, ON · 29,730 km	\$58,751

§4 EVENTS

2024

Model year 2024^[1]

Assembly plant Flint, Michigan, United States



3 Aug 2023	Transport Canada recall 2023429 ^[2] Issued for the model year · Steering
24 Aug 2023	Transport Canada recall 2023472 ^[2] Issued for the model year · Lights and instruments
1 Feb 2024	Transport Canada recall 2024061 ^[2] Issued for the model year · Structure
1 Feb 2024	Transport Canada recall 2024060 ^[2] Issued for the model year · Lights and instruments
26 Nov 2024	Transport Canada recall 2024720 ^[2] Issued for the model year · Structure
28 Apr 2026	Listed for sale, Headingley, MB ^[4] Winnipeg West Automotive Group · asking \$69,800
13 Aug 2026	Transport Canada recall 2026394 ^[2] Issued for the model year · Tires
27 Oct 2026	Listing last updated ^[4] asking \$69,800

§5 DOCUMENTS

Window sticker We have not collected this label yet.

SOURCES

- | | |
|---|--|
| [1] Cardog identity register, decoded from the VIN | [3] Cardog market quote, same model year, 136 live listings, as of 28 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year | [4] Live public dealer listings on Cardog, as of 28 Oct 2026 |

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

