

Register entry, as of 27 October 2026

Listed for sale

Record ID cd78bca85ed5

2014 GMC Savana

4.8 L, 8 cylinders · RWD · Cargo Van · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

1GT W7FCA 7 E 1 143087

WMI 1-3

GMC · GENERAL MOTORS...

DESCRIPTOR 4-8

Savana · 4.8 L

CHECK 9

Verified

YEAR 10

2014

PLANT 11

Wentzville

SERIAL 12-17

Build sequence

§1 IDENTITY [1]

Model year	2014	Engine	4.8 L, 8 cylinders
Make	GMC	Fuel	Gasoline
Model	Savana	Drive	RWD
Trim	Not in the decode	Maker	GENERAL MOTORS LLC
Body	Cargo Van	Plant	Wentzville, Missouri, United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/gmc/savana/2014

7 recalls listed by Transport Canada for this model year

Electrical

2023210 6 Apr 2023

Issue: On certain vehicles, an unused wiring harness for a rear HVAC blower motor, located in the left B-pillar area, could become damaged if exposed to moisture or contaminants. If this happens, the wires could short circuit. Note: This recall only affects cutaway chassis incomplete vehicles. Safety Risk: A short circuit can create the risk of a fire. Corrective Actions: General Motors will notify owners by mail and instruct you to bring your vehicle to a dealership to seal the wiring for the rear HVAC blower motor at the left B-pillar.

Other

2020479 7 Oct 2020

Issue: Certain vehicles may have incorrect body control module software. As a result, the immobilization system is not active during the learning procedure for a new "unlearned" blank replacement key could be used during a 30 minute reprogramming procedure to disable the immobilization system. During this time, the vehicle cannot be driven. Safety Risk: This small error does not affect vehicle safety. Corrective Actions: This is not a recall. General Motors has made changes to vehicle software to ensure that all unsold and new vehicles have the correct body control module software.

Electrical

2018234 4 May 2018

On certain vehicles equipped with power windows, liquid can enter the power window switches causing corrosion and lead to a high electrical resistance. This could cause the switch to heat up, smoke or melt, which would increase the risk of fire causing injury and/or damage to property. Correction: Dealers will replace the driver's side window switch with a switch that has additional protection against liquid intrusion.



Brakes

2015352 5 Aug 2015

Certain vehicles equipped with a hinged left side rear door may have a condition where inadequate clearance between the rear brake lines and the lower fuel filler hose clamp may result in abrasion to one or both rear brake lines. This condition could cause brake fluid loss which could result in decreased brake line pressure, increased brake pedal travel and increased stopping distance, increasing the risk of a crash causing injury and/or damage to property. This condition could cause various warning lights to illuminate in the instrument panel of the vehicle such the red "BRAKE" telltale symbol; illumination of the Stabilitrak telltale symbol; scrolling display of "Service Brake", "Service Stabilitrak," and "Service Traction Control" messages in the Driver Information Centre (DIC); and audible alerts/chimes. Correction: Dealers will inspect the brake lines. If the clearance is found to be below specification, the brake lines will be replaced with a new part design that provides adequate clearance.

Electrical

2014432 3 Oct 2014

On certain vehicles, the chassis electronic module may have been contaminated at time of manufacture, which could cause an electrical short to occur within the module. This could cause the vehicle's check engine light to be displayed, or cause the engine to fail to start or stall, resulting in a loss of motive power. If the vehicle is equipped to support electric trailer brakes, the vehicle could also lose trailer brake function and display a "Service Trailer Brake System" indicator. These issues could increase the risk of a crash resulting in injury and/or damage to property. Correction: Dealers will replace the module with a revised part.

Fuel system

2014352 19 Aug 2014

On certain compressed natural gas (CNG) fuelled vehicles, the CNG high pressure regulator may leak natural gas. Should a leak occur in the presence of an ignition source, a fire or explosion could result, increasing the risk of injury and/or damage to property. Correction: Dealers will replace the regulator. Note: If a leak is suspected, owners should not start nor drive their vehicles, and have the vehicle immediately towed, inspected and repaired.

1 more on the model-year record, cardog.app/tools/recalls/gmc/savana/2014

Listed for the model year, not checked against your VIN. GMC confirms which apply.

Check your VIN with GMC Canada or call a GMC dealer with your VIN.

www.gmccanada.ca/en/ownercenter/recalls

United States: 7 NHTSA records for this model year, kept apart from the Canadian listing.^[3]

§3 VALUE ^[4]

This car asks \$14,995^[5], \$4,805 over the median of \$10,190^[4].



Lowest ask	\$9,999
Middle half	\$9,999 – \$12,995
Median ask	\$10,190
This car	\$14,995

Same model year · 5 live listings · as of 27 Oct 2026

OTHER 2014 GMC SAVANA LISTINGS ^[5]

Fenwick, ON · 234,000 km	\$10,190
Scarborough, ON · 203,000 km	\$9,999
London, ON · 261,000 km	\$9,999
Calgary, AB · 289,426 km	\$12,995



§4 EVENTS

2014	Model year 2014 ^[1] Assembly plant Wentzville, Missouri, United States
18 Mar 2014	Transport Canada recall 2014083 ^[2] Issued for the model year · Seats and restraints
19 Aug 2014	Transport Canada recall 2014352 ^[2] Issued for the model year · Fuel system
3 Oct 2014	Transport Canada recall 2014432 ^[2] Issued for the model year · Electrical
5 Aug 2015	Transport Canada recall 2015352 ^[2] Issued for the model year · Brakes
4 May 2018	Transport Canada recall 2018234 ^[2] Issued for the model year · Electrical
7 Oct 2020	Transport Canada recall 2020479 ^[2] Issued for the model year · Other
6 Apr 2023	Transport Canada recall 2023210 ^[2] Issued for the model year · Electrical
25 Jun 2026	Listed for sale, Toronto, ON ^[5] Azores Auto Group · asking \$14,995
27 Oct 2026	Listing last updated ^[5] asking \$14,995

§5 DOCUMENTS

Window sticker This VIN reads as model year 1984 or 2014, before our coverage for this manufacturer.

SOURCES

- | | |
|---|--|
| [1] Cardog identity register, decoded from the VIN | [4] Cardog market quote, same model year, 5 live listings, as of 27 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year | [5] Live public dealer listings on Cardog, as of 27 Oct 2026 |
| [3] NHTSA recall records (United States), listed for the model year | |

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

