

Register entry, as of 29 October 2026

Listed for sale

Record ID 06ab21c17c5f

1999 Honda Accord EX-V6

3.0 L, 6 cylinders · Coupe · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

1HG CG225 7 X A 801429

WMI 1-3

American Honda Motor Co...

DESCRIPTOR 4-8

Accord · 3.0 L

CHECK 9

Verified

YEAR 10

1999

PLANT 11

Marysville

SERIAL 12-17

Build sequence

§1 IDENTITY [1]

Model year	1999	Engine	3.0 L, 6 cylinders
Make	Honda	Fuel	Gasoline
Model	Accord	Drive	Not in the decode
Trim	EX-V6	Maker	AMERICAN HONDA MOTOR CO., INC.
Body	Coupe	Plant	Marysville, Ohio, United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/honda/accord/1999

4 recalls listed by Transport Canada for this model year

Airbag

2020014 17 Jan 2020

Issue: On certain vehicles, exposure to moisture over time could cause the driver-front airbag not to inflate properly in a crash. In some cases, this could cause an airbag not to fully inflate, while in others it could cause it to deploy with more force than normal. It could also cause the inflator to rupture. If the airbag inflator ruptures, small pieces of metal could be propelled toward vehicle occupants or cause damage to the airbag and prevent its proper function. Safety Risk: In a crash requiring an airbag deployment, the driver-front airbag may not inflate properly or the inflator could rupture. This could create a risk of injury. Corrective Actions: The company will notify owners by mail. There may be a significant delay before replacement parts are available. The company will send you a second letter once replacement parts are available and instruct you to take your vehicle to a dealer to inspect the driver-front airbag inflator. If the inflator requires replacement, a newly design part will be installed.

Other

2005037 15 Feb 2005

On certain vehicles, the interlock operation of the ignition switch may not function properly, making it possible to turn the ignition key to the OFF position and remove the key without shifting the transmission to PARK. If the driver does not shift to PARK before removing the key and fails to engage the parking brake, the vehicle could roll and a crash could occur. Correction: Dealers will perform the required inspection and necessary repairs.

Other

2003276 10 Nov 2003

On certain vehicles, the ignition switch may wear excessively and prevent proper interlock operation, making it possible to turn the ignition key to the off position and remove the key without shifting the transmission to Park. If the vehicle operator does not shift to Park before removing the key and fails to engage the parking brake, the vehicle could roll and a crash could occur. Correction: Dealer will perform the required inspection and necessary repairs.



Electrical

2002096 24 May 2002

On certain vehicles electrical contacts in the ignition switch can degrade due to the high electrical current passing through the switch when the vehicle is started. Worn contacts could cause the engine to stall without warning, increasing the risk of a crash. Correction: Dealers will replace the ignition switch.

Listed for the model year, not checked against your VIN. Honda confirms which apply.
Check your VIN with Honda Canada or call a Honda dealer with your VIN.
www.honda.ca/en/recalls

United States: 17 NHTSA records for this model year, kept apart from the Canadian listing.^[3]

§3 VALUE ^[4]

This car asks \$6,995^[5], the median^[4].



Lowest ask	\$6,995
Middle half	\$6,995 – \$6,995
Median ask	\$6,995
This car	\$6,995

Same model year · 1 live listings · as of 29 Oct 2026

§4 EVENTS

1999	Model year 1999 ^[1] Assembly plant Marysville, Ohio, United States
24 May 2002	Transport Canada recall 2002096 ^[2] Issued for the model year · Electrical
10 Nov 2003	Transport Canada recall 2003276 ^[2] Issued for the model year · Other
15 Feb 2005	Transport Canada recall 2005037 ^[2] Issued for the model year · Other
17 Jan 2020	Transport Canada recall 2020014 ^[2] Issued for the model year · Airbag
28 Oct 2026	Listed for sale, Richmond, BC ^[5] Transparent Motorcars · asking \$6,995
29 Oct 2026	Listing last updated ^[5] asking \$6,995

§5 DOCUMENTS



Window sticker We do not collect window stickers for this manufacturer.

SOURCES

- | | |
|---|--|
| [1] Cardog identity register, decoded from the VIN | [4] Cardog market quote, same model year, 1 live listings, as of 29 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year | |
| [3] NHTSA recall records (United States), listed for the model year | [5] Live public dealer listings on Cardog, as of 29 Oct 2026 |

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

