

Register entry, as of 28 October 2026

Listed for sale

Record ID 6063e8e53709

# 2021 Honda Accord SE

1.5 L, 4 cylinders · FWD · Sedan · Gasoline

VEHICLE IDENTIFICATION NUMBER <sup>[1]</sup>**1HG CV1F2 8 M A 801516**

WMI 1-3

American Honda Motor Co...

DESCRIPTOR 4-8

Accord · 1.5 L

CHECK 9

Verified

YEAR 10

2021

PLANT 11

Marysville

SERIAL 12-17

Build sequence

§1 IDENTITY <sup>[1]</sup>

|            |        |        |                                 |
|------------|--------|--------|---------------------------------|
| Model year | 2021   | Engine | 1.5 L, 4 cylinders              |
| Make       | Honda  | Fuel   | Gasoline                        |
| Model      | Accord | Drive  | FWD                             |
| Trim       | SE     | Maker  | AMERICAN HONDA MOTOR CO., INC.  |
| Body       | Sedan  | Plant  | Marysville, Ohio, United States |

§2 OBLIGATIONS <sup>[2]</sup>[cardog.app/tools/recalls/honda/accord/2021](https://cardog.app/tools/recalls/honda/accord/2021)

## 2 recalls listed by Transport Canada for this model year

### Seats and restraints

2026251 21 May 2026

Issue: On certain vehicles, the weight sensor for the front passenger seat may not have been manufactured properly. As a result, the passenger-front airbag and knee airbag could deploy in a crash that doesn't require them to. Note: This recall is an expansion of Transport Canada recall no. 2024-059. If the weight sensor fails, the SRS warning light would turn on in the instrument panel. Safety Risk: An airbag system that doesn't work properly could increase the risk of injury in a crash. Corrective Actions: The company will notify owners by mail and advise you to take your vehicle to a dealership to replace the passenger-front seat weight sensor.

### Airbag

2024059 1 Feb 2024


Issue: On certain vehicles, the weight sensor for the front passenger seat may not have been manufactured properly. As a result, the passenger-front airbag and knee airbag could deploy in a crash that doesn't require them to. Note: If the weight sensor fails, the SRS warning light would turn on in the instrument panel. Safety Risk: An airbag system that doesn't work properly could increase the risk of injury in a crash. Corrective Actions: Honda will notify owners by mail and advise you to take your vehicle to a dealership for an inspection if the SRS warning light is on. If the SRS warning light is on due to a faulty weight sensor, the weight sensor will be replaced. When repair parts are available, Honda will send you a second letter. They will advise you to take your vehicle to a dealership to replace the passenger-front seat weight sensor.

Listed for the model year, not checked against your VIN. Honda confirms which apply.  
Check your VIN with Honda Canada or call a Honda dealer with your VIN.  
[www.honda.ca/en/recalls](https://www.honda.ca/en/recalls)

United States: 4 NHTSA records for this model year, kept apart from the Canadian listing.<sup>[3]</sup>

## §3 VALUE [4]

This car asks \$22,995<sup>[5]</sup>, \$2,994 under the median of \$25,989<sup>[4]</sup>.



|             |                     |
|-------------|---------------------|
| Lowest ask  | \$19,950            |
| Middle half | \$23,745 – \$28,002 |
| Median ask  | \$25,989            |
| This car    | \$22,995            |

Same model year · 31 live listings · as of 28 Oct 2026

## OTHER 2021 HONDA ACCORD LISTINGS [5]

|                          |          |
|--------------------------|----------|
| Lévis, QC · 134,000 km   | \$19,950 |
| Toronto, ON · 40,590 km  | \$27,995 |
| Toronto, ON · 119,000 km | \$23,450 |
| Toronto, ON · 108,000 km | \$25,950 |
| Toronto, ON · 113,000 km | \$26,450 |
| Richmond, BC · 91,957 km | \$23,995 |

## §4 EVENTS

|             |                                                                                                    |
|-------------|----------------------------------------------------------------------------------------------------|
| 2021        | Model year 2021 <sup>[1]</sup><br>Assembly plant Marysville, Ohio, United States                   |
| 1 Feb 2024  | Transport Canada recall 2024059 <sup>[2]</sup><br>Issued for the model year · Airbag               |
| 21 May 2026 | Transport Canada recall 2026251 <sup>[2]</sup><br>Issued for the model year · Seats and restraints |
| 5 Sep 2026  | Listed for sale, Antigonish, NS <sup>[5]</sup><br>Keltic Ford · asking \$22,995                    |
| 28 Oct 2026 | Listing last updated <sup>[5]</sup><br>asking \$22,995                                             |

## §5 DOCUMENTS

|                |                                                          |
|----------------|----------------------------------------------------------|
| Window sticker | We do not collect window stickers for this manufacturer. |
|----------------|----------------------------------------------------------|

## SOURCES

|                                                                     |                                                                               |
|---------------------------------------------------------------------|-------------------------------------------------------------------------------|
| [1] Cardog identity register, decoded from the VIN                  | [4] Cardog market quote, same model year, 31 live listings, as of 28 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year     | [5] Live public dealer listings on Cardog, as of 28 Oct 2026                  |
| [3] NHTSA recall records (United States), listed for the model year |                                                                               |



---

**STATEMENT OF SCOPE**

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

