

Register entry, as of 28 October 2026

Listed for sale

Record ID 169ee25adc9a

2009 Chevrolet Impala LS

3.5 L, 6 cylinders · Sedan · Flexible Fuel Vehicle (FFV)

VEHICLE IDENTIFICATION NUMBER [1]

2G1WB57K591324936

WMI 1-3

Chevrolet · GENERAL MOT...

DESCRIPTOR 4-8

Impala · 3.5 L

CHECK 9

Verified

YEAR 10

2009

PLANT 11

Oshawa #2

SERIAL 12-17

Build sequence

§1 IDENTITY [1]

Model year	2009	Engine	3.5 L, 6 cylinders
Make	Chevrolet	Fuel	Flexible Fuel Vehicle (FFV)
Model	Impala	Drive	Not in the decode
Trim	LS	Maker	GENERAL MOTORS LLC
Body	Sedan	Plant	Oshawa #2, Ontario, Canada

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/chevrolet/impala/2009

6 recalls listed by Transport Canada for this model year

Other

2019420 21 Aug 2019

Issue: This recall is for aftermarket replacement rear window glass produced by Vitro Automotriz. Certain rear window glass may not have been properly tempered. If the window breaks, the glass may separate into large pieces instead of very small ones. Note: This is a voluntary recall that is not being conducted under the requirements of the Motor Vehicle Safety Act. Safety Risk: Glass that breaks in to large pieces could create a risk of injury. Corrective Actions: The company will notify consumers by mail and instruct them to inspect the designation code marked on the rear window glass. Products affected by this recall have the designation "DOT 287" along with the lettering "VMR" (Replacement Market) and a date code that is before July 2019. This information is printed on the bottom corner of the glass. Consumers should contact Vitro's customer service at 1-412-995-6457 or argbacklites@vitro.com to arrange for replacement of the glass.

Electrical

2016340 30 Jun 2016

On certain vehicles, the front passenger seat frame may damage the wires of the passenger presence sensor (PPS) module. If this occurs, the system may fail to detect an occupant in passenger seat and improperly suppress the front passenger airbag. The damage could also cause the airbag fuse to short, disabling air bags and seatbelt pretensioners. These issues could increase the risk of injury to vehicle occupants in a crash where airbag and/or pretensioner deployment is warranted. Correction: Dealers will inspect wiring and repair as necessary, as well as apply protective anti-abrasion tape. Note: If the passenger airbag is suppressed, the passenger airbag status indicator would indicate that the passenger airbag is off even when a passenger is sitting in the front passenger seat. In addition, the "service airbag" message would be displayed in the driver information centre (DIC). This could also cause the cluster gauges and DIC alerts to intermittently turn off or not function properly.



Electrical

2014246 23 Jun 2014

On certain vehicles, a defect in the ignition switch could allow the switch to move out of the "run" position if the key ring is carrying added weight or the vehicle goes off-road or is subjected to some other jarring event. If this were to occur, engine power, power steering and power braking would be affected, increasing the risk of a crash causing injury and/or damage to property. The timing of the key movement out of the "run" position, relative to the activation of the sensing algorithm of the crash event, may also result in the airbags not deploying in a subsequent collision, increasing the risk of injury. Correction: For each key, dealers will install two key rings and modify the key ring opening shape. Note: Until the correction is performed, all items should be removed from the key ring.

Suspension

2012255 3 Aug 2012

On certain Chevrolet Impala police vehicles, the front control arms may fracture. If this occurs, some tire "squeal" or "chirping" may be heard when turning at low speeds. Sudden changes could occur in vehicle handling and, particularly at higher speeds, the driver may not be able to control the vehicle and a crash could occur, which may result in personal injury and/or property damage. Correction: Dealers will replace both control arms.

Seats and restraints

2010352 13 Oct 2010

Certain vehicles fail to conform to Canada Motor Vehicle Safety Standard 210 – Seat Belt Assembly Anchorages. The front seatbelt webbing may not have been properly secured to the lap belt anchor pretensioner mounted to the side of the seat nearest the door. As a result, the seatbelt may not restrain the occupant as intended during a crash, which could result in injury to the occupant. Correction: Dealers will inspect both front seatbelts for proper installation of anchors to pretensioners and, if necessary, reinstall the anchors.

Airbag

2008364 7 Oct 2008

On certain vehicles, the passenger-side airbag inflator was not built to GM's Specification and could fracture during a deployment. Pieces of the inflator could strike and injure occupants and the airbag cushion would not inflate fully therefore reducing the capability of the airbag to protect the passenger. Correction: Dealers will install a new passenger-side airbag.

Listed for the model year, not checked against your VIN. Chevrolet confirms which apply.

Check your VIN with Chevrolet Canada or call a Chevrolet dealer with your VIN.

www.chevrolet.ca/en/ownercenter/recalls

United States: 5 NHTSA records for this model year, kept apart from the Canadian listing.^[3]

§3 VALUE ^[4]

This car asks \$3,995^[5], \$151 over the median of \$3,844^[4].



Lowest ask \$3,499

Middle half \$3,645 – \$3,995

Median ask \$3,844

This car \$3,995

Same model year · 4 live listings · as of 28 Oct 2026

OTHER 2009 CHEVROLET IMPALA LISTINGS ^[5]

Charlottetown, PE · 210,552 km	\$3,694
Brooks, AB · 321,789 km	\$3,499
London, ON · 170,376 km	\$3,995



§4 EVENTS

2009	Model year 2009 ^[1] Assembly plant Oshawa #2, Ontario, Canada
7 Oct 2008	Transport Canada recall 2008364 ^[2] Issued for the model year · Airbag
13 Oct 2010	Transport Canada recall 2010352 ^[2] Issued for the model year · Seats and restraints
3 Aug 2012	Transport Canada recall 2012255 ^[2] Issued for the model year · Suspension
23 Jun 2014	Transport Canada recall 2014246 ^[2] Issued for the model year · Electrical
30 Jun 2016	Transport Canada recall 2016340 ^[2] Issued for the model year · Electrical
21 Aug 2019	Transport Canada recall 2019420 ^[2] Issued for the model year · Other
4 Oct 2026	Listed for sale, Kamloops, BC ^[5] Automotion Motors & RV Ltd · asking \$3,995
27 Oct 2026	Listing last updated ^[5] asking \$3,995

§5 DOCUMENTS

Window sticker This VIN reads as model year 2009, before our coverage for this manufacturer.

SOURCES

- | | |
|---|--|
| [1] Cardog identity register, decoded from the VIN | [4] Cardog market quote, same model year, 4 live listings, as of 28 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year | [5] Live public dealer listings on Cardog, as of 28 Oct 2026 |
| [3] NHTSA recall records (United States), listed for the model year | |

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

