

Register entry, as of 26 October 2026

Listed for sale

Record ID 9e81d168b15d

2012 Buick Regal Base

2.4 L, 4 cylinders · Sedan · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

2G4 **GN5EK** **2** **C** **9** **111582**

WMI 1-3

Buick · GENERAL MOTORS...

DESCRIPTOR 4-8

Regal · 2.4 L

CHECK 9

Verified

YEAR 10

2012

PLANT 11

Oshawa #1

SERIAL 12-17

Build sequence

§1 IDENTITY [1]

Model year	2012	Engine	2.4 L, 4 cylinders
Make	Buick	Fuel	Gasoline
Model	Regal	Drive	Not in the decode
Trim	Base	Maker	GENERAL MOTORS LLC
Body	Sedan	Plant	Oshawa #1, Ontario, Canada

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/buick/regal/2012

7 recalls listed by Transport Canada for this model year

Suspension

2026089 26 Feb 2026

Issue: On certain vehicles, the protective coating on the rear suspension toe links may chip away. If this happens, the metal can rust and the toe links could break. A broken toe link can affect vehicle stability and could cause a loss of control. Note: This recall is an expansion of Transport Canada recalls 2020-615, 2021-510 and 2021-785. This recall only affects vehicles that were originally sold or ever registered in areas of heavy road salt usage (Manitoba, Ontario, Quebec, New Brunswick, Nova Scotia, Prince Edward Island, and Newfoundland & Labrador). Safety Risk: A loss of vehicle stability could cause a loss of control and increase the risk of a crash. Corrective Actions: General Motors will notify owners by mail and advise you to take your vehicle to a dealership to replace the rear suspension toe links and adjuster fasteners.

Suspension

2021785 22 Dec 2021

Issue: On certain vehicles, the protective coating on the rear suspension toe links may chip away. If this happens, the metal can rust and the toe link could break. A broken toe link can affect vehicle stability and could cause a loss of directional control. Note: This recall is an expansion of Transport Canada recalls 2020-615 and 2021-510. This recall only affects vehicles that were originally sold or ever registered in areas of heavy road salt usage (Manitoba, Ontario, Quebec, New Brunswick, Nova Scotia, Prince Edward Island, and Newfoundland & Labrador). Safety Risk: A loss of vehicle stability could cause a loss of control and increase the risk of a crash. Corrective Actions: General Motors will notify owners by mail and instruct you to take your vehicle to a dealer to replace the rear suspension toe links and adjuster fasteners.



Suspension

2020615 10 Dec 2020

Issue: On certain vehicles, the protective coating on the rear suspension toe links may chip away. If this happens, the metal can rust and the toe link could break. A broken toe link can affect vehicle stability and could cause a loss of directional control. Note: This recall only affects vehicles that were originally sold or ever registered in areas of heavy road salt usage (Manitoba, Ontario, Quebec, New Brunswick, Nova Scotia, Prince Edward Island, and Newfoundland & Labrador). Safety Risk: A loss of vehicle stability could cause a loss of control and increase the risk of a crash. Corrective Actions: General Motors will notify owners by mail and instruct you to take your vehicle to a dealer to replace the rear suspension toe links and adjuster fasteners.

Seats and restraints

2014311 23 Jul 2014

On certain vehicles equipped with power height adjustable front seats, a bolt securing the adjuster mechanism may loosen and fall out. This would cause the seat to drop to the lowest vertical adjustment position, which could affect the driver's ability to safely operate vehicle controls as well as cause reduced driver visibility. These issues could increase the risk of a crash causing injury and/or damage to property. Correction: Dealers will replace the bolt.

Lights and instruments

2014310 23 Jul 2014

Certain vehicles may not comply with the requirements of Canada Motor Vehicle Safety Standard 108 - Lighting System and Retroreflective Devices. If one of the two front turn signal bulbs burn out in either front turn signal lamp, no indication would be provided to the driver, which is contrary to the requirements of the standard. Correction: Dealers will update vehicle software.

Electrical

2013149 6 May 2013

On certain vehicles equipped with eAssist, the Generator Control Module (GCM) may not function correctly. This could cause a gradual loss of battery charge, which would illuminate the malfunction indicator lamp. Eventually, the engine may stall. In conjunction with traffic and road conditions, and the driver's reactions, this could increase the risk of a crash. In addition, there may be a burning or melting odour, smoke and possibly a fire in the trunk. These issues could result in property damage and/or personal injury. Correction: Dealers will inspect and, if necessary, replace the Generator Control Module.


1 more on the model-year record, cardog.app/tools/recalls/buick/regal/2012

Listed for the model year, not checked against your VIN. Buick confirms which apply.
Check your VIN with Buick Canada or call a Buick dealer with your VIN.
www.buick.ca/en/ownercenter/recalls

United States: 7 NHTSA records for this model year, kept apart from the Canadian listing.^[3]

§3 VALUE [4]

This car asks \$5,995^[5], the median^[4].

	Lowest ask	\$5,995
	Middle half	\$5,995 – \$5,995
	Median ask	\$5,995
	This car	\$5,995

Same model year · 1 live listings · as of 26 Oct 2026

§4 EVENTS

2012 Model year 2012^[1]
Assembly plant Oshawa #1, Ontario, Canada



7 Mar 2012	Transport Canada recall 2012090 ^[2] Issued for the model year · Lights and instruments
6 May 2013	Transport Canada recall 2013149 ^[2] Issued for the model year · Electrical
23 Jul 2014	Transport Canada recall 2014311 ^[2] Issued for the model year · Seats and restraints
23 Jul 2014	Transport Canada recall 2014310 ^[2] Issued for the model year · Lights and instruments
10 Dec 2020	Transport Canada recall 2020615 ^[2] Issued for the model year · Suspension
22 Dec 2021	Transport Canada recall 2021785 ^[2] Issued for the model year · Suspension
26 Feb 2026	Transport Canada recall 2026089 ^[2] Issued for the model year · Suspension
25 Oct 2026	Listed for sale, Stoney Creek, ON ^[5] Xpress Auto Sales · asking \$5,995

§5 DOCUMENTS

Window sticker This VIN reads as model year 1982 or 2012, before our coverage for this manufacturer.

SOURCES

- | | |
|---|--|
| [1] Cardog identity register, decoded from the VIN | [4] Cardog market quote, same model year, 1 live listings, as of 26 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year | [5] Live public dealer listings on Cardog, as of 26 Oct 2026 |
| [3] NHTSA recall records (United States), listed for the model year | |

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

