

Register entry, as of 27 October 2026

Listed for sale

Record ID e8e61e7f29e0

# 2009 Volkswagen Routan SEL Premium

4.0 L, 6 cylinders · Minivan · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

**2V8 HW64X 3 9 R 564356**

WMI 1-3

Volkswagen · CHRYSLER G...

DESCRIPTOR 4-8

Routan · 4.0 L

CHECK 9

Verified

YEAR 10

2009

PLANT 11

Windsor

SERIAL 12-17

Build sequence

## §1 IDENTITY [1]

|            |             |        |                                                             |
|------------|-------------|--------|-------------------------------------------------------------|
| Model year | 2009        | Engine | 4.0 L, 6 cylinders                                          |
| Make       | Volkswagen  | Fuel   | Gasoline                                                    |
| Model      | Routan      | Drive  | Not in the decode                                           |
| Trim       | SEL Premium | Maker  | CHRYSLER GROUP LLC(USA),CHRYSLER CANADA, CHRYSLER DE MEXICO |
| Body       | Minivan     | Plant  | Windsor, Ontario, Canada                                    |

## §2 OBLIGATIONS [2]

[cardog.app/tools/recalls/volkswagen/routan/2009](https://cardog.app/tools/recalls/volkswagen/routan/2009)

## 5 recalls listed by Transport Canada for this model year

|                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                            |                    |
|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------|
| <b>Airbag</b>                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                              | 2016059 5 Feb 2016 |
| On certain vehicles, a defect in the Occupant Restraint Control (ORC) system could result in inadvertent airbag / seatbelt pretensioner deployment, or prevent airbags / seatbelt pretensioners from deploying when warranted. Unintended airbag / seatbelt pretensioner deployment, in a non-warranted (non-impact) situation, could startle the driver, and could result in a vehicle crash causing injury and/or property damage. Furthermore, failure of the airbags / seatbelt pretensioners to deploy in a crash when warranted could increase the risk of injury to vehicle occupants. Correction: Dealers will replace the Occupant Restraint Control (ORC) module.                                                                                                                                                                                                                |                    |
| <b>Electrical</b>                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                          | 2014266 2 Jul 2014 |
| On certain vehicles, the Wireless Ignition Node (a.k.a ignition switch) may allow the ignition key to inadvertently move from the ON position to the accessory (ACC) position while driving, causing the engine to shut off. This would result in a loss of motive power, power steering and power brakes, and would disable the airbags as well as other supplemental restraint systems (SRS). Increased steering and braking effort and a loss of motive power could increase the risk of a crash causing injury and/or damage to property. Loss of airbag / SRS function in a crash that warrants airbag deployment and/or other supplemental restraint system function could increase the risk of injury to vehicle occupants. Correction: Dealers will inspect the WIN module and install a secondary detent system if required. Note: This recall is an expansion of recall 2011095. |                    |
| <b>Structure</b>                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                           | 2014031 3 Feb 2014 |
| On certain vehicles modified for wheelchair accessibility by the Liberty Motor Company Inc., the rear axle may fracture due to a combination of corrosion damage and operation on rough roads. If the rear axle fractures, vehicle handling may be adversely affected, creating the risk of a crash and increasing the risk of injury and/or property damage. Correction: Freedom Motors assigned service shops will inspect axles and reinforce or replace as necessary.                                                                                                                                                                                                                                                                                                                                                                                                                  |                    |



## Other

2010191 8 Jun 2010

On certain vehicles equipped with power sliding doors, the sliding door wiring harness may have been routed improperly and chafe on the lower sliding door hinge bracket. This could result in a fire within the sliding door assembly, which could lead to property damage or personal injury. Correction: Dealers will inspect the sliding door wire track harness and power drive unit wiring harness assemblies for damage. The harnesses will be repaired or replaced as necessary, and rerouted under the sliding door weatherstrip.

## Other

2009208 10 Jul 2009

The owner's manual for certain vehicles was printed without the CMVSS 208 required information explaining that no objects should be placed over or near the airbag on the instrument panel, because any such objects could cause harm if the vehicle is involved in a crash severe enough to cause the airbag to inflate. Correction: Owners will be provided with an owner's manual insert containing the required airbag information.

Listed for the model year, not checked against your VIN. Volkswagen confirms which apply.


Check your VIN with Volkswagen Canada or call a Volkswagen dealer with your VIN.

[www.vw.ca/en/owners-and-drivers/recalls.html](http://www.vw.ca/en/owners-and-drivers/recalls.html)

United States: 6 NHTSA records for this model year, kept apart from the Canadian listing.<sup>[3]</sup>

## §3 VALUE [4]

This car asks \$2,495<sup>[5]</sup>, the median<sup>[4]</sup>.



|             |                   |
|-------------|-------------------|
| Lowest ask  | \$2,495           |
| Middle half | \$2,495 – \$2,495 |
| Median ask  | \$2,495           |
| This car    | \$2,495           |

Same model year · 1 live listings · as of 27 Oct 2026

## §4 EVENTS

|             |                                                                                          |
|-------------|------------------------------------------------------------------------------------------|
| 2009        | Model year 2009 <sup>[1]</sup><br>Assembly plant Windsor, Ontario, Canada                |
| 10 Jul 2009 | Transport Canada recall 2009208 <sup>[2]</sup><br>Issued for the model year · Other      |
| 8 Jun 2010  | Transport Canada recall 2010191 <sup>[2]</sup><br>Issued for the model year · Other      |
| 3 Feb 2014  | Transport Canada recall 2014031 <sup>[2]</sup><br>Issued for the model year · Structure  |
| 2 Jul 2014  | Transport Canada recall 2014266 <sup>[2]</sup><br>Issued for the model year · Electrical |
| 5 Feb 2016  | Transport Canada recall 2016059 <sup>[2]</sup><br>Issued for the model year · Airbag     |
| 25 Oct 2026 | Listed for sale, London, ON <sup>[5]</sup><br>Tiger Auto Sales Ltd. · asking \$2,495     |



27 Oct 2026      Listing last updated<sup>[5]</sup>  
asking \$2,495

## §5 DOCUMENTS

Window sticker      We do not collect window stickers for this manufacturer.

## SOURCES

- |                                                                     |                                                                              |
|---------------------------------------------------------------------|------------------------------------------------------------------------------|
| [1] Cardog identity register, decoded from the VIN                  | [4] Cardog market quote, same model year, 1 live listings, as of 27 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year     |                                                                              |
| [3] NHTSA recall records (United States), listed for the model year | [5] Live public dealer listings on Cardog, as of 27 Oct 2026                 |

## STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

