

# 2026 Ford Bronco Sport Badlands

2.0 L, 4 cylinders · 4WD · Sport Utility Vehicle · Gasoline

## VEHICLE IDENTIFICATION NUMBER [1]

**3FM CR9DA 8 T R E51767**

WMI 1-3

Ford Motor Company, Mexi...

DESCRIPTOR 4-8

Bronco Sport · 2.0 L

CHECK 9

Verified

YEAR 10

2026

PLANT 11

Hermosillo

SERIAL 12-17

Build sequence

## §1 IDENTITY [1]

|            |                       |        |                            |
|------------|-----------------------|--------|----------------------------|
| Model year | 2026                  | Engine | 2.0 L, 4 cylinders         |
| Make       | Ford                  | Fuel   | Gasoline                   |
| Model      | Bronco Sport          | Drive  | 4WD                        |
| Trim       | Badlands              | Maker  | FORD MOTOR COMPANY, MEXICO |
| Body       | Sport Utility Vehicle | Plant  | Hermosillo, Sonora, Mexico |

## §2 OBLIGATIONS [2]

[cardog.app/tools/recalls/ford/bronco-sport/2026](https://cardog.app/tools/recalls/ford/bronco-sport/2026)

## 5 recalls listed by Transport Canada for this model year

|                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                      |         |             |
|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------|-------------|
| Engine                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                               | 2026411 | 26 Aug 2026 |
| Issue: On certain vehicles, the engine pistons may not have been manufactured properly. As a result, the pistons may crack and cause the engine to fail. If this happens, there could be a sudden loss of power to the wheels. Note: This recall only affects certain vehicles equipped with a 1.5 L or 2.3 L engine. Safety Risk: A sudden loss of engine power could increase the risk of a crash. Corrective Actions: Ford will notify owners by mail and advise you to take your vehicle to a dealership to inspect and, if necessary, replace the engine.                                                                                                                                                                                                       |         |             |
| Suspension                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                           | 2026259 | 27 May 2026 |
| Issue: On certain vehicles, the front lower ball joint(s) may not have been installed correctly on the steering knuckle(s). As a result, the front lower ball joint(s) could separate and cause a loss of steering control. Safety Risk: A loss of steering control could create a risk of a crash. Corrective Actions: To reduce the safety risk Ford advises you not to drive your vehicle until the recall repairs are completed. Ford will notify owners by mail and advise you to contact a dealer to arrange for an inspection. The dealer will repair the front steering knuckle(s), as necessary.                                                                                                                                                            |         |             |
| Seats and restraints                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                 | 2026162 | 1 Apr 2026  |
| Issue: On certain vehicles, the front passenger seat occupant classification system (OCS) may not work properly. As a result, the airbag system may turn off the passenger-front airbag even when a passenger is seated. Note: This problem would cause the supplemental restraint system (SRS) malfunction indicator to display on the instrument panel, a warning to display in the driver information center and the airbag indicator light to display "Passenger Airbag OFF". Safety Risk: An airbag system that doesn't work properly could increase the risk of injury in a crash. Corrective Actions: Ford will notify owners by mail and advise you to take your vehicle to a dealership to replace the front passenger seat occupant classification sensor. |         |             |



## Visual system

2025627 14 Nov 2025

Issue: On certain vehicles, a software problem could cause the instrument panel cluster not to display when the vehicle is started. As a result, you may not be able to see certain information about the vehicle, including the speedometer, fuel gauge, warning lights and malfunction tell-tales. Safety Risk: Warnings, tell-tales and gauges that don't display could increase the risk of a crash. Corrective Actions: Ford will notify owners by mail and advise you to take your vehicle to a dealership to update the instrument panel cluster module software.

## Engine

2025281 23 May 2025

Issue: On certain vehicles, the engine block heater could overheat when the block heater is plugged in. Note: This recall only affects certain vehicles equipped with a 1.5 L or 2.0 L engine and a factory-installed block heater. Safety Risk: An engine block heater and/or wiring that overheats or melts could create the risk of a fire. Corrective Actions: To reduce the safety risk, Ford advises you not to plug in the engine block heater until the recall repairs have been completed. Ford will notify owners by mail. You can choose to have the dealer remove the block heater, or once the final repair is available, Ford will send you another notice to advise you to take your vehicle to a dealership to replace the block heater element. The dealer will also inspect and, if necessary, replace the block heater electrical cord.

Listed for the model year, not checked against your VIN. Ford confirms which apply.

Check your VIN with Ford Canada or call a Ford dealer with your VIN.

[www.ford.ca/support/recalls/](http://www.ford.ca/support/recalls/)

United States: 6 NHTSA records for this model year, kept apart from the Canadian listing.<sup>[3]</sup>

## §3 VALUE [4]

This car asks \$54,579<sup>[5]</sup>, \$794 over the median of \$53,785<sup>[4]</sup>.



|             |                     |
|-------------|---------------------|
| Lowest ask  | \$41,324            |
| Middle half | \$50,980 – \$55,485 |
| Median ask  | \$53,785            |
| This car    | \$54,579            |

Same configuration · 413 live listings · as of 29 Oct 2026

## OTHER 2026 FORD BRONCO SPORT LISTINGS [5]

|                             |          |
|-----------------------------|----------|
| Cowansville, QC · 25 km     | \$55,964 |
| Cowansville, QC · 25 km     | \$55,879 |
| Winnipeg, MB · 30 km        | \$49,723 |
| Saint-Hyacinthe, QC · 10 km | \$47,045 |
| Saint-Hyacinthe, QC · 10 km | \$46,120 |
| Saint-Hyacinthe, QC · 10 km | \$43,065 |

## §4 EVENTS

2026

Model year 2026<sup>[1]</sup>

Assembly plant Hermosillo, Sonora, Mexico

23 May 2025

Transport Canada recall 2025281<sup>[2]</sup>

Issued for the model year · Engine

14 Nov 2025

Transport Canada recall 2025627<sup>[2]</sup>

Issued for the model year · Visual system



|             |                                                                                                    |
|-------------|----------------------------------------------------------------------------------------------------|
| 1 Apr 2026  | Transport Canada recall 2026162 <sup>[2]</sup><br>Issued for the model year · Seats and restraints |
| 27 May 2026 | Transport Canada recall 2026259 <sup>[2]</sup><br>Issued for the model year · Suspension           |
| 26 Aug 2026 | Transport Canada recall 2026411 <sup>[2]</sup><br>Issued for the model year · Engine               |
| 25 Oct 2026 | Listed for sale, Hagersville, ON <sup>[5]</sup><br>Heaslip Ford · asking \$54,579                  |
| 29 Oct 2026 | Listing last updated <sup>[5]</sup><br>asking \$54,579                                             |

## §5 DOCUMENTS

Window sticker      We have not collected this label yet.

## SOURCES

- |                                                                     |                                                                                   |
|---------------------------------------------------------------------|-----------------------------------------------------------------------------------|
| [1] Cardog identity register, decoded from the VIN                  | [4] Cardog market quote, same configuration, 413 live listings, as of 29 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year     | [5] Live public dealer listings on Cardog, as of 29 Oct 2026                      |
| [3] NHTSA recall records (United States), listed for the model year |                                                                                   |

## STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

