

Register entry, as of 28 October 2026

Listed for sale

Record ID fb4e9a72fd0c

# 2022 Nissan Sentra SV

2.0 L, 4 cylinders · 4x2 · Sedan · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

**3N1 AB8CV 5 N Y 208802**

WMI 1-3

Nissan Mexicana, S.A. De C...

DESCRIPTOR 4-8

Sentra · 2.0 L

CHECK 9

Verified

YEAR 10

2022

PLANT 11

Aguascalientes

SERIAL 12-17

Build sequence

## §1 IDENTITY [1]

|            |        |        |                                        |
|------------|--------|--------|----------------------------------------|
| Model year | 2022   | Engine | 2.0 L, 4 cylinders                     |
| Make       | Nissan | Fuel   | Gasoline                               |
| Model      | Sentra | Drive  | 4x2                                    |
| Trim       | SV     | Maker  | NISSAN MEXICANA, S.A. DE C.V.          |
| Body       | Sedan  | Plant  | Aguascalientes, Aguascalientes, Mexico |

## §2 OBLIGATIONS [2]

[cardog.app/tools/recalls/nissan/sentra/2022](https://cardog.app/tools/recalls/nissan/sentra/2022)

## 2 recalls listed by Transport Canada for this model year

### Steering 2023462 16 Aug 2023

Issue: On certain vehicles, the left and/or right tie rod(s) may not be strong enough. Under certain conditions (like hitting a curb or a large pothole), the tie rod(s) could bend and/or break and cause a partial loss of steering control. Safety Risk: A loss of steering control could create the risk of a crash. Corrective Actions: Nissan will notify owners by mail. Due to a parts supply issue, Nissan will advise you to take your vehicle to the dealership only if you experience a vibration in the steering wheel or if the steering wheel is off-center. When enough parts are available, Nissan will re-notify owners and instruct you to take your vehicle to a dealership to replace the left and right tie rods.

### Structure 2023344 13 Jun 2023

Issue: On a small number of vehicles, the cowl area below the windshield may not be sealed correctly. As a result, water could leak onto the driver's side floor and damage the main body harness. If this happens, the wiring could short circuit and overheat, and various electrical systems may not work properly. Safety Risk: A short circuit can create the risk of a fire. Electrical systems that don't work properly could increase the risk of injury and/or a crash. Corrective Actions: Nissan will notify owners by mail and advise you to take your vehicle to a dealership to reseal the windshield in the driver side cowl area. The dealer will also inspect the main body wiring harness connector for signs of moisture or corrosion, and replace the main body harness and engine room wiring harness as necessary.

Listed for the model year, not checked against your VIN. Nissan confirms which apply.

Check your VIN with Nissan Canada or call a Nissan dealer with your VIN.

[www.nissan.ca/service/vin-recall.html](https://www.nissan.ca/service/vin-recall.html)

United States: 2 NHTSA records for this model year, kept apart from the Canadian listing.<sup>[3]</sup>



## §3 VALUE [4]

This car asks \$18,996<sup>[5]</sup>, \$46 over the median of \$18,950<sup>[4]</sup>.



|             |                     |
|-------------|---------------------|
| Lowest ask  | \$13,988            |
| Middle half | \$17,346 – \$19,991 |
| Median ask  | \$18,950            |
| This car    | \$18,996            |

Same configuration · 32 live listings · as of 28 Oct 2026

## OTHER 2022 NISSAN SENTRA LISTINGS [5]

|                              |          |
|------------------------------|----------|
| Burlington, ON · 71,086 km   | \$17,998 |
| Joliette, QC · 102,924 km    | \$15,474 |
| Lindsay, ON · 90,566 km      | \$17,988 |
| La Malbaie, QC · 94,850 km   | \$17,799 |
| Mirabel, QC · 57,865 km      | \$15,992 |
| Smiths Falls, ON · 58,780 km | \$19,998 |

## §4 EVENTS

|             |                                                                                         |
|-------------|-----------------------------------------------------------------------------------------|
| 2022        | Model year 2022 <sup>[1]</sup><br>Assembly plant Aguascalientes, Aguascalientes, Mexico |
| 13 Jun 2023 | Transport Canada recall 2023344 <sup>[2]</sup><br>Issued for the model year · Structure |
| 16 Aug 2023 | Transport Canada recall 2023462 <sup>[2]</sup><br>Issued for the model year · Steering  |
| 22 Sep 2026 | Listed for sale, Brossard, QC <sup>[5]</sup><br>Park Avenue Honda · asking \$18,996     |
| 27 Oct 2026 | Listing last updated <sup>[5]</sup><br>asking \$18,996                                  |

## §5 DOCUMENTS

Window sticker      We have not collected this label yet.

## SOURCES

|                                                                     |                                                                                  |
|---------------------------------------------------------------------|----------------------------------------------------------------------------------|
| [1] Cardog identity register, decoded from the VIN                  | [4] Cardog market quote, same configuration, 32 live listings, as of 28 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year     | [5] Live public dealer listings on Cardog, as of 28 Oct 2026                     |
| [3] NHTSA recall records (United States), listed for the model year |                                                                                  |



---

**STATEMENT OF SCOPE**

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

