

Register entry, as of 28 October 2026

Listed for sale

Record ID 3a82c6f8b7e5

2011 Toyota Tacoma

4.0 L, 6 cylinders · Pickup · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

3TM MU4FN 7 B M 036137

WMI 1-3

Toyota Motor Mfg de Baja...

DESCRIPTOR 4-8

Tacoma · 4.0 L

CHECK 9

Verified

YEAR 10

2011

PLANT 11

Baja California

SERIAL 12-17

Build sequence

§1 IDENTITY [1]

Model year	2011	Engine	4.0 L, 6 cylinders
Make	Toyota	Fuel	Gasoline
Model	Tacoma	Drive	Not in the decode
Trim	Not in the decode	Maker	Toyota Motor Mfg de Baja California S de RL de CV
Body	Pickup	Plant	Baja California, Mexico

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/toyota/tacoma/2011

6 recalls listed by Transport Canada for this model year

Electrical

2021723 24 Nov 2021

Issue: This recall is for certain block heater kits installed on certain vehicles or sold as accessories at Toyota or Lexus dealerships. On certain vehicles, the engine block heater cable may not have enough heat protection and could be damaged by high temperatures. If this happens, the cable could short circuit while plugged in, and cause the wiring to overheat or melt. Note: This recall only affects the following block heater/cord part numbers: C014003034 PK5A408J09 PU14000904 C014003151 PK5A408J13 PU14000905 C014000885 PK5A489J11 PU14000907 C014000888 PK5A489J22 PU14000909 C014000907 PK5A410H00 PU14000911 C014100904 PU14000900 PU14000913 C014100907 PU14000901 PU14003571 C014100911 PU14000902 PK5A489J14 PK5A408J05 PU14000903 Safety Risk: Engine block heater wiring that overheats or melts could create the risk of a fire. Corrective Actions: Toyota recommends that you should stop using the engine block heater immediately. Toyota will notify owners by mail and instruct you to take your vehicle to a dealer to disable the engine block heater. For some vehicles, the corrective actions for this recall are under development. For others, a new engine block heater cannot be installed, and the owner will receive a refund of the purchase price of the engine block heater.

Suspension

2014420 29 Sep 2014

On certain vehicles, the leaf springs in the rear suspension could fracture due to stress and corrosion. If this were to occur, the broken leaf could move out of position and contact surrounding components, including the fuel tank. If the broken leaf were to contact the fuel tank repeatedly, it could puncture the fuel tank. This could result in a fuel leak which, in the presence of an ignition source, could result in a fire causing injury and/or property damage. Correction: Dealers will replace the rear leaf spring assemblies with improved ones.



Airbag

2014124 9 Apr 2014

On certain vehicles, electrical circuitry in the steering wheel assembly may become damaged. As a result, the driver's airbag may not function as intended, causing the instrument panel airbag warning lamp to illuminate. Failure of the driver's airbag to deploy during a crash (where deployment is warranted) could increase the risk of injury to the seat occupant. Correction: Dealers will replace the spiral cable assembly.

Accessories

2013353 10 Oct 2013

On certain vehicles equipped with an optional tonneau cover where the front-most panel can be opened with the vehicle ignition key, the lock cylinder could bind. If the lock cylinder were to bind in the open position, the panel may not remain closed and the tonneau cover assembly could separate from the vehicle while it is being driven. This could potentially result in property damage and pose a hazard to other road users. Correction: Dealers will affect repairs when service parts become available. In the interim, the panel release mechanism will be disabled or the tonneau cover removed, at the owner's choice.

Seats and restraints

2013273 7 Aug 2013

On vehicles with the Access Cab body configuration, fasteners within the driver and passenger front seat belt assemblies could loosen if the access doors are repeatedly and forcefully closed over an extended period of time. Should the fasteners loosen completely, the seat belt may not properly restrain the occupant, which could increase the risk of injury in a crash or sudden stop. Correction: Dealers will replace the fasteners or the seat belt assemblies as necessary.

Label

2011104 4 Mar 2011

Certain vehicles fail to conform to Canada Motor Vehicle Safety Standard 110 - Tire Selection and Rims. These vehicles may have been equipped with accessory alloy wheels and tires prior to delivery to the customer. The specifications and recommended tire inflation pressures for the original equipment wheel and tire sizes, and the accessory wheel and tire size, are different. A replacement tire loading placard may not have been provided when the accessory wheels and tires were installed. Correction: Dealers will install a replacement tire loading placard.

Listed for the model year, not checked against your VIN. Toyota confirms which apply.


Check your VIN with Toyota Canada or call a Toyota dealer with your VIN.

www.toyota.ca/en/owners/recalls/

United States: 9 NHTSA records for this model year, kept apart from the Canadian listing.^[3]

§3 VALUE ^[4]

This car asks \$24,995^[5], \$7,496 over the median of \$17,499^[4].



Lowest ask \$9,999

Middle half \$15,495 – \$21,242

Median ask \$17,499

This car \$24,995

Same model year · 7 live listings · as of 28 Oct 2026

OTHER 2011 TOYOTA TACOMA LISTINGS ^[5]

Quebec, QC · 219,000 km	\$13,995
Komoka, ON · 264,451 km	\$16,995
Toronto, ON · 196,296 km	\$17,988
Scarborough, ON · 351,000 km	\$9,999
Ottawa, ON · 150,442 km	\$24,497



§4 EVENTS

2011	Model year 2011 ^[1] Assembly plant Baja California, Mexico
4 Mar 2011	Transport Canada recall 2011104 ^[2] Issued for the model year · Label
7 Aug 2013	Transport Canada recall 2013273 ^[2] Issued for the model year · Seats and restraints
10 Oct 2013	Transport Canada recall 2013353 ^[2] Issued for the model year · Accessories
9 Apr 2014	Transport Canada recall 2014124 ^[2] Issued for the model year · Airbag
29 Sep 2014	Transport Canada recall 2014420 ^[2] Issued for the model year · Suspension
24 Nov 2021	Transport Canada recall 2021723 ^[2] Issued for the model year · Electrical
1 Aug 2026	Listed for sale, Thetford Mines, QC ^[5] Du Beau Toyota · asking \$24,995
28 Oct 2026	Listing last updated ^[5] asking \$24,995

§5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.

SOURCES

- | | |
|---|--|
| [1] Cardog identity register, decoded from the VIN | [4] Cardog market quote, same model year, 7 live listings, as of 28 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year | [5] Live public dealer listings on Cardog, as of 28 Oct 2026 |
| [3] NHTSA recall records (United States), listed for the model year | |

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

