

Register entry, as of 29 October 2026

Listed for sale

Record ID 98df340e052d

2015 Volkswagen Golf

1.8 L, 4 cylinders · Hatchback · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

3VW 117AU 5 F M 003376

WMI 1-3

Volkswagen De Mexico Sa...

DESCRIPTOR 4-8

Golf · 1.8 L

CHECK 9

Verified

YEAR 10

2015

PLANT 11

Puebla

SERIAL 12-17

Build sequence

§1 IDENTITY [1]

Model year	2015	Engine	1.8 L, 4 cylinders
Make	Volkswagen	Fuel	Gasoline
Model	Golf	Drive	Not in the decode
Trim	Not in the decode	Maker	VOLKSWAGEN DE MEXICO SA DE CV
Body	Hatchback	Plant	Puebla, Mexico

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/volkswagen/golf/2015

13 recalls listed by Transport Canada for this model year

Fuel system	2024095 14 Feb 2024
Issue: On certain vehicles, a seal for the suction jet pump inside the fuel tank could fail. As a result, fuel may flow directly into the evaporative emission control system (EVAP). If this happens, fuel could leak from the charcoal canister. Note: This problem could cause a fuel odor, the fuel nozzle to stop early and/or fuel to spill when refueling. Safety Risk: A fuel leak can create the risk of a fire. Corrective Actions: The company will notify owners by mail and advise you to take your vehicle to a dealership to replace the suction jet pump.	
Fabrics	2021326 26 May 2021
Issue: On certain models, the chrome layer could peel off of the trim located around the gear shift cover. If this happens, sharp edges can be created. Safety Risk: Exposed sharp edges can create the risk of a cut. Corrective Actions: Volkswagen will contact owners by mail and instruct you to take your vehicle to a dealer to replace the gear shift cover trim frame.	
Label	2020353 4 Aug 2020
Issue: On certain vehicles, the warning label for the engine block heater cable is written in English only. As a result, a French user may not receive important safety information about how to use the engine block heater. A label that is not provided in both official languages could create confusion. Safety Risk: User confusion could increase the risk of injury when trying to use the block heater. Corrective Actions: The company will mail each owner a new label for the block heater cable. If you would like help installing the label, you can contact a dealer for assistance.	



Powertrain

2019423 22 Aug 2019

Issue: On certain vehicles, a build-up of silicate on the shift lever switch could cause the transmission to detect that it is in the Park position when it isn't. This could allow the ignition key to be removed when the transmission is not in the Park position. If the parking brake is not applied, this could allow the car to roll away. Safety Risk: If the transmission position is not displayed correctly, a user may not know that the vehicle is not in the PARK position. If the parking brake is not applied, this could create a risk of a vehicle roll-away and increase the risk of a crash. Corrective Actions: The company will notify owners by mail. Owners will be instructed to take their vehicle to a dealer to have a new shift lever micro switch and control unit installed.

Suspension

2019116 6 Mar 2019

Issue: On certain vehicles, the rear suspension coil springs may not have been properly manufactured and could break over time. This could cause damage to a rear tire, resulting in rapid air loss and/or tire failure. Safety Risk: A rear tire failure could affect vehicle control. Additionally, a broken coil spring could also create a road hazard for other motorists. Both of these conditions may increase the risk of a crash. Corrective Actions: The company will notify owners by mail. Owners will be instructed to take their vehicle to a dealer to have both of the rear axle coil springs replaced. If a broken coil spring is found, the rear tires should be inspected for damage and replaced as required.

Powertrain

2018371 11 Jul 2018

On certain vehicles, the park position switch may malfunction due to a problem with the electrical contacts. This could allow for removal of the ignition key without the shift lever being in the Park (P) position. If the parking brake is not applied, this could result in unintended vehicle movement, which could increase the risk of crash causing injury and/or damage to property. Correction: Dealers will install an additional park position switch and circuit board.

7 more on the model-year record, cardog.app/tools/recalls/volkswagen/golf/2015

Listed for the model year, not checked against your VIN. Volkswagen confirms which apply.
Check your VIN with Volkswagen Canada or call a Volkswagen dealer with your VIN.
www.vw.ca/en/owners-and-drivers/recalls.html

United States: 12 NHTSA records for this model year, kept apart from the Canadian listing.^[3]

§3 VALUE ^[4]

This car asks \$12,499^[5], \$2,049 over the median of \$10,450^[4].



Lowest ask	\$4,995
Middle half	\$8,495 – \$11,999
Median ask	\$10,450
This car	\$12,499

Same model year · 25 live listings · as of 29 Oct 2026

OTHER 2015 VOLKSWAGEN GOLF LISTINGS ^[5]

Notre-Dame-Des-Prairies, QC · 182,951 km	\$6,990
Gatineau, QC · 107,679 km	\$11,495
Nanaimo, BC · 117,715 km	\$19,577
Sorel-Tracy, QC · 162,290 km	\$4,995
Chilliwack, BC · 149,723 km	\$10,990
Laval, QC · 178,000 km	\$8,999



§4 EVENTS

2015	Model year 2015 ^[1] Assembly plant Puebla, Mexico
9 Jul 2014	Transport Canada recall 2014288 ^[2] Issued for the model year · Suspension
16 Jul 2014	Transport Canada recall 2014295 ^[2] Issued for the model year · Powertrain
17 Dec 2014	Transport Canada recall 2014575 ^[2] Issued for the model year · Fuel system
16 Apr 2015	Transport Canada recall 2015161 ^[2] Issued for the model year · Fuel system
5 Oct 2015	Transport Canada recall 2015445 ^[2] Issued for the model year · Airbag
23 Oct 2015	Transport Canada recall 2015504 ^[2] Issued for the model year · Engine
2 Sep 2016	Transport Canada recall 2016430 ^[2] Issued for the model year · Fuel system
11 Jul 2018	Transport Canada recall 2018371 ^[2] Issued for the model year · Powertrain
6 Mar 2019	Transport Canada recall 2019116 ^[2] Issued for the model year · Suspension
22 Aug 2019	Transport Canada recall 2019423 ^[2] Issued for the model year · Powertrain
4 Aug 2020	Transport Canada recall 2020353 ^[2] Issued for the model year · Label
26 May 2021	Transport Canada recall 2021326 ^[2] Issued for the model year · Fabrics
14 Feb 2024	Transport Canada recall 2024095 ^[2] Issued for the model year · Fuel system
25 Sep 2026	Listed for sale, Saint-Bruno-de-Montarville, QC ^[5] St-Bruno Volkswagen · asking \$12,499
29 Oct 2026	Listing last updated ^[5] asking \$12,499

§5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.



SOURCES

- | | |
|---|---|
| [1] Cardog identity register, decoded from the VIN | [4] Cardog market quote, same model year, 25 live listings, as of 29 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year | |
| [3] NHTSA recall records (United States), listed for the model year | [5] Live public dealer listings on Cardog, as of 29 Oct 2026 |

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

