

Register entry, as of 28 October 2026

Listed for sale

Record ID 1060dfe1019e

2016 Volkswagen Beetle 1.8T S, SE, SEL, Denim TDI SE, SEL

1.8 L, 4 cylinders · Convertible · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

3VW

WMI 1-3

Volkswagen De Mexico Sa...

507AT

DESCRIPTOR 4-8

Beetle · 1.8 L

3

CHECK 9

Verified

G

YEAR 10

2016

M

PLANT 11

Puebla

807382

SERIAL 12-17

Build sequence

§1 IDENTITY [1]

Model year	2016	Engine	1.8 L, 4 cylinders
Make	Volkswagen	Fuel	Gasoline
Model	Beetle	Drive	Not in the decode
Trim	1.8T S, SE, SEL, Denim TDI SE, SEL	Maker	VOLKSWAGEN DE MEXICO SA DE CV
Body	Convertible	Plant	Puebla, Mexico

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/volkswagen/beetle/2016

4 recalls listed by Transport Canada for this model year

Seats and restraints

2022735 14 Dec 2022

Issue: On certain vehicles, long-term exposure to high absolute humidity and temperature, combined with high temperature cycling, may eventually degrade the propellant contained in the driver-front airbag. This could cause the airbag to deploy with more force than normal. If the airbag inflator ruptures, fragments could be propelled toward vehicle occupants or cause damage to the airbag assembly, preventing its proper function. Safety Risk: If the vehicle is involved in a crash requiring an airbag deployment, the airbag inflator could rupture and create a risk of injury. Corrective Action: Owners will be notified by mail and instructed to take their vehicle to a dealer to replace the driver-front airbag. Note: The Canadian climate results in the propellant degrading slowly. This recall is being conducted as a precaution to address future risk. It is expected that all airbag inflators will be replaced before their function would be affected.

Powertrain

2019423 22 Aug 2019

Issue: On certain vehicles, a build-up of silicate on the shift lever switch could cause the transmission to detect that it is in the Park position when it isn't. This could allow the ignition key to be removed when the transmission is not in the Park position. If the parking brake is not applied, this could allow the car to roll away. Safety Risk: If the transmission position is not displayed correctly, a user may not know that the vehicle is not in the PARK position. If the parking brake is not applied, this could create a risk of a vehicle roll-away and increase the risk of a crash. Corrective Actions: The company will notify owners by mail. Owners will be instructed to take their vehicle to a dealer to have a new shift lever micro switch and control unit installed.



Fuel system

2016275 2 Jun 2016

On a certain vehicles, the fuel rail may detach from the cylinder head, allowing fuel to leak into the engine compartment during engine operation. Leaking fuel, in the presence of an ignition source, could lead to a fire causing injury and/or damage to property. Correction: Dealers will replace the cylinder head with a new part.

Engine

2015504 23 Oct 2015

On certain vehicles, the camshaft lobe which actuates the vacuum pump may fail, causing the pump to fail to deliver further vacuum supply to the brake booster, potentially increasing stopping distances. This would also result in a reduction in available engine power. These issues could increase the risk of a crash causing injury and/or damage to property. Note: This issue would result in the Engine Malfunction Indicator Light (MIL) illuminating. Correction: Dealers will update the engine control module (ECM) software.

Listed for the model year, not checked against your VIN. Volkswagen confirms which apply.

Check your VIN with Volkswagen Canada or call a Volkswagen dealer with your VIN.

www.vw.ca/en/owners-and-drivers/recalls.html

United States: 4 NHTSA records for this model year, kept apart from the Canadian listing.^[3]

§3 VALUE [4]

This car asks \$14,999^[5], \$4,361 over the median of \$10,638^[4].



Lowest ask	\$8,500
Middle half	\$8,708 – \$13,622
Median ask	\$10,638
This car	\$14,999

Same model year · 4 live listings · as of 28 Oct 2026

OTHER 2016 VOLKSWAGEN BEETLE LISTINGS [5]

Drummondville, QC · 161,963 km \$8,500

§4 EVENTS

2016	Model year 2016 ^[1] Assembly plant Puebla, Mexico
23 Oct 2015	Transport Canada recall 2015504 ^[2] Issued for the model year · Engine
2 Jun 2016	Transport Canada recall 2016275 ^[2] Issued for the model year · Fuel system
22 Aug 2019	Transport Canada recall 2019423 ^[2] Issued for the model year · Powertrain
14 Dec 2022	Transport Canada recall 2022735 ^[2] Issued for the model year · Seats and restraints
26 Oct 2026	Listed for sale, Montréal, QC ^[5] autoplex26.com · asking \$14,999



27 Oct 2026 Listing last updated^[5]
asking \$14,999

§5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.

SOURCES

- | | |
|---|--|
| [1] Cardog identity register, decoded from the VIN | [4] Cardog market quote, same model year, 4 live listings, as of 28 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year | |
| [3] NHTSA recall records (United States), listed for the model year | [5] Live public dealer listings on Cardog, as of 28 Oct 2026 |

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

