

Register entry, as of 28 October 2026

Listed for sale

Record ID d3d2ab86db0d

2013 Volkswagen Beetle

2.5 L, 5 cylinders · Convertible · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

3VW

WMI 1-3

Volkswagen De Mexico Sa...

5X7AT

DESCRIPTOR 4-8

Beetle · 2.5 L

3

CHECK 9

Verified

D

YEAR 10

2013

M

PLANT 11

Puebla

808118

SERIAL 12-17

Build sequence

§1 IDENTITY [1]

Model year	2013	Engine	2.5 L, 5 cylinders
Make	Volkswagen	Fuel	Gasoline
Model	Beetle	Drive	Not in the decode
Trim	Not in the decode	Maker	VOLKSWAGEN DE MEXICO SA DE CV
Body	Convertible	Plant	Puebla, Mexico

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/volkswagen/beetle/2013

7 recalls listed by Transport Canada for this model year

Heater and defroster

2024648 30 Oct 2024

Issue: Volkswagen Group Canada is conducting a parts recovery campaign targeting 2012-2016 Volkswagen vehicles equipped with a TDI (diesel) engine built between May 25, 2011 and June 1, 2016. The auxiliary heater elements are being recovered to aid in Volkswagen's analysis in support of Transport Canada defect investigation file no. 3280-15-10. Note: This action is not being conducted under the requirements of the Motor Vehicle Safety Act. For the 2016 model year Jetta, only the Jetta Hybrid model is involved in this parts recovery program. Safety Risk: No safety defect has been identified with these auxiliary heater elements. Corrective Actions: Volkswagen will notify owners by mail and advise them to take their vehicle to a dealership to replace the auxiliary heater element at no charge.

Airbag

2021017 21 Jan 2021

Issue: On certain vehicles, long-term exposure to high absolute humidity and temperature, combined with high temperature cycling, may eventually degrade the propellant contained in the driver-front airbag. This could cause the airbag to deploy with more force than normal. If the airbag inflator ruptures, fragments could be propelled toward vehicle occupants or cause damage to the airbag assembly, preventing its proper function. Safety Risk: If the vehicle is involved in a crash requiring an airbag deployment, the airbag inflator could rupture and create a risk of injury. Corrective Action: Owners will be notified by mail and instructed to take their vehicle to a dealer to replace the driver-front airbag. Note: The Canadian climate results in the propellant degrading slowly. This recall is being conducted as a precaution to address future risk. It is expected that all airbag inflators will be replaced before their function would be affected.

Label

2020353 4 Aug 2020

Issue: On certain vehicles, the warning label for the engine block heater cable is written in English only. As a result, a French user may not receive important safety information about how to use the engine block heater. A label that is not provided in both official languages could create confusion. Safety Risk: User confusion could increase the risk of injury when trying to use the block heater. Corrective Actions: The company will mail each owner a new label for the block heater cable. If you would like help installing the label, you can contact a dealer for assistance.



Powertrain

2019423 22 Aug 2019

Issue: On certain vehicles, a build-up of silicate on the shift lever switch could cause the transmission to detect that it is in the Park position when it isn't. This could allow the ignition key to be removed when the transmission is not in the Park position. If the parking brake is not applied, this could allow the car to roll away. Safety Risk: If the transmission position is not displayed correctly, a user may not know that the vehicle is not in the PARK position. If the parking brake is not applied, this could create a risk of a vehicle roll-away and increase the risk of a crash. Corrective Actions: The company will notify owners by mail. Owners will be instructed to take their vehicle to a dealer to have a new shift lever micro switch and control unit installed.

Structure

2014465 20 Oct 2014

On certain vehicles, the panoramic sunroof glass and steel frame may have been manufactured out of tolerance. This issue may result in the sunroof fracturing if the vehicle were to experience a sudden jolt, especially in cold temperatures. Sunroof glass panel breakage, while the vehicle is in motion, could cause driver distraction, which could result in a crash causing injury and/or property damage. Additionally, broken glass inside the vehicle poses a risk of injury to vehicle occupants. Correction: Dealers will replace the panoramic sunroof glass assembly.

Suspension

2014464 20 Oct 2014

On certain vehicles, if the rear axle trailing arms are damaged in a rear or side-rear impact crash and a repair facility does not correctly diagnose or replace damaged rear axle components, rear trailing arm durability could be reduced, which could result in a sudden fracture of the trailing arm. This could lead to a loss of vehicle control, which could increase the risk of a crash causing injury and/or damage to property. Correction: Dealers will install a sheet metal inlay on both rear axle trailing arms. The inlay is designed to help prevent the sudden loss of vehicle control should a rear axle trailing arm fracture occur if undiagnosed/unrepaired damage exists from a previous rear or side-rear impact/crash.

1 more on the model-year record, cardog.app/tools/recalls/volkswagen/beetle/2013

Listed for the model year, not checked against your VIN. Volkswagen confirms which apply.
Check your VIN with Volkswagen Canada or call a Volkswagen dealer with your VIN.
www.vw.ca/en/owners-and-drivers/recalls.html

United States: 7 NHTSA records for this model year, kept apart from the Canadian listing.^[3]

§3 VALUE [4]

This car asks \$14,995^[5], \$2,295 over the median of \$12,700^[4].



Lowest ask	\$9,998
Middle half	\$11,933 – \$13,894
Median ask	\$12,700
This car	\$14,995

Same model year · 7 live listings · as of 28 Oct 2026

OTHER 2013 VOLKSWAGEN BEETLE LISTINGS [5]

Grande Prairie, AB · 169,416 km	\$13,999
Ottawa, ON · 163,246 km	\$11,871
Oakville, ON · 116,700 km	\$13,788
Mississauga, ON · 163,282 km	\$12,700
Guelph, ON · 133,105 km	\$9,998



§4 EVENTS

2013	Model year 2013 ^[1] Assembly plant Puebla, Mexico
15 Nov 2012	Transport Canada recall 2012389 ^[2] Issued for the model year · Airbag
20 Oct 2014	Transport Canada recall 2014465 ^[2] Issued for the model year · Structure
20 Oct 2014	Transport Canada recall 2014464 ^[2] Issued for the model year · Suspension
22 Aug 2019	Transport Canada recall 2019423 ^[2] Issued for the model year · Powertrain
4 Aug 2020	Transport Canada recall 2020353 ^[2] Issued for the model year · Label
21 Jan 2021	Transport Canada recall 2021017 ^[2] Issued for the model year · Airbag
30 Oct 2024	Transport Canada recall 2024648 ^[2] Issued for the model year · Heater and defroster
18 Sep 2026	Listed for sale, Kelowna, BC ^[5] Turner Volkswagen · asking \$14,995
28 Oct 2026	Listing last updated ^[5] asking \$14,995

§5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.

SOURCES

- | | |
|---|--|
| [1] Cardog identity register, decoded from the VIN | [4] Cardog market quote, same model year, 7 live listings, as of 28 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year | [5] Live public dealer listings on Cardog, as of 28 Oct 2026 |
| [3] NHTSA recall records (United States), listed for the model year | |

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

