

Register entry, as of 28 October 2026

Listed for sale

Record ID e949b435e482

2015 Volkswagen Jetta SE, Sport

1.8 L, 4 cylinders · Sedan · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

3VW B07AJ 7 F M 419345

WMI 1-3

Volkswagen De Mexico Sa...

DESCRIPTOR 4-8

Jetta · 1.8 L

CHECK 9

Verified

YEAR 10

2015

PLANT 11

Puebla

SERIAL 12-17

Build sequence

§1 IDENTITY [1]

Model year	2015	Engine	1.8 L, 4 cylinders
Make	Volkswagen	Fuel	Gasoline
Model	Jetta	Drive	Not in the decode
Trim	SE, Sport	Maker	VOLKSWAGEN DE MEXICO SA DE CV
Body	Sedan	Plant	Puebla, Mexico

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/volkswagen/jetta/2015

10 recalls listed by Transport Canada for this model year

Heater and defroster

2024648 30 Oct 2024

Issue: Volkswagen Group Canada is conducting a parts recovery campaign targeting 2012-2016 Volkswagen vehicles equipped with a TDI (diesel) engine built between May 25, 2011 and June 1, 2016. The auxiliary heater elements are being recovered to aid in Volkswagen's analysis in support of Transport Canada defect investigation file no. 3280-15-10. Note: This action is not being conducted under the requirements of the Motor Vehicle Safety Act. For the 2016 model year Jetta, only the Jetta Hybrid model is involved in this parts recovery program. Safety Risk: No safety defect has been identified with these auxiliary heater elements. Corrective Actions: Volkswagen will notify owners by mail and advise them to take their vehicle to a dealership to replace the auxiliary heater element at no charge.

Label

2020353 4 Aug 2020

Issue: On certain vehicles, the warning label for the engine block heater cable is written in English only. As a result, a French user may not receive important safety information about how to use the engine block heater. A label that is not provided in both official languages could create confusion. Safety Risk: User confusion could increase the risk of injury when trying to use the block heater. Corrective Actions: The company will mail each owner a new label for the block heater cable. If you would like help installing the label, you can contact a dealer for assistance.

Powertrain

2019423 22 Aug 2019

Issue: On certain vehicles, a build-up of silicate on the shift lever switch could cause the transmission to detect that it is in the Park position when it isn't. This could allow the ignition key to be removed when the transmission is not in the Park position. If the parking brake is not applied, this could allow the car to roll away. Safety Risk: If the transmission position is not displayed correctly, a user may not know that the vehicle is not in the PARK position. If the parking brake is not applied, this could create a risk of a vehicle roll-away and increase the risk of a crash. Corrective Actions: The company will notify owners by mail. Owners will be instructed to take their vehicle to a dealer to have a new shift lever micro switch and control unit installed.



Electrical

2017455 20 Sep 2017

On certain vehicles, the factory installed block heater could overheat during use, which could increase the risk of fire causing injury and/or damage to property. Correction: Dealers will inspect and, if necessary, install a new block heater.

Engine

2015504 23 Oct 2015

On certain vehicles, the camshaft lobe which actuates the vacuum pump may fail, causing the pump to fail to deliver further vacuum supply to the brake booster, potentially increasing stopping distances. This would also result in a reduction in available engine power. These issues could increase the risk of a crash causing injury and/or damage to property. Note: This issue would result in the Engine Malfunction Indicator Light (MIL) illuminating. Correction: Dealers will update the engine control module (ECM) software.

Airbag

2015445 5 Oct 2015

On certain vehicles, an electro-magnetic coil inside the Passenger Occupant Detection System (PODS) control module was manufactured with improper insulation between the coil layer. This could result in the failure of the PODS control module, or misclassification of the front passenger seat occupant, which could prevent proper passenger airbag deployment during a crash where deployment is warranted, potentially increasing the risk of injury to the front passenger seat occupant. Correction: Dealers will replace the PODS control module. Note: Should this occur, vehicle occupants would be alerted of a problem by the airbag monitoring light illuminating or by a false indication of the Passenger Airbag OFF indicator.


4 more on the model-year record, cardog.app/tools/recalls/volkswagen/jetta/2015

Listed for the model year, not checked against your VIN. Volkswagen confirms which apply.
Check your VIN with Volkswagen Canada or call a Volkswagen dealer with your VIN.
www.vw.ca/en/owners-and-drivers/recalls.html

United States: 8 NHTSA records for this model year, kept apart from the Canadian listing.^[3]

§3 VALUE ^[4]

This car asks \$7,595^[5], \$1,852 under the median of \$9,447^[4].



Lowest ask	\$3,999
Middle half	\$7,624 – \$11,236
Median ask	\$9,447
This car	\$7,595

Same model year · 36 live listings · as of 28 Oct 2026

OTHER 2015 VOLKSWAGEN JETTA LISTINGS ^[5]

Ajax, ON · 155,100 km	\$7,490
Sarnia, ON · 134,602 km	\$8,999
Lévis, QC · 146,062 km	\$4,995
Quebec, QC · 54,000 km	\$8,990
Quebec, QC · 135,500 km	\$7,950
Petrolia, ON · 134,602 km	\$8,999

§4 EVENTS

2015

Model year 2015^[1]
Assembly plant Puebla, Mexico



5 Mar 2014	Transport Canada recall 2014068 ^[2] Issued for the model year · Accessories
22 Oct 2014	Transport Canada recall 2014469 ^[2] Issued for the model year · Seats and restraints
11 Dec 2014	Transport Canada recall 2014562 ^[2] Issued for the model year · Lights and instruments
17 Dec 2014	Transport Canada recall 2014575 ^[2] Issued for the model year · Fuel system
5 Oct 2015	Transport Canada recall 2015445 ^[2] Issued for the model year · Airbag
23 Oct 2015	Transport Canada recall 2015504 ^[2] Issued for the model year · Engine
20 Sep 2017	Transport Canada recall 2017455 ^[2] Issued for the model year · Electrical
22 Aug 2019	Transport Canada recall 2019423 ^[2] Issued for the model year · Powertrain
4 Aug 2020	Transport Canada recall 2020353 ^[2] Issued for the model year · Label
30 Oct 2024	Transport Canada recall 2024648 ^[2] Issued for the model year · Heater and defroster
28 Sep 2026	Listed for sale, Terrebonne, QC ^[5] Lallier Auto Inc.(Repentigny) · asking \$7,595
26 Oct 2026	Listing last updated ^[5] asking \$7,595

§5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.

SOURCES

- | | |
|---|---|
| [1] Cardog identity register, decoded from the VIN | [4] Cardog market quote, same model year, 36 live listings, as of 28 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year | [5] Live public dealer listings on Cardog, as of 28 Oct 2026 |
| [3] NHTSA recall records (United States), listed for the model year | |

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

