

Register entry, as of 28 October 2026

Listed for sale

Record ID ef12f1bdc8c7

2010 Subaru B9 Tribeca 7 Pass Limited w/NAVI

3.6 L, 6 cylinders · AWD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

4S4 **WX9HD** **9** **A** **4** **401263**

WMI 1-3

Subaru Of America, Inc

DESCRIPTOR 4-8

B9 Tribeca · 3.6 L

CHECK 9

Verified

YEAR 10

2010

PLANT 11

United States

SERIAL 12-17

Build sequence

§1 IDENTITY [1]

Model year	2010	Engine	3.6 L, 6 cylinders
Make	Subaru	Fuel	Gasoline
Model	B9 Tribeca	Drive	AWD
Trim	7 Pass Limited w/NAVI	Maker	SUBARU OF AMERICA, INC
Body	Sport Utility Vehicle	Plant	United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/subaru/b9-tribeca/2010

6 recalls listed by Transport Canada for this model year

Label 2024546 15 Aug 2024

Issue: On certain vehicles, the compliance label may be missing information in French. The words listed on the label for "Tires", "Rims", "Front" and "Rear" appear in English only, when they should be listed as "Tires/Pneus", "Rims/Jantes", "Front/Avant" and "Rear/Arriere". Canadian regulations require this information to be listed on the label in both English and French. Safety Risk: These small errors do not affect vehicle safety. Corrective Actions: This is not a recall. Subaru has corrected the compliance label for all new vehicles.

Electrical 2019191 18 Apr 2019

Issue: A problem with certain replacement ignition switches may allow the key turn out of the "ON" position while driving. This could cause the engine to turn off suddenly. It could also cause the airbag system not to work properly in a crash. Note: This is a voluntary service campaign that is not being conducted under the requirements of the Motor Vehicle Safety Act. This problem only affects certain parts used for replacement of original parts. Safety Risk: A sudden loss of engine power could increase the risk of a crash. An airbag system that does not work properly in a crash could cause an increased risk of injuries. Corrective Actions: The company will notify owners by mail and instruct them to take their vehicle to a dealer to inspect the ignition switch, and replace it as necessary.



Airbag

2019013 10 Jan 2019

Issue: On certain vehicles, long-term exposure to high absolute humidity and temperature, combined with high temperature cycling, may eventually degrade the propellant contained in the passenger-front airbag. This could cause the airbag to deploy with more force than normal. If the airbag inflator ruptures, fragments could be propelled toward vehicle occupants or cause damage to the airbag assembly, preventing its proper function. Safety Risk: If the vehicle is involved in a crash requiring an airbag deployment, the airbag inflator could rupture and create a risk of injury. Corrective Action: Owners will be notified by mail and instructed to take their vehicle to a dealer to have the passenger-front airbag inflator replaced. Note: The Canadian climate results in the propellant degrading slowly. This recall is being conducted as a precaution to address future risk. It is expected that all airbag inflators will be replaced before their function would be affected.

Structure

2016048 1 Feb 2016

On certain vehicles, the primary and secondary hood latches could fail at the same time. If this were to occur, the hood could open unexpectedly while the vehicle is being driven. This could compromise the driver's ability to see the road and its users, as well as cause damage to the windshield. These issues could result in a crash causing injury and/or property damage. Correction: Dealers will inspect the hood latches, and either clean and lubricate or replace with the current style part. When parts are available, dealers will install revised hood latches.

Accessories

2012444 27 Dec 2012

On certain vehicles equipped with dealer-installed accessory puddle lights, a short circuit may develop causing the lights to melt and/or emit smoke. This could result in a fire causing property damage and/or injury. Correction: Dealers will install an additional fused wiring harness to protect against short circuits.

Other

2010081 18 Mar 2010

On certain vehicles, the inner door handle cable and window regulator may interfere, causing sudden door unlatching. If the door latch is disengaged while the vehicle is being driven, the door may open, increasing the risk of personal injury or death to the driver or front seat passenger. Correction: Dealers will re-route the inner door handle cable.

Listed for the model year, not checked against your VIN. Subaru confirms which apply.


Check your VIN with Subaru Canada or call a Subaru dealer with your VIN.

www.subaru.ca/WebPage.aspx?WebSiteID=282&WebPageID=21091

United States: 10 NHTSA records for this model year, kept apart from the Canadian listing.^[3]

§3 VALUE ^[4]

This car asks \$8,990^[5], the median^[4].



Lowest ask	\$8,990
Middle half	\$8,990 – \$8,990
Median ask	\$8,990
This car	\$8,990

Same model year · 1 live listings · as of 28 Oct 2026

§4 EVENTS

2010

Model year 2010^[1]

Assembly plant United States

18 Mar 2010

Transport Canada recall 2010081^[2]

Issued for the model year · Other



27 Dec 2012	Transport Canada recall 2012444 ^[2] Issued for the model year · Accessories
1 Feb 2016	Transport Canada recall 2016048 ^[2] Issued for the model year · Structure
10 Jan 2019	Transport Canada recall 2019013 ^[2] Issued for the model year · Airbag
18 Apr 2019	Transport Canada recall 2019191 ^[2] Issued for the model year · Electrical
15 Aug 2024	Transport Canada recall 2024546 ^[2] Issued for the model year · Label
25 Oct 2026	Listed for sale, West Kelowna, BC ^[5] KV Cars Inc. · asking \$8,990

§5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.

SOURCES

- | | |
|---|--|
| [1] Cardog identity register, decoded from the VIN | [4] Cardog market quote, same model year, 1 live listings, as of 28 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year | [5] Live public dealer listings on Cardog, as of 28 Oct 2026 |
| [3] NHTSA recall records (United States), listed for the model year | |

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

