

Register entry, as of 29 October 2026

Listed for sale

Record ID e04ee401040c

2018 Toyota Camry L/LE/SE/XLE

2.5 L, 4 cylinders · 4x2 · Sedan · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

4T1 B11HK 1 J U 013461

WMI 1-3

Toyota Motor Manufacturi...

DESCRIPTOR 4-8

Camry · 2.5 L

CHECK 9

Verified

YEAR 10

2018

PLANT 11

Georgetown

SERIAL 12-17

Build sequence

§1 IDENTITY [1]

Model year	2018	Engine	2.5 L, 4 cylinders
Make	Toyota	Fuel	Gasoline
Model	Camry	Drive	4x2
Trim	L/LE/SE/XLE	Maker	TOYOTA MOTOR MANUFACTURING, KENTUCKY, INC.
Body	Sedan	Plant	Georgetown, Kentucky, United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/toyota/camry/2018

7 recalls listed by Transport Canada for this model year

Electrical

2021723 24 Nov 2021

Issue: This recall is for certain block heater kits installed on certain vehicles or sold as accessories at Toyota or Lexus dealerships. On certain vehicles, the engine block heater cable may not have enough heat protection and could be damaged by high temperatures. If this happens, the cable could short circuit while plugged in, and cause the wiring to overheat or melt. Note: This recall only affects the following block heater/cord part numbers: C014003034 PK5A408J09 PU14000904 C014003151 PK5A408J13 PU14000905 C014000885 PK5A489J11 PU14000907 C014000888 PK5A489J22 PU14000909 C014000907 PK5A410H00 PU14000911 C014100904 PU14000900 PU14000913 C014100907 PU14000901 PU14003571 C014100911 PU14000902 PK5A489J14 PK5A408J05 PU14000903 Safety Risk: Engine block heater wiring that overheats or melts could create the risk of a fire. Corrective Actions: Toyota recommends that you should stop using the engine block heater immediately. Toyota will notify owners by mail and instruct you to take your vehicle to a dealer to disable the engine block heater. For some vehicles, the corrective actions for this recall are under development. For others, a new engine block heater cannot be installed, and the owner will receive a refund of the purchase price of the engine block heater.

Brakes

2021702 17 Nov 2021

Issue: On certain vehicles, the brake vacuum pump may fail. If this happens, there could be a loss of brake assist. This can cause an increase in brake pedal effort and increase the distance needed to stop the vehicle. Safety Risk: A sudden increase in brake pedal effort could lead to an increased stopping distance. This could increase the risk of a crash. Corrective Actions: Toyota will notify owners by mail and instruct you to take your vehicle to a dealer to inspect the vacuum pump. It will be repaired or replaced, as necessary.



Fuel system

2020514 28 Oct 2020

Issue: On certain vehicles, the low-pressure fuel pump could fail. If this happens, then engine may run rough or may not start and the check engine light may turn on. This could also result in a sudden loss of engine power while driving. Note: This recall is an expansion of recalls SRC R95/SRC R96 and SRC RA2/SRC RA3 (Transport Canada Recall Numbers 2020-005 and 2020-088). Safety Risk: A sudden loss of engine power could increase the risk of a crash. Corrective Actions: The company will notify owners by mail and instruct you to take your vehicle to a dealer to replace the fuel pump.

Fuel system

2020088 4 Mar 2020

Issue: On certain vehicles, the low-pressure fuel pump could fail. If this happens, then engine may run rough or may not start and the check engine light may turn on. This could also result in a sudden loss of engine power while driving. Note: This recall is an expansion of recall SRC R95/SRC R96 (Transport Canada Recall No. 2020-005) Safety Risk: A sudden loss of engine power could increase the risk of a crash. Corrective Actions: The company will notify owners by mail and instruct you to take your vehicle to a dealer to replace the fuel pump.

Brakes

2018155 3 Apr 2018

On certain vehicles, an oil passage in the rotor of the vacuum pump may not have been machined properly and could result in oil not being distributed throughout the pump. This could lead to the illumination of a warning light and message, an audible tone, and a sudden loss of braking assist, which could increase stopping distances and increase the risk of a crash causing injury and/or damage to property. Correction: Dealers will replace the vacuum pump with a new one.

Engine

2018148 28 Mar 2018

On certain vehicles equipped with 4 cylinder engines, the engine pistons may have been produced with a diameter larger than the design specification. This could cause the engine to run rough, create an abnormal sound, emit smoke from the exhaust, and/or illuminate warning lights and messages. Additionally, it could result reduced motive power or the engine stopping, which could increase the risk of a crash causing injury and/or damage to property. Correction: Dealers will inspect piston production date code and, if an engine contains a piston from the affected production period, the engine assembly will be replaced with a new one.

1 more on the model-year record, cardog.app/tools/recalls/toyota/camry/2018

Listed for the model year, not checked against your VIN. Toyota confirms which apply.

Check your VIN with Toyota Canada or call a Toyota dealer with your VIN.

www.toyota.ca/en/owners/recalls/

United States: 8 NHTSA records for this model year, kept apart from the Canadian listing.^[3]

§3 VALUE [4]

This car asks \$24,990^[5], \$4,991 over the median of \$19,999^[4].



Lowest ask \$12,899

Middle half \$17,370 – \$21,999

Median ask \$19,999

This car \$24,990

Same configuration · 24 live listings · as of 29 Oct 2026

OTHER 2018 TOYOTA CAMRY LISTINGS [5]

Gatineau, QC · 58,010 km	\$22,995
Penticton, BC · 107,461 km	\$19,995
Penticton, BC · 147,386 km	\$17,995
Gatineau, QC · 58,010 km	\$22,995
Edmonton, AB · 33,560 km	\$28,995



Etobicoke, ON · 33,686 km

\$24,995

§4 EVENTS

2018	Model year 2018 ^[1] Assembly plant Georgetown, Kentucky, United States
14 Feb 2018	Transport Canada recall 2018090 ^[2] Issued for the model year · Fuel system
28 Mar 2018	Transport Canada recall 2018148 ^[2] Issued for the model year · Engine
3 Apr 2018	Transport Canada recall 2018155 ^[2] Issued for the model year · Brakes
4 Mar 2020	Transport Canada recall 2020088 ^[2] Issued for the model year · Fuel system
28 Oct 2020	Transport Canada recall 2020514 ^[2] Issued for the model year · Fuel system
17 Nov 2021	Transport Canada recall 2021702 ^[2] Issued for the model year · Brakes
24 Nov 2021	Transport Canada recall 2021723 ^[2] Issued for the model year · Electrical
26 Oct 2026	Listed for sale, Orangeville, ON ^[5] Orangeville Autosport · asking \$24,990
28 Oct 2026	Listing last updated ^[5] asking \$24,990

§5 DOCUMENTS

Window sticker We have not collected this label yet.

SOURCES

- | | |
|---|--|
| [1] Cardog identity register, decoded from the VIN | [4] Cardog market quote, same configuration, 24 live listings, as of 29 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year | [5] Live public dealer listings on Cardog, as of 29 Oct 2026 |
| [3] NHTSA recall records (United States), listed for the model year | |

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

