

Register entry, as of 27 October 2026

Listed for sale

Record ID c2535c3c953d

2010 Toyota Camry

2.5 L, 4 cylinders · 4x2 · Sedan · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

4T1 BF3EK 4 A U 540914

WMI 1-3

Toyota Motor Manufacturi...

DESCRIPTOR 4-8

Camry · 2.5 L

CHECK 9

Verified

YEAR 10

2010

PLANT 11

Georgetown

SERIAL 12-17

Build sequence

§1 IDENTITY [1]

Model year	2010	Engine	2.5 L, 4 cylinders
Make	Toyota	Fuel	Gasoline
Model	Camry	Drive	4x2
Trim	Not in the decode	Maker	TOYOTA MOTOR MANUFACTURING, KENTUCKY, INC.
Body	Sedan	Plant	Georgetown, Kentucky, United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/toyota/camry/2010

4 recalls listed by Transport Canada for this model year

Electrical	2021723 24 Nov 2021
Issue: This recall is for certain block heater kits installed on certain vehicles or sold as accessories at Toyota or Lexus dealerships. On certain vehicles, the engine block heater cable may not have enough heat protection and could be damaged by high temperatures. If this happens, the cable could short circuit while plugged in, and cause the wiring to overheat or melt. Note: This recall only affects the following block heater/cord part numbers: C014003034 PK5A408J09 PU14000904 C014003151 PK5A408J13 PU14000905 C014000885 PK5A489J11 PU14000907 C014000888 PK5A489J22 PU14000909 C014000907 PK5A410H00 PU14000911 C014100904 PU14000900 PU14000913 C014100907 PU14000901 PU14003571 C014100911 PU14000902 PK5A489J14 PK5A408J05 PU14000903 Safety Risk: Engine block heater wiring that overheats or melts could create the risk of a fire. Corrective Actions: Toyota recommends that you should stop using the engine block heater immediately. Toyota will notify owners by mail and instruct you to take your vehicle to a dealer to disable the engine block heater. For some vehicles, the corrective actions for this recall are under development. For others, a new engine block heater cannot be installed, and the owner will receive a refund of the purchase price of the engine block heater.	
Brakes	2010038 9 Feb 2010
On certain vehicles, clearance between the clamp on the power steering pressure hose and the brake tube for the left rear brake may be insufficient. If the vehicle is continuously operated in this condition, the hose clamp may wear a hole in the brake tube resulting in brake fluid leakage. In such case the brake pedal stroke will increase and stopping distance may be degraded which could result in a crash causing property damage, personal injury or death. Correction: Dealers will inspect and replace the brake tube.	



Other

2010012 22 Jan 2010

On certain vehicles, accelerator pedal movement may become rough, slow to return, or the pedal may stick in a depressed position. This could result in a loss of throttle control and a vehicle crash, causing property damage, personal injury or death. Correction: Dealers will install a steel reinforcement bar to the accelerator pedal assembly. With this reinforcement in place, the excess friction that can cause the pedal to stick is eliminated.

Other

2009290 7 Oct 2009

On certain vehicles, the accelerator pedal may become stuck in the wide open position due to an unsecured or incompatible driver's floor mat. A stuck open accelerator pedal may result in very high vehicle speeds and make it difficult to stop the vehicle, which could cause a crash, serious injury or death. Correction: Dealers will reconfigure the shape of the accelerator pedal. Certain models will also have the shape of the floor underneath the accelerator pedal modified and/or a brake override system installed.

Listed for the model year, not checked against your VIN. Toyota confirms which apply.


Check your VIN with Toyota Canada or call a Toyota dealer with your VIN.

www.toyota.ca/en/owners/recalls/

United States: 9 NHTSA records for this model year, kept apart from the Canadian listing.^[3]

§3 VALUE [4]

This car asks \$9,999^[5], \$2,777 over the median of \$7,222^[4].



Lowest ask	\$2,595
Middle half	\$2,990 – \$8,995
Median ask	\$7,222
This car	\$9,999

Same model year · 8 live listings · as of 27 Oct 2026

OTHER 2010 TOYOTA CAMRY LISTINGS [5]

Yarmouth, NS · 387,647 km	\$2,595
London, ON · 196,558 km	\$8,995
Markham, ON · 157,701 km	\$8,995
Dayton, NS · 387,641 km	\$2,595
Mississauga, ON · 154,825 km	\$7,450

§4 EVENTS

2010	Model year 2010 ^[1] Assembly plant Georgetown, Kentucky, United States
7 Oct 2009	Transport Canada recall 2009290 ^[2] Issued for the model year · Other
22 Jan 2010	Transport Canada recall 2010012 ^[2] Issued for the model year · Other
9 Feb 2010	Transport Canada recall 2010038 ^[2] Issued for the model year · Brakes



24 Nov 2021	Transport Canada recall 2021723 ^[2] Issued for the model year · Electrical
20 Aug 2026	Listed for sale, Richmond, BC ^[5] Newmate Auto Group · asking \$9,999
27 Oct 2026	Listing last updated ^[5] asking \$9,999

§5 DOCUMENTS

Window sticker We have not collected this label yet.

SOURCES

- | | |
|---|--|
| [1] Cardog identity register, decoded from the VIN | [4] Cardog market quote, same model year, 8 live listings, as of 27 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year | [5] Live public dealer listings on Cardog, as of 27 Oct 2026 |
| [3] NHTSA recall records (United States), listed for the model year | |

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

