

Register entry, as of 28 October 2026

Listed for sale

Record ID da795bdd1b7c

# 2006 Toyota Avalon

3.5 L, 6 cylinders · 4x2 · Sedan · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

**4T1 BK36B 6 6 U 150351**

WMI 1-3

Toyota Motor Manufacturi...

DESCRIPTOR 4-8

Avalon · 3.5 L

CHECK 9

Verified

YEAR 10

2006

PLANT 11

Georgetown

SERIAL 12-17

Build sequence

## §1 IDENTITY [1]

|            |                   |        |                                            |
|------------|-------------------|--------|--------------------------------------------|
| Model year | 2006              | Engine | 3.5 L, 6 cylinders                         |
| Make       | Toyota            | Fuel   | Gasoline                                   |
| Model      | Avalon            | Drive  | 4x2                                        |
| Trim       | Not in the decode | Maker  | TOYOTA MOTOR MANUFACTURING, KENTUCKY, INC. |
| Body       | Sedan             | Plant  | Georgetown, Kentucky, United States        |

## §2 OBLIGATIONS [2]

[cardog.app/tools/recalls/toyota/avalon/2006](https://cardog.app/tools/recalls/toyota/avalon/2006)

## 4 recalls listed by Transport Canada for this model year

### Electrical

2021723 24 Nov 2021

Issue: This recall is for certain block heater kits installed on certain vehicles or sold as accessories at Toyota or Lexus dealerships. On certain vehicles, the engine block heater cable may not have enough heat protection and could be damaged by high temperatures. If this happens, the cable could short circuit while plugged in, and cause the wiring to overheat or melt. Note: This recall only affects the following block heater/cord part numbers: C014003034 PK5A408J09 PU14000904 C014003151 PK5A408J13 PU14000905 C014000885 PK5A489J11 PU14000907 C014000888 PK5A489J22 PU14000909 C014000907 PK5A410H00 PU14000911 C014100904 PU14000900 PU14000913 C014100907 PU14000901 PU14003571 C014100911 PU14000902 PK5A489J14 PK5A408J05 PU14000903 Safety Risk: Engine block heater wiring that overheats or melts could create the risk of a fire. Corrective Actions: Toyota recommends that you should stop using the engine block heater immediately. Toyota will notify owners by mail and instruct you to take your vehicle to a dealer to disable the engine block heater. For some vehicles, the corrective actions for this recall are under development. For others, a new engine block heater cannot be installed, and the owner will receive a refund of the purchase price of the engine block heater.

### Brakes

2010361 21 Oct 2010

Certain vehicles use brake fluids containing polymers that act as lubricants for certain brake system components. If during vehicle maintenance, brake fluid is used that does not contain such polymers or only small amounts, part of the internal rubber seal located at the end of the brake master cylinder piston may become dry and may curl during movement of the piston. If this occurs, a small amount of the brake fluid could slowly leak from the brake master cylinder into the brake booster, resulting in illumination of the brake warning lamp. If the brake warning light has illuminated and the vehicle continues to be operated without refilling the master cylinder brake fluid reservoir, the driver will begin to notice a spongy or soft brake pedal feel and braking performance may gradually decline. This will increase the stopping distance, increasing the likelihood of a crash. Correction: Dealers will replace the brake master cylinder seal with a newly designed one.



## Other

2010012 22 Jan 2010

On certain vehicles, accelerator pedal movement may become rough, slow to return, or the pedal may stick in a depressed position. This could result in a loss of throttle control and a vehicle crash, causing property damage, personal injury or death. Correction: Dealers will install a steel reinforcement bar to the accelerator pedal assembly. With this reinforcement in place, the excess friction that can cause the pedal to stick is eliminated.

## Other

2009290 7 Oct 2009

On certain vehicles, the accelerator pedal may become stuck in the wide open position due to an unsecured or incompatible driver's floor mat. A stuck open accelerator pedal may result in very high vehicle speeds and make it difficult to stop the vehicle, which could cause a crash, serious injury or death. Correction: Dealers will reconfigure the shape of the accelerator pedal. Certain models will also have the shape of the floor underneath the accelerator pedal modified and/or a brake override system installed.

Listed for the model year, not checked against your VIN. Toyota confirms which apply.


Check your VIN with Toyota Canada or call a Toyota dealer with your VIN.

[www.toyota.ca/en/owners/recalls/](http://www.toyota.ca/en/owners/recalls/)

United States: 7 NHTSA records for this model year, kept apart from the Canadian listing.<sup>[3]</sup>

§3 VALUE <sup>[4]</sup>

This car asks \$9,995<sup>[5]</sup>, the median<sup>[4]</sup>.



Same model year · 1 live listings · as of 28 Oct 2026

## §4 EVENTS

|             |                                                                                          |
|-------------|------------------------------------------------------------------------------------------|
| 2006        | Model year 2006 <sup>[1]</sup><br>Assembly plant Georgetown, Kentucky, United States     |
| 7 Oct 2009  | Transport Canada recall 2009290 <sup>[2]</sup><br>Issued for the model year · Other      |
| 22 Jan 2010 | Transport Canada recall 2010012 <sup>[2]</sup><br>Issued for the model year · Other      |
| 21 Oct 2010 | Transport Canada recall 2010361 <sup>[2]</sup><br>Issued for the model year · Brakes     |
| 24 Nov 2021 | Transport Canada recall 2021723 <sup>[2]</sup><br>Issued for the model year · Electrical |
| 20 Jun 2026 | Listed for sale, Edmonton, AB <sup>[5]</sup><br>Matrix Motors YEG · asking \$9,995       |



28 Oct 2026      Listing last updated<sup>[5]</sup>  
asking \$9,995

## §5 DOCUMENTS

Window sticker      We have not collected this label yet.

## SOURCES

- |                                                                     |                                                                              |
|---------------------------------------------------------------------|------------------------------------------------------------------------------|
| [1] Cardog identity register, decoded from the VIN                  | [4] Cardog market quote, same model year, 1 live listings, as of 28 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year     |                                                                              |
| [3] NHTSA recall records (United States), listed for the model year | [5] Live public dealer listings on Cardog, as of 28 Oct 2026                 |

## STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

