

Register entry, as of 28 October 2026

Listed for sale

Record ID be9dca5165da

2022 Honda Odyssey EX-L w/ NAVI / EX-L w/ RES

3.5 L, 6 cylinders · 4x2 · Minivan · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

5FN **RL6H6** **X** **N** **B** **500217**

WMI 1-3

American Honda Motor Co...

DESCRIPTOR 4-8

Odyssey · 3.5 L

CHECK 9

Verified

YEAR 10

2022

PLANT 11

Lincoln

SERIAL 12-17

Build sequence

§1 IDENTITY [1]

Model year	2022	Engine	3.5 L, 6 cylinders
Make	Honda	Fuel	Gasoline
Model	Odyssey	Drive	4x2
Trim	EX-L w/ NAVI / EX-L w/ RES	Maker	AMERICAN HONDA MOTOR CO., INC.
Body	Minivan	Plant	Lincoln, Alabama, United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/honda/odyssey/2022

7

 recalls listed by Transport Canada for this model year

Seats and restraints

2026251 21 May 2026

Issue: On certain vehicles, the weight sensor for the front passenger seat may not have been manufactured properly. As a result, the passenger-front airbag and knee airbag could deploy in a crash that doesn't require them to. Note: This recall is an expansion of Transport Canada recall no. 2024-059. If the weight sensor fails, the SRS warning light would turn on in the instrument panel. Safety Risk: An airbag system that doesn't work properly could increase the risk of injury in a crash. Corrective Actions: The company will notify owners by mail and advise you to take your vehicle to a dealership to replace the passenger-front seat weight sensor.

Seats and restraints

2026181 9 Apr 2026

Issue: On certain vehicles, under certain conditions, a software problem could cause the side airbag(s) and side curtain airbag(s) to inflate unexpectedly. Safety Risk: An airbag that deploys without a crash could create a risk of injury. Corrective Actions: Honda will notify owners by mail and advise you to take your vehicle to a dealership to reprogram or replace the supplemental restraint system (SRS) electronic control unit (ECU), as necessary.



Seats and restraints

2026003 5 Jan 2026

Issue: On certain vehicles converted for wheelchair access by Vantage Mobility, the wheelchair tie-down retractors may not have been manufactured properly. As a result, the retractor(s) may not lock automatically. If this happens, the wheelchair may not be secured correctly and could move in a crash. Note: This recall only affects certain Q'Straint QRT-DELUXE and QRT-MAX wheelchair retractors with the part number Q8-6200 or Q8-6209. Safety Risk: A wheelchair that moves in a crash could increase the risk of injury. Corrective Actions: To reduce the safety risk, Vantage Mobility recommends you confirm the wheelchair is secured properly by attempting to move it before driving until the recall repairs have been completed. Vantage Mobility will notify owners by mail and advise you to take your vehicle to a Vantage Mobility service center to inspect and, if necessary, replace the wheelchair retractor(s).

Visual system

2024761 13 Dec 2024

Issue: Under certain conditions, a software problem could cause the wrong view mode to display when the transmission is shifted into reverse. As a result, the rearview camera image may not appear correctly on the display screen. Canadian regulations allow only certain view modes to be displayed when the vehicle is reversing. Note: Vehicles that received a software update previously under a Honda product update, campaign no. PO1 - 'Incorrect Rear View Camera View Mode', don't require this repair. Safety Risk: A rearview camera image that doesn't display the correct view mode could reduce a driver's field of view behind the vehicle. This could increase the risk of a crash. Corrective Actions: Honda will notify owners by mail and have sent a wireless over-the-air software update to eligible vehicles to update the vehicle software. Alternatively, you may schedule an appointment to have the update performed at a Honda dealership.

Airbag

2024059 1 Feb 2024

Issue: On certain vehicles, the weight sensor for the front passenger seat may not have been manufactured properly. As a result, the passenger-front airbag and knee airbag could deploy in a crash that doesn't require them to. Note: If the weight sensor fails, the SRS warning light would turn on in the instrument panel. Safety Risk: An airbag system that doesn't work properly could increase the risk of injury in a crash. Corrective Actions: Honda will notify owners by mail and advise you to take your vehicle to a dealership for an inspection if the SRS warning light is on. If the SRS warning light is on due to a faulty weight sensor, the weight sensor will be replaced. When repair parts are available, Honda will send you a second letter. They will advise you to take your vehicle to a dealership to replace the passenger-front seat weight sensor.

Visual system

2023350 15 Jun 2023

Issue: On certain vehicles, the terminals on the coaxial cable for the audio display unit may not have been manufactured correctly. As a result, the audio display unit could lose its connection, and the rearview camera image may not display when the transmission is shifted into reverse gear. Safety Risk: A rearview camera image that doesn't display could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: Honda will notify owners by mail and advise you to take your vehicle to a dealership to replace the media oriented systems transport (MOST) cable harness, and install a cover over the audio display unit connector.


1 more on the model-year record, cardog.app/tools/recalls/honda/odyssey/2022

Listed for the model year, not checked against your VIN. Honda confirms which apply.
Check your VIN with Honda Canada or call a Honda dealer with your VIN.
www.honda.ca/en/recalls

United States: 9 NHTSA records for this model year, kept apart from the Canadian listing.^[3]

§3 VALUE ^[4]

This car asks \$29,999^[5], \$5,639 under the median of \$35,638^[4].



Lowest ask	\$19,995
Middle half	\$33,468 – \$37,460
Median ask	\$35,638
This car	\$29,999

Same configuration · 18 live listings · as of 28 Oct 2026



OTHER 2022 HONDA ODYSSEY LISTINGS ^[5]

Mississauga, ON · 127,707 km	\$35,995
Brossard, QC · 98,312 km	\$34,995
Scarborough, ON · 121,092 km	\$33,890
Toronto, ON · 127,707 km	\$35,995
Chilliwack, BC · 87,431 km	\$41,998
Vaughan, ON · 218,172 km	\$24,995

§4 EVENTS

2022	Model year 2022 ^[1] Assembly plant Lincoln, Alabama, United States
16 Mar 2023	Transport Canada recall 2023136 ^[2] Issued for the model year · Visual system
15 Jun 2023	Transport Canada recall 2023350 ^[2] Issued for the model year · Visual system
1 Feb 2024	Transport Canada recall 2024059 ^[2] Issued for the model year · Airbag
13 Dec 2024	Transport Canada recall 2024761 ^[2] Issued for the model year · Visual system
5 Jan 2026	Transport Canada recall 2026003 ^[2] Issued for the model year · Seats and restraints
9 Apr 2026	Transport Canada recall 2026181 ^[2] Issued for the model year · Seats and restraints
21 May 2026	Transport Canada recall 2026251 ^[2] Issued for the model year · Seats and restraints
25 Oct 2026	Listed for sale, North York, ON ^[5] Monaco Motorcars Inc · asking \$29,999
28 Oct 2026	Listing last updated ^[5] asking \$29,999

§5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.

SOURCES

- | | |
|---|--|
| [1] Cardog identity register, decoded from the VIN | [4] Cardog market quote, same configuration, 18 live listings, as of 28 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year | [5] Live public dealer listings on Cardog, as of 28 Oct 2026 |
| [3] NHTSA recall records (United States), listed for the model year | |



STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

