

Register entry, as of 27 October 2026

Listed for sale

Record ID d61f56d859c7

2009 Hummer H3T

5.3 L, 8 cylinders · 4WD · Pickup · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

5GN **EN13L** **4** **9** **8** **129991**

WMI 1-3

Hummer · GENERAL MOTO...

DESCRIPTOR 4-8

H3T · 5.3 L

CHECK 9

Verified

YEAR 10

2009

PLANT 11

Shreveport

SERIAL 12-17

Build sequence

§1 IDENTITY [1]

Model year	2009	Engine	5.3 L, 8 cylinders
Make	Hummer	Fuel	Gasoline
Model	H3T	Drive	4WD
Trim	Not in the decode	Maker	GENERAL MOTORS LLC
Body	Pickup	Plant	Shreveport, Louisiana, United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/hummer/h3t/2009

3 recalls listed by Transport Canada for this model year

Heater and defroster 2015286 26 Jun 2015

On certain vehicles, the connector module that controls the blower motor speed in the heat/vent/air conditioning (HVAC) system could overheat under extended periods at high or medium-high blower speed. If this were to occur, it could result in the plastic around the connector module melting by the heat generated, increasing the risk of fire resulting in injury and/or damage to property. Correction: Dealers will replace the female connector and harness.

Accessories 2010140 29 Apr 2010

On certain vehicles, the integral clip-tabs on the hood louver may fracture, which could allow the hood louver to lose its retention mechanism. As the clip-tabs break, the hood louver may rattle against the hood and become loose. If this indicator is unnoticed, additional clips could fracture and the hood louver could detach from the vehicle and strike a vehicle or a bystander, which could result in property damage, personal injury or death. Correction: Dealers will apply an adhesive to the hood louver to secure it to the hood.

Fuel system 2009082 12 Mar 2009

On certain vehicles, the fuel tank front support strap may fracture. Continued use of the vehicle may eventually fracture the rear support strap and stone shield fasteners, which could allow the fuel tank to separate. The errant tank assembly could strike a vehicle, property, or a bystander, which could result in property damage, personal injury or death. Fuel leakage, in the presence of an ignition source, could result in a fire. Correction: Dealers will replace the fuel tank front support strap with an update version.

Listed for the model year, not checked against your VIN. Hummer confirms which apply.

Check your VIN with GM Canada or call a Hummer dealer with your VIN.

experience.gm.ca/en/ownercenter/recalls



§3 VALUE [3]

This car asks \$22,000^[4], the median^[3].



Lowest ask	\$22,000
Middle half	\$22,000 – \$22,000
Median ask	\$22,000
This car	\$22,000

Same model year · 1 live listings · as of 27 Oct 2026

§4 EVENTS

2009	Model year 2009 ^[1] Assembly plant Shreveport, Louisiana, United States
12 Mar 2009	Transport Canada recall 2009082 ^[2] Issued for the model year · Fuel system
29 Apr 2010	Transport Canada recall 2010140 ^[2] Issued for the model year · Accessories
26 Jun 2015	Transport Canada recall 2015286 ^[2] Issued for the model year · Heater and defroster
12 Mar 2025	Listed for sale, Ottawa, ON ^[4] Car-On Auto Sales · asking \$22,000
26 Oct 2026	Listing last updated ^[4] asking \$22,000

§5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN	[3] Cardog market quote, same model year, 1 live listings, as of 27 Oct 2026
[2] Transport Canada recall database, listed for the model year	[4] Live public dealer listings on Cardog, as of 27 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

