

Register entry, as of 28 October 2026

Listed for sale

Record ID b8ddfc3f7956

2020 Lincoln Corsair Reserve

2.0 L, 4 cylinders · 4WD · Crossover Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

5LM CJ2D9 8 L U L00325

WMI 1-3

Lincoln · FORD MOTOR CO...

DESCRIPTOR 4-8

Corsair · 2.0 L

CHECK 9

Verified

YEAR 10

2020

PLANT 11

Louisville

SERIAL 12-17

Build sequence

§1 IDENTITY [1]

Model year	2020	Engine	2.0 L, 4 cylinders
Make	Lincoln	Fuel	Gasoline
Model	Corsair	Drive	4WD
Trim	Reserve	Maker	FORD MOTOR COMPANY
Body	Crossover Utility Vehicle	Plant	Louisville, Kentucky, United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/lincoln/corsair/2020

16 recalls listed by Transport Canada for this model year

Visual system

2026100 5 Mar 2026

Issue: On certain vehicles, a software problem could cause the rearview camera image not to display properly when the transmission is shifted into reverse. Canadian regulations require the rearview image to display when the vehicle is reversing. Safety Risk: A rearview camera image that doesn't display correctly could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: Ford will notify owners by mail. The corrective actions for this recall are under development.

Visual system

2026098 3 Mar 2026

Issue: On certain vehicles, the windshield wiper motor may not have been manufactured properly. As a result, the motor could fail and cause the windshield wipers not to work. Safety Risk: Windshield wipers that don't work could reduce visibility and increase the risk of a crash. Corrective Actions: Ford will notify owners by mail and advise you to take your vehicle to a dealership to inspect and, if necessary, replace the windshield wiper motor.

Electrical

2026005 9 Jan 2026

Issue: On certain vehicles, the engine block heater could leak coolant. If this happens, the block heater could short circuit when it's plugged in. Note: This recall replaces Transport Canada recall no. 2025-554. Vehicles that were repaired under that recall don't require this repair. Safety Risk: A short circuit can create the risk of a fire. Corrective Actions: To reduce the safety risk, Ford advises you not to use the engine block heater until the recall repairs have been completed. Ford will notify owners by mail and advise you to take your vehicle to a dealership to replace the block heater. Alternatively, owners can choose to have the dealership permanently disable the engine block heater.



Seats and restraints

2025724 18 Dec 2025

Issue: On a small number of vehicles, the recall repairs completed by a Ford dealer during recall 25C18 (Transport Canada recall no. 2025-277) may not have been done correctly. As a result, another repair is required. On certain vehicles, the seat belt reminder chime may not sound for long enough when you start the vehicle, and your seat belt is not buckled. Canadian regulations require both a seat belt reminder sound and visual telltale when a driver is not wearing their seat belt. Note: This recall only affects vehicles with a Revel audio system. Safety Risk: A seat belt warning that doesn't work correctly may not remind you to buckle your seat belt. Not wearing your seat belt can increase the risk of injury in a crash. Corrective Actions: Ford will notify owners by mail and advise you to take your vehicle to a dealership to update the audio control module software.

Electrical

2025554 10 Oct 2025

This recall was replaced by Transport Canada recall no. 2026-005. Issue: On certain vehicles, the engine block heater could leak coolant. If this happens, the block heater could short circuit when it's plugged in. Safety Risk: A short circuit can create the risk of a fire. Corrective Actions: To reduce the safety risk, Ford advises you not to use the engine block heater until the recall repairs have been completed. Ford will notify owners by mail and advise you to take your vehicle to a dealership to replace the block heater.

Visual system

2025412 8 Aug 2025

Issue: On certain trucks, water could leak into the connector for the rearview camera. Over time, this could cause corrosion to the ground wire. If this happens, the rearview camera image may not display correctly or at all. Note: Vehicles equipped with 360-degree camera systems are not affected by this recall. Safety Risk: A rearview camera image that doesn't display correctly could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: Ford will notify owners by mail and advise you to take your truck to a dealership to replace the rearview camera and the rearview camera wiring harness.

10 more on the model-year record, cardog.app/tools/recalls/lincoln/corsair/2020

Listed for the model year, not checked against your VIN. Lincoln confirms which apply.

Check your VIN with Lincoln Canada or call a Lincoln dealer with your VIN.

www.lincolncanada.com/support/recalls/

United States: 16 NHTSA records for this model year, kept apart from the Canadian listing.^[3]

§3 VALUE ^[4]

This car asks \$27,588^[5], \$788 over the median of \$26,800^[4].



Lowest ask \$24,495

Middle half \$25,678 – \$27,793

Median ask \$26,800

This car \$27,588

Same configuration · 11 live listings · as of 28 Oct 2026

OTHER 2020 LINCOLN CORSAIR LISTINGS ^[5]

Waterloo, ON · 56,422 km	\$23,595
Kitchener, ON · 56,422 km	\$23,595
Gander, NL · 20,034 km	\$28,995
Kentville, NS · 65,212 km	\$26,800
Lethbridge, AB · 99,099 km	\$25,557
Dollard-Des Ormeaux, QC · 79,000 km	\$24,495



§4 EVENTS

2020	Model year 2020 ^[1] Assembly plant Louisville, Kentucky, United States
13 Aug 2020	Transport Canada recall 2020372 ^[2] Issued for the model year · Suspension
24 Sep 2020	Transport Canada recall 2020454 ^[2] Issued for the model year · Visual system
24 Sep 2021	Transport Canada recall 2021586 ^[2] Issued for the model year · Visual system
27 Dec 2022	Transport Canada recall 2022743 ^[2] Issued for the model year · Seats and restraints
24 Jan 2023	Transport Canada recall 2023018 ^[2] Issued for the model year · Visual system
15 May 2023	Transport Canada recall 2023288 ^[2] Issued for the model year · Visual system
31 Jan 2025	Transport Canada recall 2025043 ^[2] Issued for the model year · Visual system
14 Mar 2025	Transport Canada recall 2025140 ^[2] Issued for the model year · Visual system
23 May 2025	Transport Canada recall 2025277 ^[2] Issued for the model year · Seats and restraints
27 Jun 2025	Transport Canada recall 2025360 ^[2] Issued for the model year · Visual system
8 Aug 2025	Transport Canada recall 2025412 ^[2] Issued for the model year · Visual system
10 Oct 2025	Transport Canada recall 2025554 ^[2] Issued for the model year · Electrical
18 Dec 2025	Transport Canada recall 2025724 ^[2] Issued for the model year · Seats and restraints
9 Jan 2026	Transport Canada recall 2026005 ^[2] Issued for the model year · Electrical
3 Mar 2026	Transport Canada recall 2026098 ^[2] Issued for the model year · Visual system
5 Mar 2026	Transport Canada recall 2026100 ^[2] Issued for the model year · Visual system
19 Oct 2026	Listed for sale, Brampton, ON ^[5] Performance Hyundai Brampton · asking \$27,588



27 Oct 2026 Listing last updated^[5]
asking \$27,588

§5 DOCUMENTS

Window sticker We have not collected this label yet.

SOURCES

- | | |
|---|--|
| [1] Cardog identity register, decoded from the VIN | [4] Cardog market quote, same configuration, 11 live listings, as of 28 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year | [5] Live public dealer listings on Cardog, as of 28 Oct 2026 |
| [3] NHTSA recall records (United States), listed for the model year | |

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

