

Register entry, as of 27 October 2026

Listed for sale

Record ID ebcab5008004

2015 Lincoln MKC LS

2.3 L, 4 cylinders · 4WD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

5LM TJ2AH 9 F U J06452

WMI 1-3

Lincoln · FORD MOTOR CO...

DESCRIPTOR 4-8

MKC · 2.3 L

CHECK 9

Verified

YEAR 10

2015

PLANT 11

Louisville

SERIAL 12-17

Build sequence

§1 IDENTITY [1]

Model year	2015	Engine	2.3 L, 4 cylinders
Make	Lincoln	Fuel	Gasoline
Model	MKC	Drive	4WD
Trim	LS	Maker	FORD MOTOR COMPANY
Body	Sport Utility Vehicle	Plant	Louisville, Kentucky, United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/lincoln/mkc/2015

10 recalls listed by Transport Canada for this model year

Electrical 2026004 9 Jan 2026

Issue: On certain vehicles, the engine block heater could leak coolant. If this happens, the block heater could short circuit when it's plugged in.
Note: This recall only affects certain vehicles equipped with a 2.0 L engine. Safety Risk: A short circuit can create the risk of a fire. Corrective Actions: To reduce the safety risk, Ford advises you not to use the engine block heater until the recall repairs have been completed. Ford will notify owners by mail and advise you to take your vehicle to a dealership to replace the block heater. Alternatively, owners can choose to have the dealership permanently disable the engine block heater.

Visual system 2025449 3 Sep 2025

Issue: On certain vehicles, there could be a problem with the connections inside the rearview camera. As a result, the rearview camera image may not display correctly or at all when the transmission is shifted into reverse. Note: For certain models, this recall also affects incomplete vehicles. Safety Risk: A rearview camera image that doesn't display could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: Ford will notify owners by mail and advise you to take your vehicle to a dealership to inspect and, if necessary, replace the rearview camera.

Visual system 2025224 24 Apr 2025

Issue: On certain vehicles, there could be a problem with the connections inside the rearview camera. As a result, the rearview camera image may not display correctly or at all when the transmission is shifted into reverse. Safety Risk: A rearview camera image that doesn't display could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: Ford will notify owners by mail and advise you to take your vehicle to a dealership to replace the rearview camera.



Electrical

2023310 29 May 2023

Issue: On certain vehicles, the battery monitor sensor could be damaged during servicing. If this happens, the battery monitor system could short circuit. Safety Risk: A short circuit could create a fire risk, even while the vehicle is parked and turned off. Corrective Actions: Ford will notify owners by mail and instruct you to bring your vehicle to a Ford dealership to install an in-line fuse for the battery monitor sensor. Ford advises to park your vehicle outdoors and away from other vehicles or structures until the recall repairs have been completed.

Seats and restraints

2017373 25 Jul 2017

On certain vehicles, improperly tempered bolts may have been used to install certain seats, seatbacks, seatbelt buckles, or seatbelt anchors due to a manufacturing issue. An improperly tempered bolt could fracture and compromise the structural integrity of the seat and/or seatbelt system's performance in a sudden stop or crash, which could increase the risk of injury to vehicle occupants. Correction: Dealers will inspect the bolts, and will remove and replace as necessary. Note: Only E-350 Extended Wagon models with 11-, 12- or 15-passenger seating configurations are involved in this recall.

Structure

2016432 6 Sep 2016

On certain vehicles, the pawl spring tab in the side door latch could break. This condition typically will prevent the door from latching. In certain situations where the door is able to be closed, the door may be partially latched and could unlatch while driving. This could increase the risk of injury to a vehicle occupant seated next to the door, or result in damage to property. Correction: If a door will not latch, dealers will replace all four door latches with a more robust part. Note: A door that is partially latched can cause the courtesy light to remain on, set a door ajar message in the instrument cluster and sound a door ajar chime to alert the driver that there is a door latch problem.

4 more on the model-year record, cardog.app/tools/recalls/lincoln/mkc/2015

Listed for the model year, not checked against your VIN. Lincoln confirms which apply.


Check your VIN with Lincoln Canada or call a Lincoln dealer with your VIN.

www.lincolncanada.com/support/recalls/

United States: 12 NHTSA records for this model year, kept apart from the Canadian listing.^[3]

§3 VALUE [4]

This car asks \$10,990^[5], \$1,005 under the median of \$11,995^[4].



Lowest ask	\$9,249
Middle half	\$10,990 – \$13,999
Median ask	\$11,995
This car	\$10,990

Same model year · 9 live listings · as of 27 Oct 2026

OTHER 2015 LINCOLN MKC LISTINGS [5]

Hamilton, ON · 185,338 km	\$9,249
Kitchener, ON · 129,362 km	\$11,499
Richmond, BC · 168,200 km	\$9,500
Toronto, ON · 115,308 km	\$15,795
Fergus, ON · 115,308 km	\$15,795
Courtenay, BC · 159,292 km	\$12,797



§4 EVENTS

2015	Model year 2015 ^[1] Assembly plant Louisville, Kentucky, United States
6 Aug 2014	Transport Canada recall 2014332 ^[2] Issued for the model year · Visual system
9 Jan 2015	Transport Canada recall 2015008 ^[2] Issued for the model year · Fuel system
9 Jan 2015	Transport Canada recall 2015007 ^[2] Issued for the model year · Powertrain
31 Mar 2016	Transport Canada recall 2016138 ^[2] Issued for the model year · Engine
6 Sep 2016	Transport Canada recall 2016432 ^[2] Issued for the model year · Structure
25 Jul 2017	Transport Canada recall 2017373 ^[2] Issued for the model year · Seats and restraints
29 May 2023	Transport Canada recall 2023310 ^[2] Issued for the model year · Electrical
24 Apr 2025	Transport Canada recall 2025224 ^[2] Issued for the model year · Visual system
3 Sep 2025	Transport Canada recall 2025449 ^[2] Issued for the model year · Visual system
9 Jan 2026	Transport Canada recall 2026004 ^[2] Issued for the model year · Electrical
3 Oct 2026	Listed for sale, Cambridge, ON ^[5] Pristine Auto Sales & Service · asking \$10,990
27 Oct 2026	Listing last updated ^[5] asking \$10,990

§5 DOCUMENTS

Window sticker We have not collected this label yet.

SOURCES

- | | |
|---|--|
| [1] Cardog identity register, decoded from the VIN | [4] Cardog market quote, same model year, 9 live listings, as of 27 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year | [5] Live public dealer listings on Cardog, as of 27 Oct 2026 |
| [3] NHTSA recall records (United States), listed for the model year | |



STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

