

Register entry, as of 27 October 2026

Listed for sale

Record ID 19e0c2cb35b5

# 2010 Toyota Highlander Sports

3.5 L, 6 cylinders · 4WD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

**5TD EK3EH 3 A S 002694**

WMI 1-3

Toyota Motor Manufacturi...

DESCRIPTOR 4-8

Highlander · 3.5 L

CHECK 9

Verified

YEAR 10

2010

PLANT 11

Princeton

SERIAL 12-17

Build sequence

## §1 IDENTITY [1]

|            |                       |        |                                           |
|------------|-----------------------|--------|-------------------------------------------|
| Model year | 2010                  | Engine | 3.5 L, 6 cylinders                        |
| Make       | Toyota                | Fuel   | Gasoline                                  |
| Model      | Highlander            | Drive  | 4WD                                       |
| Trim       | Sports                | Maker  | TOYOTA MOTOR MANUFACTURING, INDIANA, INC. |
| Body       | Sport Utility Vehicle | Plant  | Princeton, Indiana, United States         |

## §2 OBLIGATIONS [2]

[cardog.app/tools/recalls/toyota/highlander/2010](https://cardog.app/tools/recalls/toyota/highlander/2010)

## 7 recalls listed by Transport Canada for this model year

### Electrical

2021723 24 Nov 2021

Issue: This recall is for certain block heater kits installed on certain vehicles or sold as accessories at Toyota or Lexus dealerships. On certain vehicles, the engine block heater cable may not have enough heat protection and could be damaged by high temperatures. If this happens, the cable could short circuit while plugged in, and cause the wiring to overheat or melt. Note: This recall only affects the following block heater/cord part numbers: C014003034 PK5A408J09 PU14000904 C014003151 PK5A408J13 PU14000905 C014000885 PK5A489J11 PU14000907 C014000888 PK5A489J22 PU14000909 C014000907 PK5A410H00 PU14000911 C014100904 PU14000900 PU14000913 C014100907 PU14000901 PU14003571 C014100911 PU14000902 PK5A489J14 PK5A408J05 PU14000903 Safety Risk: Engine block heater wiring that overheats or melts could create the risk of a fire. Corrective Actions: Toyota recommends that you should stop using the engine block heater immediately. Toyota will notify owners by mail and instruct you to take your vehicle to a dealer to disable the engine block heater. For some vehicles, the corrective actions for this recall are under development. For others, a new engine block heater cannot be installed, and the owner will receive a refund of the purchase price of the engine block heater.

### Electrical

2015493 21 Oct 2015

On certain vehicles, inconsistent application of grease during the manufacturing process could cause the driver's side power window master switch to stick or become inoperative due to electrical contact point wear. This could cause debris to accumulate between the contact points, potentially resulting in an electrical short circuit. If a short circuit occurs, the switch assembly may overheat, produce smoke, melt and/or potentially lead to a fire causing injury and/or property damage. Correction: Dealers will inspect the driver's power window master switch and apply a specialized grease that inhibits heat build-up, or replace the power window master switch circuit board, as necessary. Note: This is an expansion of recall 2012-338.



**Airbag**

2014124 9 Apr 2014

On certain vehicles, electrical circuitry in the steering wheel assembly may become damaged. As a result, the driver's airbag may not function as intended, causing the instrument panel airbag warning lamp to illuminate. Failure of the driver's airbag to deploy during a crash (where deployment is warranted) could increase the risk of injury to the seat occupant. Correction: Dealers will replace the spiral cable assembly.

**Other**

2013296 4 Sep 2013

On certain vehicles, a control board for the Intelligent Power Module (IPM), part of the hybrid system inverter assembly, could fail while the vehicle is underway. This could cause various warning lamps, including the malfunction indicator lamp, slip indicator lamp, brake system warning lamp, and master warning lamp, to illuminate on the instrument panel. If this occurred, in most cases, the vehicle would enter fail-safe driving mode, resulting in reduced motive power in which the vehicle could still be driven for short distances. In some instances, the fuse of the power supply circuit could blow, causing the hybrid system to stop functioning. The resultant loss of vehicle propulsion, in conjunction with traffic and road conditions, and the driver's reactions, could increase the risk of a crash causing property damage and/or personal injury. Correction: Dealers will inspect and, if necessary, replace the Intelligent Power Module.

**Accessories**

2010124 19 Apr 2010

On certain vehicles, if the Toyota optional accessory "tray-type" floor mat is not secured by the retaining hooks, or if it is placed on top of an existing floor mat, the "tray-type" floor mat could move forward and interfere with the accelerator pedal. This could result in a crash causing property damage, personal injury or death. Correction: The manufacturer will notify owners to remove the "tray-type" floor mat and provide instructions on how to obtain a reimbursement.

**Other**

2010012 22 Jan 2010

On certain vehicles, accelerator pedal movement may become rough, slow to return, or the pedal may stick in a depressed position. This could result in a loss of throttle control and a vehicle crash, causing property damage, personal injury or death. Correction: Dealers will install a steel reinforcement bar to the accelerator pedal assembly. With this reinforcement in place, the excess friction that can cause the pedal to stick is eliminated.


1 more on the model-year record, [cardog.app/tools/recalls/toyota/highlander/2010](https://cardog.app/tools/recalls/toyota/highlander/2010)

Listed for the model year, not checked against your VIN. Toyota confirms which apply.  
Check your VIN with Toyota Canada or call a Toyota dealer with your VIN.  
[www.toyota.ca/en/owners/recalls/](https://www.toyota.ca/en/owners/recalls/)

United States: 11 NHTSA records for this model year, kept apart from the Canadian listing.<sup>[3]</sup>

**§3 VALUE** <sup>[4]</sup>

This car asks \$12,417<sup>[5]</sup>, \$1,759 over the median of \$10,658<sup>[4]</sup>.



|             |                    |
|-------------|--------------------|
| Lowest ask  | \$6,999            |
| Middle half | \$8,425 – \$13,438 |
| Median ask  | \$10,658           |
| This car    | \$12,417           |

Same model year · 4 live listings · as of 27 Oct 2026

**OTHER 2010 TOYOTA HIGHLANDER LISTINGS** <sup>[5]</sup>

|                              |          |
|------------------------------|----------|
| Brampton, ON · 188,830 km    | \$8,900  |
| Hamilton, ON · 144,112 km    | \$16,500 |
| Scarborough, ON · 390,000 km | \$6,999  |



## §4 EVENTS

|             |                                                                                                |
|-------------|------------------------------------------------------------------------------------------------|
| 2010        | Model year 2010 <sup>[1]</sup><br>Assembly plant Princeton, Indiana, United States             |
| 7 Oct 2009  | Transport Canada recall 2009290 <sup>[2]</sup><br>Issued for the model year · Other            |
| 22 Jan 2010 | Transport Canada recall 2010012 <sup>[2]</sup><br>Issued for the model year · Other            |
| 19 Apr 2010 | Transport Canada recall 2010124 <sup>[2]</sup><br>Issued for the model year · Accessories      |
| 4 Sep 2013  | Transport Canada recall 2013296 <sup>[2]</sup><br>Issued for the model year · Other            |
| 9 Apr 2014  | Transport Canada recall 2014124 <sup>[2]</sup><br>Issued for the model year · Airbag           |
| 21 Oct 2015 | Transport Canada recall 2015493 <sup>[2]</sup><br>Issued for the model year · Electrical       |
| 24 Nov 2021 | Transport Canada recall 2021723 <sup>[2]</sup><br>Issued for the model year · Electrical       |
| 19 Jul 2026 | Listed for sale, Calgary, AB <sup>[5]</sup><br>Tower Chrysler Dodge Jeep Ram · asking \$12,417 |
| 27 Oct 2026 | Listing last updated <sup>[5]</sup><br>asking \$12,417                                         |

## §5 DOCUMENTS

Window sticker      We have not collected this label yet.

## SOURCES

- |                                                                     |                                                                              |
|---------------------------------------------------------------------|------------------------------------------------------------------------------|
| [1] Cardog identity register, decoded from the VIN                  | [4] Cardog market quote, same model year, 4 live listings, as of 27 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year     | [5] Live public dealer listings on Cardog, as of 27 Oct 2026                 |
| [3] NHTSA recall records (United States), listed for the model year |                                                                              |

## STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

