

Register entry, as of 28 October 2026

Listed for sale

Record ID 69c30905250e

2017 Toyota Tacoma SR/SR5/TRD Off Road/TRD Sport/TRD Pro

3.5 L, 6 cylinders · 4WD · Pickup · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

5TF **CZ5AN** **0** **H** **X** **121687**

WMI 1-3

Toyota Motor Manufacturi...

DESCRIPTOR 4-8

Tacoma · 3.5 L

CHECK 9

Verified

YEAR 10

2017

PLANT 11

San Antonio

SERIAL 12-17

Build sequence

§1 IDENTITY [1]

Model year	2017	Engine	3.5 L, 6 cylinders
Make	Toyota	Fuel	Gasoline
Model	Tacoma	Drive	4WD
Trim	SR/SR5/TRD Off Road/TRD Sport/TRD Pro	Maker	TOYOTA MOTOR MANUFACTURING, TEXAS, INC.
Body	Pickup	Plant	San Antonio, Texas, United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/toyota/tacoma/2017

5 recalls listed by Transport Canada for this model year

Electrical

2021723 24 Nov 2021

Issue: This recall is for certain block heater kits installed on certain vehicles or sold as accessories at Toyota or Lexus dealerships. On certain vehicles, the engine block heater cable may not have enough heat protection and could be damaged by high temperatures. If this happens, the cable could short circuit while plugged in, and cause the wiring to overheat or melt. Note: This recall only affects the following block heater/cord part numbers: C014003034 PK5A408J09 PU14000904 C014003151 PK5A408J13 PU14000905 C014000885 PK5A489J11 PU14000907 C014000888 PK5A489J22 PU14000909 C014000907 PK5A410H00 PU14000911 C014100904 PU14000900 PU14000913 C014100907 PU14000901 PU14003571 C014100911 PU14000902 PK5A489J14 PK5A408J05 PU14000903 Safety Risk: Engine block heater wiring that overheats or melts could create the risk of a fire. Corrective Actions: Toyota recommends that you should stop using the engine block heater immediately. Toyota will notify owners by mail and instruct you to take your vehicle to a dealer to disable the engine block heater. For some vehicles, the corrective actions for this recall are under development. For others, a new engine block heater cannot be installed, and the owner will receive a refund of the purchase price of the engine block heater.

Fuel system

2020514 28 Oct 2020

Issue: On certain vehicles, the low-pressure fuel pump could fail. If this happens, then engine may run rough or may not start and the check engine light may turn on. This could also result in a sudden loss of engine power while driving. Note: This recall is an expansion of recalls SRC R95/SRC R96 and SRC RA2/SRC RA3 (Transport Canada Recall Numbers 2020-005 and 2020-088). Safety Risk: A sudden loss of engine power could increase the risk of a crash. Corrective Actions: The company will notify owners by mail and instruct you to take your vehicle to a dealer to replace the fuel pump.



Brakes

2018155 3 Apr 2018

On certain vehicles, an oil passage in the rotor of the vacuum pump may not have been machined properly and could result in oil not being distributed throughout the pump. This could lead to the illumination of a warning light and message, an audible tone, and a sudden loss of braking assist, which could increase stopping distances and increase the risk of a crash causing injury and/or damage to property. Correction: Dealers will replace the vacuum pump with a new one.

Electrical

2017363 20 Jul 2017

On certain vehicles, the electrical power cords of some dealer installed block heaters may have been improperly manufactured, causing the wires to contact each other, resulting in a short circuit. A short circuit could lead to a fire which would increase the risk of injury and/or damage to property. Correction: For vehicles where the subject block heater was approved for installation, the dealer will replace the block heater assembly with a new one of an improved design. For vehicles where the subject block heater was not approved for installation, dealers will remove the block heater assembly. In the interim, until the remedy can be performed, dealers will cut the plug end from the block heater cord to disable the block heater's operation.

Powertrain

2017231 27 Apr 2017

On certain vehicles, the seal between the rear differential and the axle housing could degrade due to contact variation. This could result in leaking differential oil. If the vehicle is operated in this condition, damage to the differential could occur, and could potentially result in noise, reduced motive power and rear axle lockup. These issues could increase the risk of a crash causing injury and/or damage to property. Correction: Dealers will inspect the rear differential for leaks. If no leaks are found, fastening nuts will be re-tightened. If leaks are found, the differential gasket will be replaced, and new differential fastening nuts installed. Note: This applies to vehicles equipped with automatic transmission and non-locking differentials only.

Listed for the model year, not checked against your VIN. Toyota confirms which apply.


Check your VIN with Toyota Canada or call a Toyota dealer with your VIN.

www.toyota.ca/en/owners/recalls/

United States: 5 NHTSA records for this model year, kept apart from the Canadian listing.^[3]

§3 VALUE ^[4]

This car asks \$42,999^[5], \$7,999 over the median of \$35,000^[4].



Lowest ask	\$24,895
Middle half	\$30,893 – \$37,592
Median ask	\$35,000
This car	\$42,999

Same configuration · 13 live listings · as of 28 Oct 2026

OTHER 2017 TOYOTA TACOMA LISTINGS ^[5]

Leamington, ON · 130,499 km	\$35,000
Milton, ON · 234,050 km	\$23,995
Essex, ON · 130,499 km	\$35,000
Moncton, NB · 147,586 km	\$30,989
Sault Ste. Marie, ON · 203,852 km	\$27,995
Sault Ste. Marie, ON · 74,548 km	\$35,995



§4 EVENTS

2017	Model year 2017 ^[1] Assembly plant San Antonio, Texas, United States
27 Apr 2017	Transport Canada recall 2017231 ^[2] Issued for the model year · Powertrain
20 Jul 2017	Transport Canada recall 2017363 ^[2] Issued for the model year · Electrical
3 Apr 2018	Transport Canada recall 2018155 ^[2] Issued for the model year · Brakes
28 Oct 2020	Transport Canada recall 2020514 ^[2] Issued for the model year · Fuel system
24 Nov 2021	Transport Canada recall 2021723 ^[2] Issued for the model year · Electrical
27 Oct 2026	Listed for sale, St. Catharines, ON ^[5] Performance Toyota · asking \$42,999

§5 DOCUMENTS

Window sticker We have not collected this label yet.

SOURCES

- | | |
|---|--|
| [1] Cardog identity register, decoded from the VIN | [4] Cardog market quote, same configuration, 13 live listings, as of 28 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year | [5] Live public dealer listings on Cardog, as of 28 Oct 2026 |
| [3] NHTSA recall records (United States), listed for the model year | |

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

