

Register entry, as of 28 October 2026

Listed for sale

Record ID c928e99e88cb

2009 BMW X6 xDrive35i

3.0 L, 6 cylinders · AWD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

5UX FG435 4 9 L 224158

WMI 1-3

Bmw Manufacturer Corpor...

DESCRIPTOR 4-8

X6 · 3.0 L

CHECK 9

Verified

YEAR 10

2009

PLANT 11

United States

SERIAL 12-17

Build sequence

§1 IDENTITY [1]

Model year	2009	Engine	3.0 L, 6 cylinders
Make	BMW	Fuel	Gasoline
Model	X6	Drive	AWD
Trim	xDrive35i	Maker	BMW MANUFACTURER CORPORATION / BMW NORTH AMERICA
Body	Sport Utility Vehicle	Plant	United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/bmw/x6/2009

9 recalls listed by Transport Canada for this model year

Label	2024544 15 Aug 2024
Issue: On certain vehicles, the tire and loading information label does not list that there is no spare tire in both official languages. The label reads as "NONE" when it should read as "NONE / AUCUN". Canadian regulations require the information to be listed on the label in both English and French. Safety Risk: This error does not affect vehicle safety. Corrective Actions: This is not a recall. The company has corrected the tire and loading information label for all new vehicles.	
Airbag	2019018 15 Jan 2019
Issue: On certain vehicles, long-term exposure to high absolute humidity and temperature, combined with high temperature cycling, may eventually degrade the propellant contained in the passenger-front airbag. This could cause the airbag to deploy with more force than normal. If the airbag inflator ruptures, fragments could be propelled toward vehicle occupants or cause damage to the airbag assembly, preventing its proper function. Safety Risk: If the vehicle is involved in a crash requiring an airbag deployment, the airbag inflator could rupture and create a risk of injury. Corrective Action: Owners will be notified by mail and instructed to take their vehicle to a dealer to have the passenger-front airbag module replaced. Note: The Canadian climate results in the propellant degrading slowly. This recall is being conducted as a precaution to address future risk. It is expected that all airbag inflators will be replaced before their function would be affected.	
Electrical	2018195 19 Apr 2018
On certain vehicles, the auxiliary water pump (which cools the turbocharger after the engine is turned OFF) can overheat and fail. This could result in a vehicle fire causing injury and/or damage to property. Correction: Dealers will replace the auxiliary water pump. Note: Owners are advised to park the vehicle outdoors until the remedy is applied. Additional note: This is an expansion of recalls 2011-376 and 2012-008.	



Airbag

2018018 9 Jan 2018

On certain vehicles, long-term exposure to high absolute humidity and temperature, combined with high temperature cycling, could eventually degrade the propellant contained in the passenger frontal airbag. This could cause the airbag to deploy with more force than normal. As a result, if the vehicle were involved in a collision that warrants airbag deployment, fragments could be propelled toward vehicle occupants, and the airbag assembly could be damaged, preventing proper function. These issues could increase the risk of injury. Correction: Dealers will replace the passenger frontal airbag module. Note: Canadian climate results in the propellant degrading slowly. The recall is being conducted as a precaution to address future risk, and is expected to replace airbag inflators before their function would be affected.

Fuel system

2016505 13 Oct 2016

On certain vehicles, the wires going to the in-tank fuel pump may not have been crimped correctly. An incorrect crimp could increase the resistance of the circuit which could cause the contact pin to heat and melt the surrounding plastic. This could potentially cause the fuel pump to stop working causing the vehicle to stall without warning, increasing the risk of a crash causing injury and/or damage to property. Also, in a very rare case, a fuel leak combined with an external ignition source, could increase the risk of fire causing injury and/or damage to property. Correction: Dealers will replace the fuel delivery module.

Airbag

2016142 31 Mar 2016

On certain vehicles, the driver frontal airbag inflator could produce excessive internal pressure during airbag deployment. Increased pressure may cause the inflator to rupture, which could allow fragments to be propelled toward vehicle occupants, increasing the risk of injury. This could also damage the airbag module, which could prevent proper deployment. Failure of the airbag to fully deploy during a crash (where deployment is warranted) could increase the risk of personal injury to the seat occupant. Correction: Dealers will replace the front driver air bag inflator or air bag module, depending on the vehicle model.


3 more on the model-year record, cardog.app/tools/recalls/bmw/x6/2009

Listed for the model year, not checked against your VIN. BMW confirms which apply.
Check your VIN with BMW Canada or call a BMW dealer with your VIN.
crm.bmw.ca/en-CA/VehicleRecall

United States: 10 NHTSA records for this model year, kept apart from the Canadian listing.^[3]

§3 VALUE ^[4]

This car asks \$6,990^[5], the median^[4].



Same model year · 1 live listings · as of 28 Oct 2026

§4 EVENTS

2009

Model year 2009^[1]

Assembly plant United States

8 Jul 2009

Transport Canada recall 2009204^[2]

Issued for the model year · Brakes



21 Oct 2011	Transport Canada recall 2011376 ^[2] Issued for the model year · Electrical
12 Apr 2012	Transport Canada recall 2012129 ^[2] Issued for the model year · Label
31 Mar 2016	Transport Canada recall 2016142 ^[2] Issued for the model year · Airbag
13 Oct 2016	Transport Canada recall 2016505 ^[2] Issued for the model year · Fuel system
9 Jan 2018	Transport Canada recall 2018018 ^[2] Issued for the model year · Airbag
19 Apr 2018	Transport Canada recall 2018195 ^[2] Issued for the model year · Electrical
15 Jan 2019	Transport Canada recall 2019018 ^[2] Issued for the model year · Airbag
15 Aug 2024	Transport Canada recall 2024544 ^[2] Issued for the model year · Label
26 Oct 2026	Listed for sale, Quebec, QC ^[5] platinumauto.ca · asking \$6,990
27 Oct 2026	Listing last updated ^[5] asking \$6,990

§5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.

SOURCES

- | | |
|---|--|
| [1] Cardog identity register, decoded from the VIN | [4] Cardog market quote, same model year, 1 live listings, as of 28 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year | [5] Live public dealer listings on Cardog, as of 28 Oct 2026 |
| [3] NHTSA recall records (United States), listed for the model year | |

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

