

Register entry, as of 29 October 2026

Listed for sale

Record ID 707886b9bfd6

2013 Hyundai Santa Fe Sport Sport Popular / Sport Leather / Sport Tech / Sport Turbo / Sport Turbo leather

2.0 L, 4 cylinders · 4x2 · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

5XY **ZU3LA** **7** **D** **G** **012034**

WMI 1-3

Hyundai · KIA GEORGIA, INC

DESCRIPTOR 4-8

Santa Fe Sport · 2.0 L

CHECK 9

Verified

YEAR 10

2013

PLANT 11

Georgia

SERIAL 12-17

Build sequence

§1 IDENTITY [1]

Model year	2013	Engine	2.0 L, 4 cylinders
Make	Hyundai	Fuel	Gasoline
Model	Santa Fe Sport	Drive	4x2
Trim	Sport Popular / Sport Leather / Sport Tech / Sport Turbo / Sport Turbo leather	Maker	KIA GEORGIA, INC
Body	Sport Utility Vehicle	Plant	Georgia, United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/hyundai/santa-fe-sport/2013

15 recalls listed by Transport Canada for this model year

Label 2024552 23 Sep 2024

Issue: On certain vehicles, the compliance label may be missing information in French. The words listed on the label for "Tires", "Rims", "Front" and "Rear" appear in English only, when they should be listed as "Tires/Pneus", "Rims/Jantes", "Front/Avant" and "Rear/Arriere". Canadian regulations require this information to be listed on the label in both English and French. Safety Risk: These small errors do not affect vehicle safety. Corrective Actions: This is not a recall. The company has corrected the compliance label for all new vehicles.

Brakes 2024080 8 Feb 2024

Issue: On certain vehicles, brake fluid could leak into the control module for the antilock brake system (ABS) and cause it to short circuit. Note: This recall replaces recall R0246 (Transport Canada recall number 2023-527). For the Sonata model, only the Sonata Hybrid model is affected by this recall. Safety Risk: A short circuit could create a fire risk, even while the vehicle is parked and turned off. Corrective Actions: Hyundai will notify owners by mail and advise you to take your vehicle to a dealership to replace the fuse for the ABS module. Hyundai recommends that you should park your vehicle outdoors and away from other vehicles or structures until the recall repairs have been completed.



Brakes

2023527 22 Sep 2023

This recall was replaced by Transport Canada Recall No. 2024-080. Issue: On certain vehicles, brake fluid could leak into the control module for the antilock brake system (ABS) and cause it to short circuit. Safety Risk: A short circuit could create a fire risk, even while the vehicle is parked and turned off. Corrective Actions: Hyundai will notify owners by mail and advise you to take your vehicle to a dealership to replace the fuse for the ABS module. Hyundai recommends that you should park your vehicle outdoors and away from other vehicles or structures until the recall repairs have been completed.

Electrical

2022659 15 Nov 2022

Issue: On certain vehicles, the rear parking assist sensors (mounted in the rear bumper) could short circuit. Note: This recall replaces Transport Canada recall 2022-118. Vehicles that were already repaired under Hyundai recall R0212 don't require this repair. Safety Risk: A short circuit could create a fire risk. Corrective Actions: Hyundai will notify owners by mail and instruct you to bring your vehicle to a dealership to replace the rear parking assist sensor fuse and any defective sensors. Hyundai recommends that if the instrument cluster does not work, the transmission shifter is stuck in park, or if you see melted plastic on the rear bumper, you should park the vehicle outside and contact a Hyundai dealer.

Accessories

2022118 15 Mar 2022

This recall was replaced by Transport Canada Recall No. 2022-659. Issue: On certain vehicles, the rear parking assist sensors (mounted in the rear bumper) could short circuit. Note: Vehicles repaired under Hyundai recall R0078 (Transport Canada Recall No. 2013-067) also require this repair. Safety Risk: A short circuit could create a fire risk. Corrective Actions: Hyundai will notify owners by mail and instruct you to bring your vehicle to a dealership to replace the rear parking assist sensor fuse and any defective sensors. Hyundai recommends that if the instrument cluster does not work, the transmission shifter is stuck in park, or if you see melted plastic on the rear bumper, you should park the vehicle outside and contact a Hyundai dealer.

Brakes

2021253 28 Apr 2021

Issue: On certain vehicles, brake fluid can enter the brake Hydraulic Electronic Control Unit (HECU) and cause a short circuit. Note: This recall replaces R0172 (Transport Canada recall 2020-410). Vehicles that were repaired under that recall also require this repair. Safety Risk: A short circuit could create a fire risk. Corrective Actions: Hyundai will notify owners by mail and instruct you to take your vehicle to a dealer to have the HECU inspected and replaced if necessary. The dealer will also replace the ABS multi-fuse. Hyundai recommends that you should park your vehicle outdoors, and away from other vehicles or structures until the recall repairs have been completed.

9 more on the model-year record, cardog.app/tools/recalls/hyundai/santa-fe-sport/2013

Listed for the model year, not checked against your VIN. Hyundai confirms which apply.

Check your VIN with Hyundai Canada or call a Hyundai dealer with your VIN.

www.hyundaicanada.com/en/owners-section/recalls

United States: 6 NHTSA records for this model year, kept apart from the Canadian listing.^[3]

§3 VALUE

No priced market quote for this vehicle yet.

OTHER 2013 HYUNDAI SANTA FE SPORT LISTINGS ^[4]

Scarborough, ON · 185,764 km	\$9,888
Leduc, AB · 171,572 km	\$10,987
Ottawa, ON · 222,570 km	\$7,995

§4 EVENTS

2013

Model year 2013^[1]

Assembly plant Georgia, United States



28 Feb 2013	Transport Canada recall 2013067 ^[2] Issued for the model year · Accessories
6 Apr 2017	Transport Canada recall 2017197 ^[2] Issued for the model year · Engine
8 Jun 2017	Transport Canada recall 2017297 ^[2] Issued for the model year · Structure
10 Jan 2019	Transport Canada recall 2019012 ^[2] Issued for the model year · Engine
11 Mar 2019	Transport Canada recall 2019130 ^[2] Issued for the model year · Engine
21 Aug 2019	Transport Canada recall 2019420 ^[2] Issued for the model year · Other
16 Dec 2019	Transport Canada recall 2019640 ^[2] Issued for the model year · Engine
28 Feb 2020	Transport Canada recall 2020091 ^[2] Issued for the model year · Electrical
1 Sep 2020	Transport Canada recall 2020410 ^[2] Issued for the model year · Brakes
28 Apr 2021	Transport Canada recall 2021253 ^[2] Issued for the model year · Brakes
15 Mar 2022	Transport Canada recall 2022118 ^[2] Issued for the model year · Accessories
15 Nov 2022	Transport Canada recall 2022659 ^[2] Issued for the model year · Electrical
22 Sep 2023	Transport Canada recall 2023527 ^[2] Issued for the model year · Brakes
8 Feb 2024	Transport Canada recall 2024080 ^[2] Issued for the model year · Brakes
23 Sep 2024	Transport Canada recall 2024552 ^[2] Issued for the model year · Label
25 Oct 2026	Listed for sale, Sooke, BC ^[4] 4 Wheel Deals · asking \$6,998
28 Oct 2026	Listing last updated ^[4] asking \$6,998

§5 DOCUMENTS

Window sticker We have not collected this label yet.



SOURCES

- | | |
|---|---|
| [1] Cardog identity register, decoded from the VIN | [3] NHTSA recall records (United States), listed for the model year |
| [2] Transport Canada recall database, listed for the model year | [4] Live public dealer listings on Cardog, as of 29 Oct 2026 |

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

