

Register entry, as of 26 October 2026

Listed for sale

Record ID 5591b055d5a6

2009 Pontiac Vibe

2.4 L, 4 cylinders · FWD · Hatchback · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

5Y2 SP670 X 9 Z 417664

WMI 1-3

Pontiac · New United Motor...

DESCRIPTOR 4-8

Vibe · 2.4 L

CHECK 9

Verified

YEAR 10

2009

PLANT 11

Fremont

SERIAL 12-17

Build sequence

§1 IDENTITY [1]

Model year	2009	Engine	2.4 L, 4 cylinders
Make	Pontiac	Fuel	Gasoline
Model	Vibe	Drive	FWD
Trim	Not in the decode	Maker	New United Motor Manufacturing, Inc.
Body	Hatchback	Plant	Fremont, California, United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/pontiac/vibe/2009

8 recalls listed by Transport Canada for this model year

Airbag 2018016 9 Jan 2018

On certain vehicles, long-term exposure to high absolute humidity and temperature, combined with high temperature cycling, could eventually degrade the propellant contained in the passenger frontal airbag. This could cause the airbag to deploy with more force than normal. As a result, if the vehicle were involved in a collision that warrants airbag deployment, fragments could be propelled toward vehicle occupants, and the airbag assembly could be damaged, preventing proper function. These issues could increase the risk of injury. Correction: Depending on the vehicle model, dealers will either replace the passenger frontal airbag inflator, or replace the airbag assembly. Note: Canadian climate results in the propellant degrading slowly. The recall is being conducted as a precaution to address future risk, and is expected to replace airbag inflators before their function would be affected. Additional note: The 2010 model year vehicles involved in this campaign have been identified as having once being registered in "Zone B" in the USA.

Airbag 2017134 10 Mar 2017

General Motors Canada is conducting a voluntary Safety Improvement Program involving the passenger airbag inflator in certain vehicles that were originally sold or ever registered in certain high humidity areas of the United States equipped with Takata airbags. General Motors will replace the passenger inflator on affected vehicles, depending on the vehicle involved. Owners who believe their vehicles may have been originally purchased or registered in the states of New Jersey, Delaware, District of Columbia, Maryland, Pennsylvania, Ohio, Indiana, Illinois, Virginia, West Virginia, Kentucky, Missouri, Nebraska, Kansas, Oklahoma, Arkansas, Tennessee, North Carolina, Nevada, Arizona, New Mexico, California, Texas, Louisiana, Mississippi, Alabama, Georgia, South Carolina, Florida, Hawaii, Puerto Rico or the U.S. Virgin Islands should contact a General Motors dealer. This action is not being conducted under the requirements of the Motor Vehicle Safety Act. Note: This Safety Improvement Campaign is superseded by recall 2018-016 (GM Recall 17476). Please see <http://www.gm.com/saf-sec-sur/7/VRDB-BDRV/search-recherche/detail.aspx?lang=eng&rn=2018016> for more information.



Electrical

2015496 22 Oct 2015

On certain vehicles, inconsistent application of grease during the manufacturing process could cause the driver's side power window master switch to stick or become inoperative due to electrical contact point wear. This could cause debris to accumulate between the contact points, potentially resulting in an electrical short circuit. If a short circuit occurs, the switch assembly may overheat, produce smoke, melt and/or potentially lead to a fire causing injury and/or property damage. Correction: Dealers will inspect the driver's power window master switch and apply a specialized grease that inhibits heat build-up, or replace the power window master switch circuit board, as necessary. Note: This is an expansion of recall 2012-342.

Airbag

2014145 22 Apr 2014

On certain vehicles, electrical circuitry in the steering wheel assembly may become damaged. As a result, the driver's airbag may not function as intended, causing the instrument panel airbag warning lamp to illuminate. Failure of the driver's airbag to deploy during a crash (where deployment is warranted) could increase the risk of injury to the seat occupant. Correction: Dealers will replace the spiral cable assembly.

Electrical

2012342 10 Oct 2012

On certain vehicles, due to improperly applied grease, the driver's side power window master switch could stick or become inoperative. If attempts are made to lubricate the switch, the switch assembly could overheat and melt. A melting switch may produce smoke and potentially lead to a fire causing property damage and/or personal injury. Correction: Dealers will inspect the driver's power window master switch and apply a specialized grease that inhibits heat build-up, or replace the power window master switch circuit board, as necessary.

Other

2010034 9 Feb 2010

On certain vehicles, the accelerator pedal may become stuck in the wide open position due to an unsecured or incompatible driver's floor mat. A stuck open accelerator pedal may result in very high vehicle speeds and make it difficult to stop the vehicle, which could cause a crash, serious injury or death. Correction: Owners will be notified by first class mail to remove any unsecured driver's floor mat until further notice by the manufacturer.

2 more on the model-year record, cardog.app/tools/recalls/pontiac/vibe/2009

Listed for the model year, not checked against your VIN. Pontiac confirms which apply.
Check your VIN with GM Canada or call a Pontiac dealer with your VIN.
experience.gm.ca/en/ownercenter/recalls

United States: 9 NHTSA records for this model year, kept apart from the Canadian listing.^[3]

§3 VALUE [4]

This car asks \$6,995^[5], \$1,500 over the median of \$5,495^[4].



Lowest ask	\$3,200
Middle half	\$3,796 – \$7,994
Median ask	\$5,495
This car	\$6,995

Same model year · 4 live listings · as of 26 Oct 2026

OTHER 2009 PONTIAC VIBE LISTINGS [5]

Beloeil, QC · 226,491 km	\$3,200
London, ON · 251,532 km	\$3,995
Truro, NS · 265,925 km	\$10,991



§4 EVENTS

2009	Model year 2009 ^[1] Assembly plant Fremont, California, United States
27 Aug 2009	Transport Canada recall 2009252 ^[2] Issued for the model year · Brakes
22 Jan 2010	Transport Canada recall 2010015 ^[2] Issued for the model year · Engine
9 Feb 2010	Transport Canada recall 2010034 ^[2] Issued for the model year · Other
10 Oct 2012	Transport Canada recall 2012342 ^[2] Issued for the model year · Electrical
22 Apr 2014	Transport Canada recall 2014145 ^[2] Issued for the model year · Airbag
22 Oct 2015	Transport Canada recall 2015496 ^[2] Issued for the model year · Electrical
10 Mar 2017	Transport Canada recall 2017134 ^[2] Issued for the model year · Airbag
9 Jan 2018	Transport Canada recall 2018016 ^[2] Issued for the model year · Airbag
25 Oct 2026	Listed for sale, London, ON ^[5] Tiger Auto Sales Ltd. · asking \$6,995
26 Oct 2026	Listing last updated ^[5] asking \$6,995

§5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.

SOURCES

- | | |
|---|--|
| [1] Cardog identity register, decoded from the VIN | [4] Cardog market quote, same model year, 4 live listings, as of 26 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year | [5] Live public dealer listings on Cardog, as of 26 Oct 2026 |
| [3] NHTSA recall records (United States), listed for the model year | |

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

