

Register entry, as of 27 October 2026

Listed for sale

Record ID c61411b93a2d

2025 RIVIAN R1S Adventure

AWD · Sport Utility Vehicle · Electric

VEHICLE IDENTIFICATION NUMBER [1]

7PD SGBBA 3 S N 061377

WMI 1-3

Rivian Automotive LLC

DESCRIPTOR 4-8

R1S

CHECK 9

Computes

YEAR 10

2025

PLANT 11

Normal

SERIAL 12-17

Build sequence

§1 IDENTITY [1]

Model year	2025	Engine	Not in the decode
Make	RIVIAN	Fuel	Electric
Model	R1S	Drive	AWD
Trim	Adventure	Maker	RIVIAN AUTOMOTIVE LLC
Body	Sport Utility Vehicle	Plant	Normal, Illinois, United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/rivian/r1s/2025

6 recalls listed by Transport Canada for this model year

Visual system

2026443 17 Sep 2026

Issue: Under certain conditions, a software problem could cause the rearview camera image to be blocked. Canadian regulations require the rearview image to display while the transmission is in reverse gear. Safety Risk: A rearview camera image that doesn't display could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: Rivian will notify owners by email. Rivian has released an over-the-air software update to fix this problem. There is no further action required if your vehicle has software release 2026.23.0 or a later release.

Seats and restraints

2026009 15 Jan 2026

Issue: On certain vehicles, the second-row outboard seat belt retractor(s) may not have been installed properly. As a result, the seat belts could loosen or detach in a crash. Safety Risk: A seat belt that detaches in a crash could increase the risk of injury. Corrective Actions: To reduce the safety risk, Rivian recommends that you shouldn't transport passengers in the second-row outboard seats until the recall repairs are completed. Rivian will notify owners by email and advise you to take your vehicle to a Rivian service center to inspect and, if necessary, secure the seat belt retractor(s).

Suspension

2026002 5 Jan 2026

Issue: On certain vehicles, the rear suspension toe link(s) may not have been properly reinstalled after service. As a result, the toe link(s) could become loose or separate. If this happens, there could be reduced vehicle stability. Safety Risk: Reduced vehicle stability could cause a loss of control and increase the risk of a crash. Corrective Actions: Rivian will notify owners by email and advise you to take your vehicle to a Rivian service center to inspect and, if necessary, replace the rear suspension toe link bolt(s).



Lights and instruments

2025314 11 Jun 2025

Issue: On certain vehicles, the front turn signal lamps may not have been manufactured properly. As a result, one or both front turn signals may not work, and the vehicles may not meet certain requirement of Canadian regulations. Note: This problem would cause a "Turn signal lights not working. Service it soon." message to be displayed. Safety Risk: Front turn signals that don't work may cause a person not to recognize when a driver intends to turn or change lanes and could increase the risk of a crash. Corrective Action: Rivian will notify owners by email and advise you to take your vehicle to a Rivian service center to inspect and, if necessary, replace the front turn signal lamps.

Lights and instruments

2025073 13 Feb 2025

Issue: On certain vehicles, the headlamps may not have been manufactured properly. As a result, under certain conditions, the headlamps may not turn on and cause the vehicles not to meet certain requirements of Canadian regulations. Safety Risk: Headlamps that don't work properly can reduce visibility and could increase the risk of a crash. Corrective Actions: Rivian will notify owners by email and advise you to take your vehicle to a Rivian service center to replace the headlamp control module.

Lights and instruments

2024672 4 Nov 2024

Issue: On certain vehicles, there could be a problem with the "car costume" feature included in an over-the-air software update. Under certain conditions, using the feature could cause various exterior lights not to work properly. Safety Risk: Exterior lights that don't work properly could make the vehicle less visible to others and increase the risk of a crash. Corrective Actions: To reduce the safety risk, Rivian has released an over-the-air software update to disable the feature and fix the issue. Rivian will notify affected owners by email. There is no further action required if your vehicle has software release 2024.39.31 or a later release.

Listed for the model year, not checked against your VIN. RIVIAN confirms which apply.
No online lookup from RIVIAN · call a RIVIAN dealer with your VIN.

United States: 11 NHTSA records for this model year, kept apart from the Canadian listing.^[3]

§3 VALUE ^[4]

This car asks \$126,950^[5], the median^[4].



Lowest ask	\$126,950
Middle half	\$126,950 – \$126,950
Median ask	\$126,950
This car	\$126,950

Same model year · 1 live listings · as of 27 Oct 2026

§4 EVENTS

2025	Model year 2025 ^[1] Assembly plant Normal, Illinois, United States
4 Nov 2024	Transport Canada recall 2024672 ^[2] Issued for the model year · Lights and instruments
13 Feb 2025	Transport Canada recall 2025073 ^[2] Issued for the model year · Lights and instruments
11 Jun 2025	Transport Canada recall 2025314 ^[2] Issued for the model year · Lights and instruments



5 Jan 2026	Transport Canada recall 2026002 ^[2] Issued for the model year · Suspension
15 Jan 2026	Transport Canada recall 2026009 ^[2] Issued for the model year · Seats and restraints
17 Sep 2026	Transport Canada recall 2026443 ^[2] Issued for the model year · Visual system
16 Oct 2026	Listed for sale, Oakville, ON ^[5] Shift Motors · asking \$126,950
26 Oct 2026	Listing last updated ^[5] asking \$126,950

§5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.

SOURCES

- | | |
|---|--|
| [1] Cardog identity register, decoded from the VIN | [4] Cardog market quote, same model year, 1 live listings, as of 27 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year | [5] Live public dealer listings on Cardog, as of 27 Oct 2026 |
| [3] NHTSA recall records (United States), listed for the model year | |

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

