

Register entry, as of 27 October 2026

Listed for sale

Record ID 3dd669ee584a

# 2009 Mitsubishi Lancer SportBack

2.4 L · 4x2 · Hatchback · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

**JA3** **AX88W** **X** **9** **U** **614419**

WMI 1-3

Mitsubishi Motors Corporat...

DESCRIPTOR 4-8

Lancer SportBack · 2.4 L

CHECK 9

Computes

YEAR 10

2009

PLANT 11

Mizushima

SERIAL 12-17

Build sequence

## §1 IDENTITY [1]

|            |                   |        |                                     |
|------------|-------------------|--------|-------------------------------------|
| Model year | 2009              | Engine | 2.4 L                               |
| Make       | Mitsubishi        | Fuel   | Gasoline                            |
| Model      | Lancer SportBack  | Drive  | 4x2                                 |
| Trim       | Not in the decode | Maker  | Mitsubishi Motors Corporation (MMC) |
| Body       | Hatchback         | Plant  | Mizushima, Japan                    |

## §2 OBLIGATIONS [2]

[cardog.app/tools/recalls/mitsubishi/lanacer-sportback/2009](https://cardog.app/tools/recalls/mitsubishi/lanacer-sportback/2009)

## 9 recalls listed by Transport Canada for this model year

|                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                     |         |             |
|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------|-------------|
| Structure                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                           | 2020216 | 15 May 2020 |
| <p>Issue: On certain vehicles, road salt can corrode the front cross-member (subframe). As a result, a lower control arm could eventually detach from the cross-member. This could cause a loss of vehicle control. Safety Risk: A loss of control can create the risk of a crash. Corrective Actions: Mitsubishi will notify owners by mail and instruct you to take your vehicle to a dealer to inspect the front cross-member (subframe). If no significant corrosion is found, the dealer will spray a sealing and anti-corrosion coating both inside and on the cross-member. If significant corrosion is found, the dealer will replace the cross-member.</p> |         |             |
| Visual system                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                       | 2018588 | 26 Oct 2018 |
| <p>On certain vehicles, water may drain from the windshield cowl area onto the front wiper link ball joint. Over time, this could result in corrosion and/or wear to the joint, which could result in the separation of the wiper link ball. If separation were to occur, the windshield wipers could become inoperative, which could limit the driver's visibility under certain operating conditions which may increase the risk of a crash causing injury and/or damage to property. Correction: Dealers will replace the wiper link rod with a countermeasure one, and will replace the wiper motor crank arm with a new one.</p>                               |         |             |
| Accessories                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                         | 2018054 | 26 Jan 2018 |
| <p>On certain vehicles, the sunroof may not have been bonded properly and could separate from the vehicle. This could pose a risk to other road users, increasing the risk of injury and/or damage to property. Correction: Dealers will replace the sunroof glass assembly.</p>                                                                                                                                                                                                                                                                                                                                                                                    |         |             |



**Electrical**

2018052 26 Jan 2018

On certain vehicles, the flange of the drive belt automatic tensioner may crack over time due to repetitive high load operations and stress concentration. This could cause the drive belt to detach, leading to battery depletion, which would result in a loss of motive power and a loss of power steering assist. These issues could increase the risk of a crash causing injury and/or damage to property. Correction: Dealers will replace the auto tensioner with a countermeasure unit.

**Airbag**

2016382 29 Jul 2016

On certain vehicles operated in areas of heavy road salt usage, a mixture of snow, water and road-salt solution may infiltrate between the front impact sensor and the bracket that attaches it to the vehicle. Over time, repeated freezing/thawing cycles could cause a crack to develop in the sensor case allowing water intrusion and short circuit of the sensor. In the event of a crash, this could result in delayed deployment of the driver and passenger front airbags which would increase the risk of injury. Correction: Dealers will inspect the front impact sensor and replace it if it is found to be cracked. An updated designed bracket and cover will also be installed.

**Heater and defroster**

2015166 17 Apr 2015

On certain vehicles, the blower motor may have been incorrectly manufactured. This could result in a premature failure of the blower motor which could affect the defroster performance resulting in reduced visibility, increasing the risk of a crash causing injury and/or damage to property. Correction: Dealers will replace blower motor and the power transistor as needed.


3 more on the model-year record, [cardog.app/tools/recalls/mitsubishi/lancer-sportback/2009](https://cardog.app/tools/recalls/mitsubishi/lancer-sportback/2009)

Listed for the model year, not checked against your VIN. Mitsubishi confirms which apply.  
Check your VIN with Mitsubishi Canada or call a Mitsubishi dealer with your VIN.  
[www.mitsubishi-motors.ca/en/owners/maintenance-service/mitsubishi-recalls](https://www.mitsubishi-motors.ca/en/owners/maintenance-service/mitsubishi-recalls)

United States: 2 NHTSA records for this model year, kept apart from the Canadian listing.<sup>[3]</sup>

**§3 VALUE** <sup>[4]</sup>

This car asks \$11,500<sup>[5]</sup>, the median<sup>[4]</sup>.



|             |                     |
|-------------|---------------------|
| Lowest ask  | \$11,500            |
| Middle half | \$11,500 – \$11,500 |
| Median ask  | \$11,500            |
| This car    | \$11,500            |

Same model year · 1 live listings · as of 27 Oct 2026

**§4 EVENTS**

|             |                                                                                                    |
|-------------|----------------------------------------------------------------------------------------------------|
| 2009        | Model year 2009 <sup>[1]</sup><br>Assembly plant Mizushima, Japan                                  |
| 9 Nov 2009  | Transport Canada recall 2009317 <sup>[2]</sup><br>Issued for the model year · Airbag               |
| 15 Sep 2014 | Transport Canada recall 2014397 <sup>[2]</sup><br>Issued for the model year · Engine               |
| 17 Apr 2015 | Transport Canada recall 2015166 <sup>[2]</sup><br>Issued for the model year · Heater and defroster |



|             |                                                                                                      |
|-------------|------------------------------------------------------------------------------------------------------|
| 17 Apr 2015 | Transport Canada recall 2015165 <sup>[2]</sup><br>Issued for the model year · Lights and instruments |
| 29 Jul 2016 | Transport Canada recall 2016382 <sup>[2]</sup><br>Issued for the model year · Airbag                 |
| 26 Jan 2018 | Transport Canada recall 2018054 <sup>[2]</sup><br>Issued for the model year · Accessories            |
| 26 Jan 2018 | Transport Canada recall 2018052 <sup>[2]</sup><br>Issued for the model year · Electrical             |
| 26 Oct 2018 | Transport Canada recall 2018588 <sup>[2]</sup><br>Issued for the model year · Visual system          |
| 15 May 2020 | Transport Canada recall 2020216 <sup>[2]</sup><br>Issued for the model year · Structure              |
| 25 Sep 2026 | Listed for sale, Kelowna, BC <sup>[5]</sup><br>Harmony Honda · asking \$11,500                       |
| 27 Oct 2026 | Listing last updated <sup>[5]</sup><br>asking \$11,500                                               |

## §5 DOCUMENTS

Window sticker      We have not collected this label yet.

## SOURCES

- |                                                                     |                                                                              |
|---------------------------------------------------------------------|------------------------------------------------------------------------------|
| [1] Cardog identity register, decoded from the VIN                  | [4] Cardog market quote, same model year, 1 live listings, as of 27 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year     | [5] Live public dealer listings on Cardog, as of 27 Oct 2026                 |
| [3] NHTSA recall records (United States), listed for the model year |                                                                              |

## STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

