

Register entry, as of 28 October 2026

Listed for sale

Record ID 68a14bb6e4ae

2013 Subaru XV CrossTrek Prm+AWP

2.0 L, 4 cylinders · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

JF2 GPACC 0 D H 200875

WMI 1-3

Subaru Corporation

DESCRIPTOR 4-8

XV CrossTrek · 2.0 L

CHECK 9

Computes

YEAR 10

2013

PLANT 11

Japan

SERIAL 12-17

Build sequence

§1 IDENTITY [1]

Model year	2013	Engine	2.0 L, 4 cylinders
Make	Subaru	Fuel	Gasoline
Model	XV CrossTrek	Drive	Not in the decode
Trim	Prm+AWP	Maker	SUBARU CORPORATION
Body	Sport Utility Vehicle	Plant	Japan

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/subaru/xv-crosstrek/2013

5 recalls listed by Transport Canada for this model year

Label	2024546 15 Aug 2024
Issue: On certain vehicles, the compliance label may be missing information in French. The words listed on the label for "Tires", "Rims", "Front" and "Rear" appear in English only, when they should be listed as "Tires/Pneus", "Rims/Jantes", "Front/Avant" and "Rear/Arriere". Canadian regulations require this information to be listed on the label in both English and French. Safety Risk: These small errors do not affect vehicle safety. Corrective Actions: This is not a recall. Subaru has corrected the compliance label for all new vehicles.	
Brakes	2019104 1 Mar 2019
Issue: On certain vehicles, the brake lamp switch could fail. This would cause the brake lamps not to turn on when the brakes are applied. Depending on the model, this could cause an inability to shift from park or to start using the push-button ignition. This may also cause problems with the following: anti-lock brake system (ABS), vehicle dynamics control (VDC), and/or Eyesight system. Safety Risk: If the brake lights do not work, a following driver may not to recognize that a vehicle ahead is braking, increasing the risk of crash. Corrective Actions: The company will notify owners by mail. Owners will be instructed to take their vehicle to a dealer to have the brake lamp switch replaced.	
Engine	2018606 2 Nov 2018
On certain vehicles, the engine valve springs could fracture, causing an engine failure or a stall with an inability to restart. This could increase the risk of a crash causing injury and/or damage to property. Correction: Dealers will replace the engine valve springs. Note: A driver may notice abnormal noise and/or vibration prior to an engine failure or stalling.	



Accessories

2013063 25 Feb 2013

On certain vehicles equipped with a dealer-installed accessory remote engine starter, if the fob is dropped, movement of the internal battery retaining clip may occur and cause damage to a component on the printed circuit board. Under this condition, the fob may transmit an engine start (or stop) request without the user pressing the button. If the vehicle is in range and receives the request, the engine may start and run for up to 15 minutes (or until a stop request is received). The engine may continue to start and stop until the fob battery is depleted, or until the vehicle runs out of fuel. If that occurs when the vehicle is parked in an enclosed area, such as a garage, there is a risk of carbon monoxide build-up, which could result in asphyxiation or carbon monoxide poisoning. Correction: Dealers will replace the remote engine starter fob.

Other

2013058 19 Feb 2013

Certain vehicles fail to comply with the requirements of Canada Motor Vehicle Safety Standard 205 - Glazing Materials. The "DOT" symbol, the "AS3" code mark and/or the manufacturer's number ("44") markings may have been inadvertently omitted from the rear glazing. Correction: Since this does not pose any safety risk, no corrective action is required.

Listed for the model year, not checked against your VIN. Subaru confirms which apply.

Check your VIN with Subaru Canada or call a Subaru dealer with your VIN.

www.subaru.ca/WebPage.aspx?WebSiteID=282&WebPageID=21091

United States: 2 NHTSA records for this model year, kept apart from the Canadian listing.^[3]

§3 VALUE ^[4]

This car asks \$11,690^[5], \$1,566 over the median of \$10,124^[4].



Lowest ask	\$3,495
Middle half	\$8,711 – \$12,142
Median ask	\$10,124
This car	\$11,690

Same configuration · 8 live listings · as of 28 Oct 2026

OTHER 2013 SUBARU XV CROSSTREK LISTINGS ^[5]

Edmonton, AB · 162,591 km	\$13,500
Komoka, ON · 197,920 km	\$7,995
London, ON · 219,064 km	\$3,495
Hamilton, ON · 229,000 km	\$7,895
L'Île-Perrot, QC · 156,537 km	\$9,250
L'Île-perrot, QC · 156,537 km	\$9,250

§4 EVENTS

2013	Model year 2013 ^[1] Assembly plant Japan
19 Feb 2013	Transport Canada recall 2013058 ^[2] Issued for the model year · Other
25 Feb 2013	Transport Canada recall 2013063 ^[2] Issued for the model year · Accessories



2 Nov 2018	Transport Canada recall 2018606 ^[2] Issued for the model year · Engine
1 Mar 2019	Transport Canada recall 2019104 ^[2] Issued for the model year · Brakes
15 Aug 2024	Transport Canada recall 2024546 ^[2] Issued for the model year · Label
5 Aug 2026	Listed for sale, Pointe-Claire, QC ^[5] Spinelli Toyota Pointe-Claire · asking \$11,690
25 Oct 2026	Listing last updated ^[5] asking \$11,690

§5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.

SOURCES

- | | |
|---|---|
| [1] Cardog identity register, decoded from the VIN | [4] Cardog market quote, same configuration, 8 live listings, as of 28 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year | [5] Live public dealer listings on Cardog, as of 28 Oct 2026 |
| [3] NHTSA recall records (United States), listed for the model year | |

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

