

Register entry, as of 28 October 2026

Listed for sale

Record ID 4c47ca4340c0

2004 Acura TSX

2.4 L, 4 cylinders · Sedan · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

JH4 **CL968** **2** **4** **C** **802932**

WMI 1-3

Acura · HONDA MOTOR C...

DESCRIPTOR 4-8

TSX · 2.4 L

CHECK 9

Computes

YEAR 10

2004

PLANT 11

Sayama

SERIAL 12-17

Build sequence

§1 IDENTITY [1]

Model year	2004	Engine	2.4 L, 4 cylinders
Make	Acura	Fuel	Gasoline
Model	TSX	Drive	Not in the decode
Trim	Not in the decode	Maker	HONDA MOTOR CO., LTD.
Body	Sedan	Plant	Sayama, Saitama, Japan

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/acura/tsx/2004

2 recalls listed by Transport Canada for this model year

Electrical 2013082 14 Mar 2013

On certain vehicles operated in areas where road salt and de-icing chemicals are used, if the driver enters the vehicle with a salt/snow mixture on their feet, this could melt and soak the carpet, allowing the salt-water solution to contact the base of the Engine Control Unit (ECU). As a result, the ECU could suffer corrosion damage, which may cause the engine to stall. Engine stalling would result in a loss of vehicle propulsion which, in conjunction with traffic and road conditions, and the driver's reactions, could increase the risk of a crash causing property damage and/or personal injury. Correction: Dealers will install a waterproof cover over the ECU. A damaged ECU will be replaced.

Lights and instruments 2004324 9 Sep 2004

On certain vehicles, the wiring harness located in the trunk hinge area is not adequately protected and, over time, could be damaged when the trunk is opened and closed. A damaged harness can cause a blown fuse or an open circuit; either results in a loss of licence plate light, back up light and/or tail light function. All affected lights are on the trunk lid. The portion of the light assembly on the rear quarter panel, which includes a tail light, a brake light and a turn signal, are not affected. Correction: Dealers will inspect the rear wire harness. If any damage is found, the harness will be replaced. If no damage is found, the dealer will install corrugated plastic tubing over the harness to prevent damage.

Listed for the model year, not checked against your VIN. Acura confirms which apply.

Check your VIN with Acura Canada or call a Acura dealer with your VIN.

www.acura.ca/en/recalls

United States: 4 NHTSA records for this model year, kept apart from the Canadian listing.^[3]



§3 VALUE [4]

This car asks \$9,900^[5], the median^[4].



Lowest ask	\$9,900
Middle half	\$9,900 – \$9,900
Median ask	\$9,900
This car	\$9,900

Same model year · 1 live listings · as of 28 Oct 2026

§4 EVENTS

2004	Model year 2004 ^[1] Assembly plant Sayama, Saitama, Japan
9 Sep 2004	Transport Canada recall 2004324 ^[2] Issued for the model year · Lights and instruments
14 Mar 2013	Transport Canada recall 2013082 ^[2] Issued for the model year · Electrical
2 May 2026	Listed for sale, Richmond, BC ^[5] JC Motors · asking \$9,900
28 Oct 2026	Listing last updated ^[5] asking \$9,900

§5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN	[4] Cardog market quote, same model year, 1 live listings, as of 28 Oct 2026
[2] Transport Canada recall database, listed for the model year	[5] Live public dealer listings on Cardog, as of 28 Oct 2026
[3] NHTSA recall records (United States), listed for the model year	

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

