

2013 Suzuki SX4 Crossover (US)/Crossover Premium (US)/JX (Canada)/[JA/JX] (Canada)Sedan LE (US)/Sedan LE Pop Pkg. (US)/JA (Canada)

2.0 L, 4 cylinders · AWD · Hatchback · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

JS2	YB5A3	9	D	6	101887
WMI 1-3 Suzuki Motor Of America, Inc	DESCRIPTOR 4-8 SX4 · 2.0 L	CHECK 9 Computes	YEAR 10 2013	PLANT 11 Sagara	SERIAL 12-17 Build sequence

§1 IDENTITY [1]

Model year	2013	Engine	2.0 L, 4 cylinders
Make	Suzuki	Fuel	Gasoline
Model	SX4	Drive	AWD
Trim	Crossover (US)/Crossover Premium (US)/JX (Canada)/[JA/JX] (Canada)Sedan LE (US)/Sedan LE Pop Pkg. (US)/JA (Canada)	Maker	SUZUKI MOTOR OF AMERICA, INC
Body	Hatchback	Plant	Sagara, Kumamoto Prefecture, Japan

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/suzuki/sx4/2013

5 recalls listed by Transport Canada for this model year

Steering 2018643 21 Nov 2018

On certain vehicles, a defect in the power steering pump could cause it to seize after a long period of vehicle non-operation (such as overnight parking) during cold ambient temperatures. This would unexpectedly increase the steering effort force necessary to steer the vehicle at lower vehicle speeds, which could increase the risk of a crash causing injury and/or damage to property. Correction: Dealers will replace the power steering pump.

Powertrain 2018276 24 May 2018

On certain vehicles, a circuit board inside the Transmission Control Module (TCM) may develop a crack, preventing it from controlling the transmission properly. This could result in reduced vehicle speed and poor acceleration, which could increase the risk of a crash causing injury and/or property damage. Correction: Dealers will replace the TCM with a reprogrammed unit.



Steering

2015415 21 Sep 2015

On certain vehicles, a defect in the power steering pump could cause it to seize after a long period of vehicle non-operation (such as overnight parking) during cold ambient temperatures. This would unexpectedly increase the steering effort force necessary to steer the vehicle at lower vehicle speeds, which could increase the risk of a crash causing injury and/or damage to property. Correction: Dealers will replace the power steering pump with an improved part.

Powertrain

2014578 18 Dec 2014

On certain vehicles, the detent pin within the shift lock structure may have been incorrectly positioned. An incorrectly positioned detent pin in combination with high temperature conditions could allow the transmission shift selector to be moved out of the PARK position without depressing the brake pedal. Depending which gear the driver selects, the vehicle could begin to move forward or backward immediately. This movement could result in property damage, or cause the vehicle to strike a bystander, potentially resulting in injury. Correction: Dealers will replace the shift selector assembly with an improved part which incorporates an extended detent pin.

Powertrain

2013407 18 Nov 2013

On certain vehicles, the bolts that fasten the drive plate to the torque converter may not have been sufficiently tightened during vehicle assembly. Should these bolts loosen, they could become caught between the drive plate and the cylinder block, which may cause the engine to stall, resulting in a loss of motive power. This could increase the risk of a crash causing injury and/or property damage. Correction: Dealers will affect repairs.

Listed for the model year, not checked against your VIN. Suzuki confirms which apply.

Check your VIN with Suzuki Canada or call a Suzuki dealer with your VIN.

www.suzuki.ca/recalls/

United States: 5 NHTSA records for this model year, kept apart from the Canadian listing.^[3]

§3 VALUE [4]

This car asks \$4,995^[5], \$2,002 under the median of \$6,997^[4].



Lowest ask	\$4,995
Middle half	\$5,996 – \$7,998
Median ask	\$6,997
This car	\$4,995

Same model year · 2 live listings · as of 29 Oct 2026

OTHER 2013 SUZUKI SX4 LISTINGS [5]

Edmonton, AB · 157,571 km \$8,999

§4 EVENTS

2013	Model year 2013 ^[1] Assembly plant Sagara, Kumamoto Prefecture, Japan
18 Nov 2013	Transport Canada recall 2013407 ^[2] Issued for the model year · Powertrain
18 Dec 2014	Transport Canada recall 2014578 ^[2] Issued for the model year · Powertrain



21 Sep 2015	Transport Canada recall 2015415 ^[2] Issued for the model year · Steering
24 May 2018	Transport Canada recall 2018276 ^[2] Issued for the model year · Powertrain
21 Nov 2018	Transport Canada recall 2018643 ^[2] Issued for the model year · Steering
28 Oct 2026	Listed for sale, Montréal, QC ^[5] Toyota Gabriel Centre-Ville · asking \$4,995
29 Oct 2026	Listing last updated ^[5] asking \$4,995

§5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.

SOURCES

- | | |
|---|--|
| [1] Cardog identity register, decoded from the VIN | [4] Cardog market quote, same model year, 2 live listings, as of 29 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year | [5] Live public dealer listings on Cardog, as of 29 Oct 2026 |
| [3] NHTSA recall records (United States), listed for the model year | |

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

