

Register entry, as of 27 October 2026

Listed for sale

Record ID b555bb24d10d

2009 Suzuki Grand Vitara L4 Luxury (2.4L JLX-Leather)

2.4 L, 4 cylinders · 4WD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

JS3 **TD047** **4** **9** **4** **100232**

WMI 1-3

Suzuki Motor Of America, Inc

DESCRIPTOR 4-8

Grand Vitara · 2.4 L

CHECK 9

Computes

YEAR 10

2009

PLANT 11

Iwata

SERIAL 12-17

Build sequence

§1 IDENTITY [1]

Model year	2009	Engine	2.4 L, 4 cylinders
Make	Suzuki	Fuel	Gasoline
Model	Grand Vitara	Drive	4WD
Trim	L4 Luxury (2.4L JLX-Leather)	Maker	SUZUKI MOTOR OF AMERICA, INC
Body	Sport Utility Vehicle	Plant	Iwata, Shizuoka, Japan

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/suzuki/grand-vitara/2009

4 recalls listed by Transport Canada for this model year

Airbag

2019129 11 Mar 2019

Issue: On certain vehicles, the occupant classification system (OCS) may not work properly. This could cause the airbag system not to turn off the airbag when an infant or child is seated in the front passenger seat. This could also cause the passenger seat belt reminder to activate when the seat is empty. Note: This problem only affects vehicles with leather seats. Safety Risk: In a crash, an airbag that deploys in front of an infant or child increases the risk of injury. Corrective Actions: The company will notify owners by mail. Owners will be instructed to take their vehicle to a Suzuki service provider to have the front passenger seat cushion replaced.

Powertrain

2017066 9 Feb 2017

On certain vehicles, the gear shift rear shaft could break due to repeated right to left and left to right movement of the shifter lever. If this occurs, the driver would not be able to switch gear which could increase the risk of a crash causing injury and/or damage to property. Correction: Dealers will replace the gear shift rear shaft with an improved part.

Airbag

2013305 17 Sep 2013

On certain vehicles, the Occupant Classification System may malfunction, causing the airbag warning lamp to illuminate, and could fail to disable the passenger airbag if a child were seated in the front passenger seating position. This could result in an unwarranted airbag deployment in a crash, increasing the risk of injury to a child seated in the front passenger seat. Note: In this situation, the "PASS AIR BAG OFF" light would fail to illuminate, regardless of if a child or adult is seated in the front passenger seat. Correction: Vehicles will receive special extended warranty coverage of 10 years or 200,000 kilometers (whichever comes first) from the date the vehicle was originally placed into service. Under this special coverage program, vehicles which experience this condition will have the occupant detection mat replaced.



Engine

2011041 27 Jan 2011

On certain vehicles, the tension adjuster pulley for the drive belt, which operates the alternator, water pump, air conditioner compressor and power steering pump, may contain an improperly manufactured internal spring that can break due to repeated stress. Should the spring break, this would cause the drive belt tension to be maladjusted, allowing the belt to slip. If the belt comes off, the loss of steering power assist would require the driver to exert increased effort to steer the vehicle. This could result in a crash causing property damage and/or personal injury. Additionally, the loss of water pump function would cause the coolant temperature to rise, which can lead to engine overheating, while the loss of alternator charging ability would lead to battery discharge and eventual engine stall. Correction: Dealers will replace the drive belt tension adjuster pulley.


Listed for the model year, not checked against your VIN. Suzuki confirms which apply.
Check your VIN with Suzuki Canada or call a Suzuki dealer with your VIN.

www.suzuki.ca/recalls/

United States: 4 NHTSA records for this model year, kept apart from the Canadian listing.^[3]

§3 VALUE [4]

This car asks \$8,999^[5], the median^[4].



Lowest ask	\$8,999
Middle half	\$8,999 – \$8,999
Median ask	\$8,999
This car	\$8,999

Same model year · 1 live listings · as of 27 Oct 2026

§4 EVENTS

2009	Model year 2009 ^[1] Assembly plant Iwata, Shizuoka, Japan
27 Jan 2011	Transport Canada recall 2011041 ^[2] Issued for the model year · Engine
17 Sep 2013	Transport Canada recall 2013305 ^[2] Issued for the model year · Airbag
9 Feb 2017	Transport Canada recall 2017066 ^[2] Issued for the model year · Powertrain
11 Mar 2019	Transport Canada recall 2019129 ^[2] Issued for the model year · Airbag
26 Oct 2026	Listed for sale, Cowichan Valley, BC ^[5] Pride Motorsports Inc · asking \$8,999
27 Oct 2026	Listing last updated ^[5] asking \$8,999



§5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.

SOURCES

- | | |
|---|--|
| [1] Cardog identity register, decoded from the VIN | [4] Cardog market quote, same model year, 1 live listings, as of 27 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year | |
| [3] NHTSA recall records (United States), listed for the model year | [5] Live public dealer listings on Cardog, as of 27 Oct 2026 |

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

