

Register entry, as of 27 October 2026

Listed for sale

Record ID 09639332da48

2006 Lexus GS

4.3 L, 6 cylinders · 4x2 · Sedan · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

JTH **BN96S** **4** **6** **5** **006322**

WMI 1-3

Lexus · TOYOTA MOTOR C...

DESCRIPTOR 4-8

GS · 4.3 L

CHECK 9

Computes

YEAR 10

2006

PLANT 11

Tahara

SERIAL 12-17

Build sequence

§1 IDENTITY [1]

Model year	2006	Engine	4.3 L, 6 cylinders
Make	Lexus	Fuel	Gasoline
Model	GS	Drive	4x2
Trim	Not in the decode	Maker	TOYOTA MOTOR CORPORATION
Body	Sedan	Plant	Tahara, Aichi, Japan

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/lexus/gs/2006

4 recalls listed by Transport Canada for this model year

Fuel system 2014458 16 Oct 2014

On certain vehicles, the fuel delivery pipes in the engine compartment may have been produced with particles from the anti-corrosion plating on the gasket seating surface where the fuel pressure sensor is installed. This could affect the sealing properties of the gasket seated between the pressure sensor and the pipe, potentially resulting in a fuel leak. A fuel leak in the presence of an ignition source could result in a fire causing injury and/or property damage. Correction: Dealers will replace the gasket and repair the gasket seating surface.

Other 2011080 24 Feb 2011

On certain AWD vehicles, if the floor carpet near the accelerator pedal is not reinstalled correctly following a service repair, the plastic pad embedded into the floor carpet could interfere with the operation of the accelerator pedal. If this occurs, the accelerator pedal could temporarily become stuck in a partially depressed position, rather than return to the idle position. This could result in a loss of throttle control and a crash causing property damage and/or personal injury. Correction: Dealers will modify the plastic pad.

Fuel system 2011037 26 Jan 2011

On certain GS 300, GS 300 AWD, GS 350, IS 250, IS 250 AWD and IS 350 vehicles, the fuel pressure sensor connected to the engine fuel delivery pipe may not have been sufficiently tightened during vehicle assembly. Should the pressure sensor loosen, fuel could leak past a gasket used in the connection between the sensor and pipe, and through the threaded portion of the sensor. Fuel leakage, in the presence of an ignition source, could result in a fire causing property damage and/or personal injury. Correction: Dealers will inspect for fuel leakage from the threaded portion of the fuel pressure sensor. If there are no signs of a fuel leak, the fuel pressure sensor will be tightened to specifications. If a fuel leak is confirmed, the gasket between the sensor and the fuel delivery pipe will be replaced, and the sensor will be tightened.



Fuel system

2009015 19 Jan 2009

On certain vehicles, the use of selected ethanol fuels may cause the aluminium fuel rails to corrode. This could result in plugged fuel injector(s), causing a rough engine idle and/or the illumination of the engine warning lamp. Corrosion may also cause a pinhole to develop on the fuel rail, which could result in fuel leakage. Fuel leakage, in the presence of an ignition source, could result in a vehicle fire. Correction: Dealers will replace the fuel rails.

Listed for the model year, not checked against your VIN. Lexus confirms which apply.

Check your VIN with Lexus Canada or call a Lexus dealer with your VIN.

www.lexus.ca/en/maintain-your-lexus/campaigns/

United States: 8 NHTSA records for this model year, kept apart from the Canadian listing.^[3]

§3 VALUE ^[4]

This car asks \$5,999^[5], the median^[4].



Lowest ask	\$5,999
Middle half	\$5,999 – \$5,999
Median ask	\$5,999
This car	\$5,999

Same model year · 1 live listings · as of 27 Oct 2026

§4 EVENTS

2006	Model year 2006 ^[1] Assembly plant Tahara, Aichi, Japan
19 Jan 2009	Transport Canada recall 2009015 ^[2] Issued for the model year · Fuel system
26 Jan 2011	Transport Canada recall 2011037 ^[2] Issued for the model year · Fuel system
24 Feb 2011	Transport Canada recall 2011080 ^[2] Issued for the model year · Other
16 Oct 2014	Transport Canada recall 2014458 ^[2] Issued for the model year · Fuel system
2 Sep 2026	Listed for sale, Markham, ON ^[5] Markham Honda · asking \$5,999
27 Oct 2026	Listing last updated ^[5] asking \$5,999



§5 DOCUMENTS

Window sticker We have not collected this label yet.

SOURCES

- | | |
|---|--|
| [1] Cardog identity register, decoded from the VIN | [4] Cardog market quote, same model year, 1 live listings, as of 27 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year | |
| [3] NHTSA recall records (United States), listed for the model year | [5] Live public dealer listings on Cardog, as of 27 Oct 2026 |

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

