

Register entry, as of 27 October 2026

Listed for sale

Record ID 4c088d81ac8a

2008 Lexus IS 250 AWD

2.5 L, 6 cylinders · AWD · Sedan · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

JTH **CK262** **2** **8** **2** **026951**

WMI 1-3

Lexus · TOYOTA MOTOR C...

DESCRIPTOR 4-8

IS · 2.5 L

CHECK 9

Computes

YEAR 10

2008

PLANT 11

Japan

SERIAL 12-17

Build sequence

§1 IDENTITY [1]

Model year	2008	Engine	2.5 L, 6 cylinders
Make	Lexus	Fuel	Gasoline
Model	IS	Drive	AWD
Trim	250 AWD	Maker	TOYOTA MOTOR CORPORATION
Body	Sedan	Plant	Japan

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/lexus/is/2008

10 recalls listed by Transport Canada for this model year

Electrical

2021723 24 Nov 2021

Issue: This recall is for certain block heater kits installed on certain vehicles or sold as accessories at Toyota or Lexus dealerships. On certain vehicles, the engine block heater cable may not have enough heat protection and could be damaged by high temperatures. If this happens, the cable could short circuit while plugged in, and cause the wiring to overheat or melt. Note: This recall only affects the following block heater/cord part numbers: C014003034 PK5A408J09 PU14000904 C014003151 PK5A408J13 PU14000905 C014000885 PK5A489J11 PU14000907 C014000888 PK5A489J22 PU14000909 C014000907 PK5A410H00 PU14000911 C014100904 PU14000900 PU14000913 C014100907 PU14000901 PU14003571 C014100911 PU14000902 PK5A489J14 PK5A408J05 PU14000903 Safety Risk: Engine block heater wiring that overheats or melts could create the risk of a fire. Corrective Actions: Toyota recommends that you should stop using the engine block heater immediately. Toyota will notify owners by mail and instruct you to take your vehicle to a dealer to disable the engine block heater. For some vehicles, the corrective actions for this recall are under development. For others, a new engine block heater cannot be installed, and the owner will receive a refund of the purchase price of the engine block heater.

Fuel system

2018346 26 Jun 2018

On certain vehicles equipped with a 3.5L V6 engine, the fuel pulsation dampers located in the fuel delivery pipe could develop a leak over time. A fuel leak in the presence of an ignition source could increase the risk of fire causing injury and/or damage to property. Correction: Dealers will replace the fuel delivery pipe with an updated part.



Airbag

2017007 9 Jan 2017

On certain vehicles, long-term exposure to high absolute humidity and temperature, combined with high temperature cycling, could eventually degrade the propellant contained in the passenger frontal airbag. This could cause the airbag to deploy with more force than normal. As a result, if the vehicle were involved in a collision that warrants airbag deployment, fragments could be propelled toward vehicle occupants, and the airbag assembly could be damaged, preventing proper function. These issues could increase the risk of injury. Correction: Depending on the model, dealers will either replace the passenger frontal airbag inflator or airbag assembly. Note: Canadian climate results in the propellant degrading slowly. The recall is being conducted as a precaution to address future risk, and is expected to replace airbag inflators before their function would be affected.

Fuel system

2014458 16 Oct 2014

On certain vehicles, the fuel delivery pipes in the engine compartment may have been produced with particles from the anti-corrosion plating on the gasket seating surface where the fuel pressure sensor is installed. This could affect the sealing properties of the gasket seated between the pressure sensor and the pipe, potentially resulting in a fuel leak. A fuel leak in the presence of an ignition source could result in a fire causing injury and/or property damage. Correction: Dealers will replace the gasket and repair the gasket seating surface.

Engine

2013297 4 Sep 2013

On certain vehicles, the bolts used to secure the housing and sprocket of the intake-side Variable-Valve Timing (VVT) gear assembly could loosen. If this occurs, the VVT gear will not control the intake valves correctly. In some instances, the VVT gear housing and sprocket could separate, causing the engine to stall. Engine stalling would result in a loss of vehicle propulsion which, in conjunction with traffic and road conditions, and the driver's reactions, could increase the risk of a crash causing property damage and/or personal injury. Correction: Dealers will replace the VVT unit with an improved version.

Visual system

2013031 30 Jan 2013

On certain vehicles, the wiper arm securing nuts could have been insufficiently tightened during assembly. If the movement of the wipers is restricted by an external load, such as heavy snow on the windshield, the wiper arms could slip and one or both wipers could become inoperative. If this occurs, driver visibility could be reduced, which could increase the risk of a crash causing injury and/or property damage. Correction: Dealers will clean the mating surface of the wiper arm and motor shaft and install improved wiper arm nuts.

4 more on the model-year record, cardog.app/tools/recalls/lexus/is/2008

Listed for the model year, not checked against your VIN. Lexus confirms which apply.

Check your VIN with Lexus Canada or call a Lexus dealer with your VIN.

www.lexus.ca/en/maintain-your-lexus/campaigns/

United States: 11 NHTSA records for this model year, kept apart from the Canadian listing.^[3]

§3 VALUE ^[4]

This car asks \$9,995^[5], the median^[4].



Lowest ask	\$9,800
Middle half	\$9,995 – \$11,888
Median ask	\$9,995
This car	\$9,995

Same model year · 5 live listings · as of 27 Oct 2026

OTHER 2008 LEXUS IS LISTINGS ^[5]

Burnaby, BC · 1 km	\$9,800
Richmond, BC · 134,464 km	\$9,995
Richmond, BC · 103,994 km	\$14,995
Oakville, ON · 76,131 km	\$11,888



§4 EVENTS

2008	Model year 2008 ^[1] Assembly plant Japan
19 Jan 2009	Transport Canada recall 2009015 ^[2] Issued for the model year · Fuel system
7 Oct 2009	Transport Canada recall 2009290 ^[2] Issued for the model year · Other
5 Jul 2010	Transport Canada recall 2010221 ^[2] Issued for the model year · Engine
26 Jan 2011	Transport Canada recall 2011037 ^[2] Issued for the model year · Fuel system
30 Jan 2013	Transport Canada recall 2013031 ^[2] Issued for the model year · Visual system
4 Sep 2013	Transport Canada recall 2013297 ^[2] Issued for the model year · Engine
16 Oct 2014	Transport Canada recall 2014458 ^[2] Issued for the model year · Fuel system
9 Jan 2017	Transport Canada recall 2017007 ^[2] Issued for the model year · Airbag
26 Jun 2018	Transport Canada recall 2018346 ^[2] Issued for the model year · Fuel system
24 Nov 2021	Transport Canada recall 2021723 ^[2] Issued for the model year · Electrical
27 Dec 2025	Listed for sale, London, ON ^[5] Samoza Autos · asking \$9,995
27 Oct 2026	Listing last updated ^[5] asking \$9,995

§5 DOCUMENTS

Window sticker We have not collected this label yet.

SOURCES

- | | |
|---|--|
| [1] Cardog identity register, decoded from the VIN | [4] Cardog market quote, same model year, 5 live listings, as of 27 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year | [5] Live public dealer listings on Cardog, as of 27 Oct 2026 |
| [3] NHTSA recall records (United States), listed for the model year | |



STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

