

Register entry, as of 27 October 2026

Listed for sale

Record ID c4eb76b5e236

2015 Lexus RC 350

3.5 L, 6 cylinders · 4WD · Coupe · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

JTH SE5BC 2 F 5 002356

WMI 1-3

Lexus · TOYOTA MOTOR C...

DESCRIPTOR 4-8

RC · 3.5 L

CHECK 9

Computes

YEAR 10

2015

PLANT 11

Tahara

SERIAL 12-17

Build sequence

§1 IDENTITY [1]

Model year	2015	Engine	3.5 L, 6 cylinders
Make	Lexus	Fuel	Gasoline
Model	RC	Drive	4WD
Trim	350	Maker	TOYOTA MOTOR CORPORATION
Body	Coupe	Plant	Tahara, Aichi, Japan

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/lexus/rc/2015

4 recalls listed by Transport Canada for this model year

Fuel system

2026175 8 Apr 2026

Issue: On certain vehicles, the low-pressure fuel pump could fail. If this happens, the engine may run rough or may not start and the check engine light may turn on. This could also result in a sudden loss of engine power while driving. Safety Risk: A sudden loss of engine power could increase the risk of a crash. Corrective Actions: Lexus will notify owners by mail and advise you to take your vehicle to a dealer to replace the fuel pump.

Electrical

2021723 24 Nov 2021

Issue: This recall is for certain block heater kits installed on certain vehicles or sold as accessories at Toyota or Lexus dealerships. On certain vehicles, the engine block heater cable may not have enough heat protection and could be damaged by high temperatures. If this happens, the cable could short circuit while plugged in, and cause the wiring to overheat or melt. Note: This recall only affects the following block heater/cord part numbers: C014003034 PK5A408J09 PU14000904 C014003151 PK5A408J13 PU14000905 C014000885 PK5A489J11 PU14000907 C014000888 PK5A489J22 PU14000909 C014000907 PK5A410H00 PU14000911 C014100904 PU14000900 PU14000913 C014100907 PU14000901 PU14003571 C014100911 PU14000902 PK5A489J14 PK5A408J05 PU14000903 Safety Risk: Engine block heater wiring that overheats or melts could create the risk of a fire. Corrective Actions: Toyota recommends that you should stop using the engine block heater immediately. Toyota will notify owners by mail and instruct you to take your vehicle to a dealer to disable the engine block heater. For some vehicles, the corrective actions for this recall are under development. For others, a new engine block heater cannot be installed, and the owner will receive a refund of the purchase price of the engine block heater.



Fuel system

2020514 28 Oct 2020

Issue: On certain vehicles, the low-pressure fuel pump could fail. If this happens, then engine may run rough or may not start and the check engine light may turn on. This could also result in a sudden loss of engine power while driving. Note: This recall is an expansion of recalls SRC R95/SRC R96 and SRC RA2/SRC RA3 (Transport Canada Recall Numbers 2020-005 and 2020-088). Safety Risk: A sudden loss of engine power could increase the risk of a crash. Corrective Actions: The company will notify owners by mail and instruct you to take your vehicle to a dealer to replace the fuel pump.

Fuel system

2020088 4 Mar 2020

Issue: On certain vehicles, the low-pressure fuel pump could fail. If this happens, then engine may run rough or may not start and the check engine light may turn on. This could also result in a sudden loss of engine power while driving. Note: This recall is an expansion of recall SRC R95/SRC R96 (Transport Canada Recall No. 2020-005) Safety Risk: A sudden loss of engine power could increase the risk of a crash. Corrective Actions: The company will notify owners by mail and instruct you to take your vehicle to a dealer to replace the fuel pump.

Listed for the model year, not checked against your VIN. Lexus confirms which apply.
Check your VIN with Lexus Canada or call a Lexus dealer with your VIN.

www.lexus.ca/en/maintain-your-lexus/campaigns/

United States: 3 NHTSA records for this model year, kept apart from the Canadian listing.^[3]

§3 VALUE [4]

This car asks \$23,200^[5], \$4,196 under the median of \$27,396^[4].



Lowest ask	\$23,200
Middle half	\$24,999 – \$29,388
Median ask	\$27,396
This car	\$23,200

Same model year · 5 live listings · as of 27 Oct 2026

§4 EVENTS

2015	Model year 2015 ^[1] Assembly plant Tahara, Aichi, Japan
4 Mar 2020	Transport Canada recall 2020088 ^[2] Issued for the model year · Fuel system
28 Oct 2020	Transport Canada recall 2020514 ^[2] Issued for the model year · Fuel system
24 Nov 2021	Transport Canada recall 2021723 ^[2] Issued for the model year · Electrical
8 Apr 2026	Transport Canada recall 2026175 ^[2] Issued for the model year · Fuel system
7 May 2026	Listed for sale, Pointe-Claire, QC ^[5] Spinelli Toyota Pointe-Claire · asking \$23,200



24 Oct 2026 Listing last updated^[5]
asking \$23,200

§5 DOCUMENTS

Window sticker We have not collected this label yet.

SOURCES

- | | |
|---|--|
| [1] Cardog identity register, decoded from the VIN | [4] Cardog market quote, same model year, 5 live listings, as of 27 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year | |
| [3] NHTSA recall records (United States), listed for the model year | [5] Live public dealer listings on Cardog, as of 27 Oct 2026 |

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

