

Register entry, as of 29 October 2026

Listed for sale

Record ID f397c76ad561

2016 Lexus GX 460

4.6 L, 8 cylinders · 4WD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

JTJ **JM7FX** **9** **G** **5** **120699**

WMI 1-3

Lexus · TOYOTA MOTOR C...

DESCRIPTOR 4-8

GX · 4.6 L

CHECK 9

Computes

YEAR 10

2016

PLANT 11

Tahara

SERIAL 12-17

Build sequence

§1 IDENTITY [1]

Model year	2016	Engine	4.6 L, 8 cylinders
Make	Lexus	Fuel	Gasoline
Model	GX	Drive	4WD
Trim	460	Maker	TOYOTA MOTOR CORPORATION
Body	Sport Utility Vehicle	Plant	Tahara, Aichi, Japan

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/lexus/gx/2016

3 recalls listed by Transport Canada for this model year

Electrical

2021723 24 Nov 2021

Issue: This recall is for certain block heater kits installed on certain vehicles or sold as accessories at Toyota or Lexus dealerships. On certain vehicles, the engine block heater cable may not have enough heat protection and could be damaged by high temperatures. If this happens, the cable could short circuit while plugged in, and cause the wiring to overheat or melt. Note: This recall only affects the following block heater/cord part numbers: C014003034 PK5A408J09 PU14000904 C014003151 PK5A408J13 PU14000905 C014000885 PK5A489J11 PU14000907 C014000888 PK5A489J22 PU14000909 C014000907 PK5A410H00 PU14000911 C014100904 PU14000900 PU14000913 C014100907 PU14000901 PU14003571 C014100911 PU14000902 PK5A489J14 PK5A408J05 PU14000903 Safety Risk: Engine block heater wiring that overheats or melts could create the risk of a fire. Corrective Actions: Toyota recommends that you should stop using the engine block heater immediately. Toyota will notify owners by mail and instruct you to take your vehicle to a dealer to disable the engine block heater. For some vehicles, the corrective actions for this recall are under development. For others, a new engine block heater cannot be installed, and the owner will receive a refund of the purchase price of the engine block heater.

Airbag

2019008 9 Jan 2019

Issue: On certain vehicles, long-term exposure to high absolute humidity and temperature, combined with high temperature cycling, may eventually degrade the propellant contained in the passenger-front airbag. This could cause the airbag to deploy with more force than normal. If the airbag inflator ruptures, fragments could be propelled toward vehicle occupants or cause damage to the airbag assembly, preventing its proper function. Safety Risk: If the vehicle is involved in a crash requiring an airbag deployment, the airbag inflator could rupture and create a risk of injury. Corrective Action: Owners will be notified by mail and instructed to take their vehicle to a dealer to have the passenger-front airbag inflator or airbag module replaced. Note: The Canadian climate results in the propellant degrading slowly. This recall is being conducted as a precaution to address future risk. It is expected that all airbag inflators will be replaced before their function would be affected.



Electrical

2017363 20 Jul 2017

On certain vehicles, the electrical power cords of some dealer installed block heaters may have been improperly manufactured, causing the wires to contact each other, resulting in a short circuit. A short circuit could lead to a fire which would increase the risk of injury and/or damage to property. Correction: For vehicles where the subject block heater was approved for installation, the dealer will replace the block heater assembly with a new one of an improved design. For vehicles where the subject block heater was not approved for installation, dealers will remove the block heater assembly. In the interim, until the remedy can be performed, dealers will cut the plug end from the block heater cord to disable the block heater's operation.


Listed for the model year, not checked against your VIN. Lexus confirms which apply.
Check your VIN with Lexus Canada or call a Lexus dealer with your VIN.

www.lexus.ca/en/maintain-your-lexus/campaigns/

United States: 2 NHTSA records for this model year, kept apart from the Canadian listing.^[3]

§3 VALUE ^[4]

This car asks \$43,999^[5], \$7,002 over the median of \$36,997^[4].



Lowest ask	\$30,888
Middle half	\$32,490 – \$38,595
Median ask	\$36,997
This car	\$43,999

Same model year · 5 live listings · as of 29 Oct 2026

OTHER 2016 LEXUS GX LISTINGS ^[5]

Woodbridge, ON · 200,000 km	\$30,888
Toronto, ON · 141,011 km	\$38,595
Fergus, ON · 141,011 km	\$38,595
Edmonton, AB · 112,295 km	\$36,997

§4 EVENTS

2016	Model year 2016 ^[1] Assembly plant Tahara, Aichi, Japan
20 Jul 2017	Transport Canada recall 2017363 ^[2] Issued for the model year · Electrical
9 Jan 2019	Transport Canada recall 2019008 ^[2] Issued for the model year · Airbag
24 Nov 2021	Transport Canada recall 2021723 ^[2] Issued for the model year · Electrical
28 Oct 2026	Listed for sale, Grande Prairie, AB ^[5] Bannister GP Honda · asking \$43,999



§5 DOCUMENTS

Window sticker We have not collected this label yet.

SOURCES

- | | |
|---|--|
| [1] Cardog identity register, decoded from the VIN | [4] Cardog market quote, same model year, 5 live listings, as of 29 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year | |
| [3] NHTSA recall records (United States), listed for the model year | [5] Live public dealer listings on Cardog, as of 29 Oct 2026 |

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

